

SERVICE ESTIMATE

94189 - C00001
Mr Tan Hak Khoo
36 JALAN SEMERBAK

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 20/04/2018

WIP No. : 56781

Veh.In/Out:

*Tel.No. : Mobile: 97866623

Reg.No. : SLU201J

Reg.date : 24/10/2017

Mileage : 0

Chassis No: JN1BCAV37Z0530083

Singapore 329060

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Tan Hak Khoo

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, ETC	0	1800.00	0		1,800.00	S 900
800	TO PUTTY SPRAYPAINT ON REAR BUMPER, ETC	0	1600.00	0		1,600.00	S 800
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S 390 ✓
	FACE-RR BUMPER	1.0 EA	800.10			800.10	S de ✓
	BRACKET-BUMPER	1.0 EA	30.80			30.80	S ?
	BRACKET-BUMPER	1.0 EA	30.80			30.80	S ?
	FINISHER RR BUMPER C	1.0 EA	19.90			19.90	S de ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Labour	Total	3,886.00
Parts	Total	881.60
Package	Total	0.00

Gross Total. 4,767.60

Net..... 4,767.60

GST @ 7.0% 333.73

Total..... 5,101.35

Paid..... 0.00

Please Pay.. 5,101.35

Tan Hak Khoo 97495749
WP
7/5/18 @ 1350
3 days
Resurvey by fee paid.
sure/like auto..

GST: S=StdRated; O=OutOfScope; Z=ZeroRated