Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18007435/GPA3Q2

Date: 02/06/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: P1680520

Claimant Vehicle No: SDF2286A Insured Vehicle No: SHB9697A

Date of Loss: 21/03/2018 Nature of Claim: TP Claim No: C0473213

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDF2286A

 Make & Model:
 TOYOTA COROLLA, 1.5 AXIO (A)
 Engine No:
 1NZC739669

 Reg. Date:
 17/01/2008 (Man. Year: 2007)
 Chassis No:
 NZE1416050553

 Colour:
 Silver
 Odometer:
 212848 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,484.60	418.35	1,066.25	71.82
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,280.00	600.00	680.00	53.13
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	2,764.60	1,018.35	1,746.25	63.16
	Approved Total (Overridden) (S\$)		800.00		
	(S\$)	2,764.60	800.00	1,746.25 1,746.25 1,964.60 1,964.60 1,37.52	71.06
	+ GST 7.00/7.00% (S\$)	193.52	800.00 1,964.60 56.00 137.52	71.06	
	Nett Amount (S\$)	2,958.12	856.00	2,102.12	71.06
	+ Car Rental (3.0 x S\$100.00/day + 7.	.00% GST) (S\$)	321.00		
	Ne	tt Liability (S\$)	1,177.00		
	Global Sum S	Settlement (S\$)	1,170.00		

INSPECTION

Date of Assignment: 20/04/2018

Date Inspected: 03/05/2018 Inspected At: Ricardo Auto Centre Pte Ltd (HQ)

160 Sin Ming Drive, #02-02, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: XING GUO QIANG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source: MRM-SG		Version: 1.0 (Last Synchronised: 23 Apr 2020)		
Parts:	143	TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	e: (Unsubmitted, no print-code for SDF2286A)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	. Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (CONSISTENT)	Repair	499.50 F	*- FL
2	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT)	Serviceable	363.40 F	*-FL
3	1		*FRONT BUMPER SPONGE (CONSISTENT)	Serviceable	78.90 F	*-FL
4	1		*FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	Necessary	53.50 F	*53.50 FL
5	1		*FRONT GRILLE WITH EMBLEM (CONSISTENT)	Cracked	409.30 F	*409.30 FL
6	10		*FRONT BUMPER CLIPS (CONSISTENT)	Necessary	35.00 F	*35.00 FL
7	1		*FRONT NUMBER PLATE WITH HOLDER (CONSISTENT)	Scratched	45.00 FS	*45.00 FS
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.					
Sub Total (S\$)			1,484.60	542.80		
- List Item Discount on L Items 0.00/25.00% (S\$) _ Total Parts (S\$)			0.00	124.45		
			1,484.60	418.35		
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CUT ,WELD & STRAIGHTEN FRONT PORTIO OF CAR CAUSED BY ACCIDENT ,ADJUST & REPLACE DAMAGE PARTS	New	500.00	200.00
2	TO SPRAY PAINT ON REPAIRED AREA	New	750.00	400.00
3	TO FOCUS HEADLAMP	New	30.00	0.00
	Gross Labour Cost (S\$)		1,280.00	600.00
	Report was unsubmitted durir	ng this print-out.		

< END OF ESTIMATES >