

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18007537/KHA3Q2

Date: 08/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SKL2210D **Insured Vehicle No :** SKD5635J

Date of Loss: 17/04/2018 **Nature of Claim:** TP **Claim No:** 5006186366SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL2210D	Engine No:	R18A13890563
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	JHMRN6880DC200563
Reg. Date:	14/10/2013 (Man. Year: 2013)	Odometer:	50637 km
Colour:	Metallic Pearl White		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,621.36	2,116.32	505.04	19.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	1,050.00	400.00	27.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,071.36	3,166.32	905.04	22.23
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	4,071.36	2,550.00	1,521.36	37.37
+ GST 7.00/7.00% (S\$)	285.00	178.50	106.50	37.37
Nett Amount (S\$)	4,356.36	2,728.50	1,627.86	37.37
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,230.50		
Global Sum Settlement (S\$)		3,230.00		

INSPECTION

Date of Assignment: 24/04/2018

Date Inspected: 02/05/2018 Inspected At:

City Auto Pte Ltd (Sin Ming) (HQ)
Block 8 Sin Ming Road #01-58/60/62
Sin Ming Est
Singapore 575643

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	903.80 FL	*903.80 FL
2	1		*REAR BOOT EMBLEM -RSZ	Necessary	44.10 FL	*44.10 FL
3	1		*REAR BOOT EMBLEM -H	Not Necessary	31.90 FL	*- FL
4	1		*REAR BOOT EMBLEM -STREAM	Necessary	38.60 FL	*38.60 FL
5	1		*REAR BUMPER	Buckled	588.90 FL	*588.90 FL
6	2		*REAR BUMPER LOWER GARNISH	Distorted	645.00 FL	*645.00 FL
7	1		*REAR BUMPER LOWER RAD REFLECTOR	Not Necessary	45.80 FL	*- FL
8	1		*REAR BOOT LOCK	Repair	109.40 FL	*- FL
9	1		*REAR END PANEL	Repair	306.70 FL	*- FL
10	1		*REVERSE SENSOR	Shorted	350.00 FS	*300.00 FS
11	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
12	1		*NUMBER PLATE	Serviceable	25.00 FS	*- FS
13	1		*NUMBER PLATE GARNISH	Serviceable	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,164.20	2,560.40
- List Item Discount on L Items 20.00/20.00% (\$)	542.84	444.08
Total Parts (\$)	2,621.36	2,116.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	450.00	400.00
2	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	800.00	500.00
3	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS	New	120.00	120.00
4	TO SPRAY ANTI -RUST	New	80.00	30.00
Gross Labour Cost (\$)			1,450.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >