

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SINGAPORE 079909

INV No. AC2003967

INV Date 15/05/2020

Reference CC3/CTI18007557/K1ea3n2

Code CT

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 824D

Insured Veh. SJX 5708P

Claim No. SNM18D02165C02/8

Policy No. DMHCSN1684801600

Accident Date 22/04/2018

Inspection Date 23/04/2018

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile							
CHIN	IA TAIPING INSUI	RANCE (S) PTE LTD	Ref : CC3/CTI18007557/K1ea3n2				
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date: 15-05-2020 Code: CTI				
1.		Policy Particulars	- THIRD PARTY CLAIM				
	Insured Veh.	SJX 5708P	Veh. Inspected	SHC 824D			
	Policy No.	DMHCSN1684801600	Coverage (\$)	0.00			
	Claim No.	SNM18D02165C02/8	Excess (\$)	0.00			
	Assign From		Assign Date	23/04/2018			
2.	2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c	1685			
	Engine No.	HIDDEN	Year of Reg.	2015			
	Chassis No.	KMHLB41UMGU077095	Colour	YELLOW			
	Odometer	396994	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM			
	General	GOOD					
3.			ons of Tyres				
		Size	Make	Balance			
	R/H Front Tyre	205/60 R16	TRIANGLE	7 mm			
	L/H Front Tyre	205/60 R16	TRIANGLE	7 mm			
	R/H Rear Tyre	205/60 R16	TRIANGLE	7 mm			
	L/H Rear Tyre	205/60 R16	TRIANGLE	7 mm			
4.							
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.						
	DAMAGES SEE D						
5.		General	Information				
	Accident Date	22/04/2018	Inspection Date	23/04/2018			
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969					
5a.			emarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.		Estimate	Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Days				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

1,150.48

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 824D

REPLACEMENT OF PARTS REAR BUMPER REAR BUMPER REINFORCEMENT REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00 REAR BUMPER SIDE BRACKET REAR BUMPER CLIPS REAR BUMPER SPONGE REAR BUMPER UNDER COVER	DEFORMED SERVICEABLE SERVICEABLE SERVICEABLE NECESSARY SERVICEABLE	603.60 504.35 360.00 49.00 22.00 143.40	-
REAR BUMPER REINFORCEMENT REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00 REAR BUMPER SIDE BRACKET REAR BUMPER CLIPS REAR BUMPER SPONGE	SERVICEABLE SERVICEABLE SERVICEABLE NECESSARY	504.35 360.00 49.00 22.00	-
REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00 REAR BUMPER SIDE BRACKET REAR BUMPER CLIPS REAR BUMPER SPONGE	SERVICEABLE SERVICEABLE NECESSARY	360.00 49.00 22.00	-
@\$180.00 REAR BUMPER SIDE BRACKET REAR BUMPER CLIPS REAR BUMPER SPONGE	SERVICEABLE NECESSARY	49.00 22.00	-
REAR BUMPER CLIPS REAR BUMPER SPONGE	NECESSARY	22.00	
REAR BUMPER SPONGE			22.00
	SERVICEABLE	1/3 /0	
REAR BUMPER UNDER COVER		143.40	-
NEAR BOWN EN ONBER GOVER	CUT	225.00	225.00
LESS 20% DISCOUNT		-381.47	-170.12
		1,525.88	680.48
SPECIAL NETT ITEMS			
REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
		185.70	50.00
<u>LABOUR</u>			
PANEL BEATING .		250.00	200.00
SPRAY PAINTING CHARGE .		250.00	200.00
WIRING CHARGE.	NOT NECESSARY	50.00	-
R/REFIX REVERSE SENSOR .		120.00	20.00
		670.00	420.00
GRAND TOTAL		2,381.58	1,150.48
· · · · · · · · · · · · · · · · · · ·	SPECIAL NETT ITEMS REAR BUMPER REVERSE SENSOR (SN) REAR BUMPER RUBBER MAT (SN) LABOUR PANEL BEATING . SPRAY PAINTING CHARGE . WIRING CHARGE. R/REFIX REVERSE SENSOR .	SPECIAL NETT ITEMS REAR BUMPER REVERSE SENSOR (SN) REAR BUMPER RUBBER MAT (SN) LABOUR PANEL BEATING . SPRAY PAINTING CHARGE . WIRING CHARGE. R/REFIX REVERSE SENSOR .	### Table 1

RECOMMENDED COST OF REPAIRS

Report Ref No. CC3/CTI18007557/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 824D

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 824D

RE-INSPECTION





