

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 824D

DATE 23/4/2018 10:20

MAKE :

MODEL : HYUNDAI i40

CANK
LKK
JU

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>Abnormal</i>			\$ 603.60	
	Rear Bumper Reinforcement <i>X sec</i>			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X sec</i>		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket <i>X sec</i>			\$ 49.00	
	Rear Bumper Clips <i>sec</i>			\$ 22.00	
	Rear Bumper Sponge <i>X sec</i>			\$ 143.40	
	Rear Bumper Under Cover <i>sec</i>			\$ 225.00	
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor <i>X sec</i>			\$ 135.70	Nett
	Rear Bumper Rubber Mat <i>sec</i>			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge			200	
	Panel Beating			\$ 250.00	
	Spray Painting Charge			\$ 250.00	200
	Wiring Charge			\$ 50.00	X 20
	R/Refix Reverse Sensor			\$ 120.00	20
	TOTAL LABOUR			\$ 670.00	
	ESTIMATE TOTAL			\$ 2,381.58	
<i>Ka Li (UUA)</i> <i>23/4/18 1136h</i> <i>2 Rs.</i> <i>P/P</i> <i>Before Part ph</i>					
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey on "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					