

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8625C

MAKE :

MODEL : HYUNDAI i40

DATE 23/4/2018 13:31

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X Repair</i>			\$ 603.60
	Rear Bumper Side Bracket, LH <i>X su</i>			\$ 49.00
	Rear Bumper Clips <i>X 4"</i>			\$ 22.00
	Rear Bumper Under Cover <i>X su</i>			\$ 225.00
	SUB TOTAL			\$ 899.60
	LESS 20%			\$ 179.92
	DISCOUNTED TOTAL			\$ 719.68
	Labour Charge			
	Panel Beating			\$ 250.00 <i>100</i>
	Spray Painting Charge			\$ 250.00 <i>200</i>
	Wiring Charge			\$ 50.00 <i>X 11</i>
	R/Refix Reverse Sensor			\$ 120.00 <i>X 11</i>
	TOTAL LABOUR			\$ 670.00
	ESTIMATE TOTAL			\$ 1,389.68
<i>Kah 1 (11/11)</i> <i>23/4/18 13:31</i> <i>2 Pys</i> <i>P/P</i> <i>After Repair pLh</i>				
<div> LKK Auto Consultants hence notify the Repairer of the following: <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company </div> <div> Acknowledged by Repairer Signature: Date: </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				