

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

(EQ/LKK)

FZ

VEHICLE NO : SHD 3460U

DATE 23/4/2018 10:04

MAKE :

Fauzy

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,681.40
	Boot Lid Rubber ✗			\$ 115.80
	Boot Lid Lock Upper ✗			\$ 137.90
	Boot Lid Lock Lower ✗			\$ 31.70
	Boot Lid 'H' Emblem ✓			\$ -27.20
	Boot Lid CRDI Plate ✓			\$ -41.00
	Licence Lamp (RH) ✗			\$ 33.95
	Bootlid Moulding ✗			\$ 85.00
	Bootlid i40 Emblem ✓			\$ -41.00
	Bootlid Lower Garnish ✗			\$ 398.00
	Rear Bumper ✓			\$ -603.60
	Rear Bumper Reinforcement ✓			\$ -504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ✓		\$ 180.00	\$ -360.00
	Rear Bumper Side Bracket ?		\$ 49.00	\$ 7 98.00
	Rear Bumper Clips ✓			\$ -22.00
	Rear Bumper Sponge ✓			\$ -143.40
	Rear Bumper Under Cover ✓			\$ -225.00
	Tail Lamp Quarter Panel (RH) ✗			\$ 97.90
	Rear Panel ✗			\$ 592.30
	Rear Panel Garnish ?			\$ 7 57.70
	Rear Panel Lower Panel ✗			\$ 495.50
	SUB TOTAL			\$ 5,792.70
	LESS 20%			\$ 1,158.54
	DISCOUNTED TOTAL			\$ 4,634.16
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00 Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70 Nett
	Rear Fender Advertisement Logo (LH/RH) ✓			\$ 200.00 Nett
	Labour Charge			
	Panel Beating			\$ 750.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,720.00
	ESTIMATE TOTAL			\$ 6,719.86

LKK Auto Consultants have notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a 'Without Prejudice' basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Kekidick
 23/4/18 1226h
 3 Days.
 PIP

Before Part p/h

Nett
 Nett
 Nett
 600
 600
 x
 20
 20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.