



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18007594/Kpa3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 10-10-2018



ATTN: RICHARD ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKG 7102B	Veh. Inspected	SGF 653B
Policy No.	GA272259/1	Coverage (\$)	0.00
Claim No.	S8M00EZ7	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	24/04/2018

2. Vehicle Particulars & Condition

Make & Model	KIA PICANTO (M)	c.c	1086
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	KNABA24326T285926	Colour	METALLIC ORANGE
Odometer	113622	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	165/65R13	ROAD WEAR	8 mm
L/H Front Tyre	165/65R13	ROAD WEAR	8 mm
R/H Rear Tyre	165/65R13	TOYO	8 mm
L/H Rear Tyre	165/65R13	TOYO	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/04/2018	Inspection Date	02/05/2018
Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------