

ASS. REC. BY:

REF:

CS/FCL18007613/TTrb⁰²

Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person):

CWS Irene Jaw

of

FCL

Date/Time:

24/04/2018 4:11pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 8964P

Insured:

SHA 8140B

at Workshop m/s

Autofrance

Tel:

6319 0174

of

305 Alexandra Rd

Policy No:

Claim No:

D18003157 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

20042018

(Client's Record)

CA / REV / REP. / REV 24 HRS. DS.

04/05/2018 @ after 4pm

H.O.D. Endorsement:

Date/Time:

25/04/2018 10:50am

Person Contacted:

Cordine

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	Shabbir.
	SKW 8964P - X	
	SHA 8140B - CS/FCL17016619 / Agbr2	DVA: 250317
	Confirm \$5502.30 : 5 days	
	Red: \$9895.30, 64%	

Signature: *Tan*

REF: FCL

ASSIGNMENT

From: Date: 04/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 8964P
at Workshop n/s: Autofrance
of 305 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Shubir
after 4pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKW 8964P Yr Regn: 2015 Nov

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Peugeot 308 c.c 1199

Colour: Bronze A/C: Insured / Std / NI / NA

Sp. Reading: 23630 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VF3LRHNYWFS208767

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17
R: 225/45R17

BS / DUN / EXNOVA / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A.	D.O.I. 4/5/18 @ 1630

Survey held at: Autofrance

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 15 AUG 2018

Date/Time: File Pass to?

1) typist
Date/Time: File Return to?

2)

Report Format: TP

Lump Sum / I.B.I: \$5502.30

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

1) S-RS: \$

2) Photos

3) Other

TOTAL

5X15: 75

170+
50
50
43

388

MOTOR SURVEY ASSIGNMENT

Date	23-04-2018	Our Ref No. D18003157MFSH
Accident Date	20-04-2018	Claim Type. Third Party
Insured Vehicle	SHA8140B	Third Party Vehicle. SKW8964P
Survey Location	305 ALEXANDRA ROAD	
Contact Person.	CAROLINE	
Contact No.	63762288/ 0	Fax No. 64777373
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AUTOFRANCE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : BP 3662
 Date Estimated : 23/04/2018
 Prepared By : Mohamed Shabir Abdul Hamid

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Gan Siong Jin Julian (Yan Shangren)
 27 West Coast Crescent
 #11-23

Singapore 128048

- ACCOUNT - 2000

CASH - Sale service

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKW8964P	VF3LRHNYWFS208467	20/11/2015	308SW1.2 Allure	0

DESCRIPTION

SUNDRIES

VALUE

nec 30. 150.00

ELECTRICLA WIRING CHECK FOR PROPER FUNCTIONING (NETT)

✓ 150.00

TO REMOVE AND REFIX REAR BUMPE REVERSE SENSOR,
CONDUCT DISTANCE SETTING (NETT)

✓ 150.00

TUFF KOTE - BODY CAVITY PRESERVATION (NETT) @ \$60.00
PER-PANEL-

X 180.00

SEALANT FOR BODY PANEL (NETT) @ \$90.00-PER-PANEL

X 270.00

TO REMOVE AND REFIX REAR LH QUARTER GLASS CONDUCT
WATER LEAK TEST TO FACILITATE REPAIR (NETT)_

X 600.00

SEALANT FOR QUARTER GLASS LH (NETT)

X 60.00

INNER SEAL FOR QUARTER GLASS (NETT)

X 50.00

TO REMOVE AND REFIX REAR LH QUARTER GLASS SOLAR FILM
(NETT)

X 350.00

TO REPAIR, REPLACE TAIL GATE REAR BUMPER, REAR END
PANEL, TAIL LAMP PANEL, REAR LH FENDER, REAR
REINFORCEMENT AND ALL OTHER AFFECTED PARTS AND AREAS

1500 1200. 3,600.00

TO SPRAY PAINT REAR BUMPER REAR TAIL GATE, REAR END
PANEL REAR LH QUARTER PANEL REAR LH TAIL LAMP PANE,
AND ALL OTHER AFFECTED PARTS AND AREAS

1500 1200. 3,000.00

TO CONDUCT 4 WHEEL ALIGNMENT CHECK STEERING ANGLE
AND GEOMETRY (NETT)

un X 600.00

TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT
CODES RESTORE PROGRAMME MODULES (NETT)

✓ 600.00

Total Labour 1: 9,760.00

DESCRIPTION

REAR BUMPER

QTY

PRICE

DISC

VALUE

1

800.00

10%

de 720.00

720

GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : **BP 3662**
 Date Estimated : **23/04/2018**
 Prepared By : **Mohamed Shabir Abdul Hamid**

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKW8964P	VF3LRHNYWFS208467	20/11/2015	308SW1.2 Allure	0

DESCRIPTION	QTY	PRICE	DISC	VALUE
RR BUMPER SIDE BRACKET SET	1	60.00	10.00	54.00
RR BUMPER CENTRAL BRACKET	1	80.00	10.00	72.00
RR BUMPER BRACKET SUPERIEUR	1	54.00	10.00	48.60
RR BUMPR HFAS AERIAL SUPPORT	1	25.00	10.00	22.50
RR BPR REINFORCEMENT	1	225.00	10.00	202.50
SET PROXIMITY SENSOR SUPPORTS RR	1	103.00	10.00	92.70
RR BUMPER FIXING STIFFENER SET	1	80.00	10.00	72.00
REAR END PANEL ASSY	1	535.00	10.00	481.50
TAILGATE ASSY	1	2,253.00	10.00	2,027.70
REAR WING LH ASSY	1	890.00	10.00	801.00
TAILLAMP OUTER LH	1	305.00	10.00	274.50
TAILLAMP INNER LH	1	246.00	10.00	221.40
RR BUMPER REFLECTOR LH	1	20.00	10.00	18.00
SENSOR-OBSTACLE DETECTION FRT/REAR	2	99.00	10.00	178.20
OBSTACLE DETECTION SENSOR FRT/RR	1	180.00	10.00	162.00

Total Parts : **5,637.60**
LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tauhin 97493789
 - WP

4/5/18 @ 1630

5 days

Reming before paint

sure @ (LKK Auto Consultants)

Customer Service Officer

Contact

Labour 1	:	15397.60	9,760.00
Parts	:		5,637.60
Labour 2	:	15208.60	0.00
Excess	:		0.00
Total GST @ 7%	:		1,077.83
Grand Total	:		16,475.43

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Co. Regs. No. 52907220C GST Regs. No. M2-0000551-1

305 Alexandra Road

Vantage Automotive Centre

Singapore 159942

Service Booking: 6477 7377

Parts: 6477 7420

Vantage 24-Hour Assist: 6473 8588

Fax: 6477 7300

**PEUGEOT****SERVICE TAX INVOICE**

RE-PRINT

REPAIR ORDER NO. bp 114357	Date IN 04/05/2018	Invoice Number	Page No. 1 of 2
	Payment Term 30 Days From Invoice	Invoice Date	
	Customer Service Advisor Mohamed Shabir Abdul Hamid	Invoice By Mohamed Shabir Abdul Hamid	
CUSTOMER INFORMATION		INVOICE TO 14356	
Gan Siong Jin Julian (Yan Shangren) 27 West Coast Crescent #11-23 Singapore 128048		First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	
REGISTRATION No. SKW8964P	CHASSIS No. VF3LRHNYWFS208467	STOCK No. 208870	REGISTRATION DATE 20/11/2015
		MODEL 308SW1.2 Allure	MILEAGE 23630

CODE	DESCRIPTION	UNITS	DISC %	NETT
	SUNDRIES	1	0.00	30.00
	ELECTRICLA WIRING CHECK FOR PROPER FUNCTIONING (NETT)	1	0.00	150.00
	TO REMOVE AND REFIX REAR BUMPE REVERSE SENSOR, CONDUCT DISTANCE SETTING (NETT)	1	0.00	150.00
	TO REPAIR, REPLACE TAIL GATE REAR BUMPER, REAR END PANEL, TAIL LAMP PANEL, REAR LH FENDER, REAR REINFORCEMENT AND ALL OTHER AFFECTED PARTS AND A	1	0.00	1,500.00
	TO SPRAY PAINT REAR BUMPER REAR TAIL GATE, REAR END PANEL REAR LH QUARTER PANEL REAR LH TAIL LAMP PANE, AND ALL OTHER AFFECTED PARTS AND AREAS	1	0.00	1,500.00
	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE PROGRAMME MODULES (NETT)	1	0.00	600.00
Sub-Total :				3,930.00

CODE	DESCRIPTION	UNITS	DISC %	NETT
1608472280	OBSTACLE DETECTION SENSOR FRT/RR	1	10.00	162.00
1611609180	REAR BUMPER	1	10.00	720.00
1611616380	SET PROXIMITY SENSOR SUPPORTS RR	1	10.00	92.70
1611616480	RR BUMPER SIDE BRACKET SET	1	10.00	54.00
1611616780	RR BUMPER BRACKET SUPERIEUR	1	10.00	48.60
9677378480	RR BPR REINFORCEMENT	1	10.00	202.50
9678093980	TAILLAMP OUTER LH	1	10.00	274.50
9804315280	RR BUMPER REFLECTOR LH	1	10.00	18.00
Sub-Total :				1,572.30

Attending CSO : Mohamed Shabir Abdul Hamid
Should you require further explanation, please reach me at

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Co. Regs. No. 52907220C GST Regs. No. M2-0000551-1

 305 Alexandra RoadVantage Automotive Centre
Singapore 159942 Service Booking: 6477 7377

Parts: 6477 7420

Vantage 24-Hour Assist: 6473 8588

Fax: 6477 7300

**PEUGEOT****SERVICE TAX INVOICE**

RE-PRINT

REPAIR ORDER NO. bp 114357	Date IN	Invoice Number	Page No.
	04/05/2018		2 of 2
	Payment Term	Invoice Date	
	30 Days From Invoice		
	Customer Service Advisor	Invoice By	
	Mohamed Shabir Abdul Hamid	Mohamed Shabir Abdul Hamid	

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	5,502.30
Labour Charges	3,930.00	Less Insurance Excess	S\$	0.00
Parts Charges	1,572.30	GST @ 7%	S\$	385.16
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	5,887.46
		Less Deposit/Voucher	S\$	0.00
Computer generated invoice. No signature is required.		Amount Payable	S\$	5,887.46
All amounts are in Singapore Dollars. Work was carried out subject to the Company's Terms and Conditions of Service. No complaints will be entertained unless reported within seven (7) days of the date of this invoice. For credit purchases, interest @1% per month will be debited on overdue amounts.				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007615/T1rbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-08-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8140B	Veh. Inspected	SKW 8964P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003157MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	24/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	PEUGEOT 308	c.c	1199	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF3LRHNYWFS208467	Colour	BRONZE	
Odometer	23630	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	GOODYEAR	6 mm	
L/H Front Tyre	225/45 R17	GOODYEAR	6 mm	
R/H Rear Tyre	225/45 R17	GOODYEAR	6 mm	
L/H Rear Tyre	225/45 R17	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/04/2018	Inspection Date	04/05/2018	
Survey held at	AUTOFRANCE 305, ALEXANDRA ROAD SINGAPORE 159942.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 8964P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	150.00	30.00
1	RR BUMPER SIDE BRACKET SET (SN)	NECESSARY	54.00	54.00
1	RR BUMPER CENTRAL BRACKET (SN)	NOT NECESSARY	72.00	-
1	RR BUMPER BRACKET SUPERIEUR (SN)	CRACKED	48.60	48.60
1	RR BUMPR HFAS AERIAL SUPPORT (SN)	NOT NECESSARY	22.50	-
1	RR BPR REINFORCEMENT (SN)	BENT	202.50	202.50
1	SET PROXIMITY SENSOR SUPPORTS RR (SN)	DISTORTED	92.70	92.70
1	RR BUMPER FIXING STIFFENER SET (SN)	NOT NECESSARY	72.00	-
1	REAR END PANEL ASSY (SN)	NOT NECESSARY	481.50	-
1	TAILGATE ASSY (SN)	NOT NECESSARY	2,027.70	-
1	REAR WING LH ASSY (SN)	TO REPAIR SEE LABOUR	801.00	-
1	TAILLAMP OUTER LH (SN)	CRACKED	274.50	274.50
1	TAILLAMP INNER LH (SN)	NOT NECESSARY	221.40	-
1	RR BUMPER REFLECTOR LH (SN)	CRACKED	18.00	18.00
2	SENSOR-OBSTACLE DETECTION FRT/REAR (SN)	NOT NECESSARY	178.20	-
1	OBSTACLE DETECTION SENSOR FRT/RR (SN)	DISTORTED	162.00	162.00
1	REAR BUMPER (SN)	DEFORMED	720.00	720.00
			5,598.60	1,602.30
LABOUR				
	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING.		150.00	150.00
	TO REMOVE AND REFIX REAR BUMPE REVERSE SENSOR,CONDUCT DISTANCE SETTING.		150.00	150.00
	TUFF KOTE-BODY CAVITY PRESERVATION.	NOT NECESSARY	180.00	-
	SEALANT FOR BODY PANEL.	NOT NECESSARY	270.00	-
	TO REMOVE AND REFIX REAR LH QUARTER GLASS CONDUCT WATER TEST TO FACILITATE REPAIR.	NOT NECESSARY	600.00	-
	SEALANT FOR QUARTER GLASS LH.	NOT NECESSARY	60.00	-
	INNER SEAL FOR QUARTER GLASS.	NOT NECESSARY	50.00	-
	TO REMOVE AND REFIX REAR LH QUARTER GLASS SOLAR FILM.	NOT NECESSARY	350.00	-

Report Ref No. CS/FCI18007615/T1rhn2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPAIR,REPLACE TAIL GATE REAR BUMPER,REAR END PANEL,TAIL LAMP PANEL,REAR LH FENDER,REAR REINFORCEMENT AND ALL OTHER AFFECTED PARTS AND AREAS..INCLUSIVE OF THE REPAIR OF REAR WING LH ASSY.		3,600.00	1,500.00
	TO SPRAY PAINT REAR BUMPER,REAR TAIL GATE,REAR END PANEL,REAR LH QUARTER PANEL,REAR LH TAIL LAMP PANE AND ALL OTHER AFFECTED PARTS AND AREAS.		3,000.00	1,500.00
	TO CONDUCT 4 WHEEL ALIGNMENT CHECK STEERING ANGLE AND GEOMETRY.	NOT NECESSARY	600.00	-
	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE PROGRAMME MODULES.		600.00	600.00
			9,610.00	3,900.00
GRAND TOTAL			15,208.60	5,502.30
RECOMMENDED COST OF REPAIRS				5,502.30

Report Ref No. CS/FCI18007615/T1rbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.