

2209202

ASS. REC. BY:

REF:

CS3 / sm017021630 / TTB-1

Special Instruction:

range & days

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Thelma Choo

of

SMD

Date/Time: 25/04/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SU 9881T

Insured:

G88 7553R

at Workshop m/s

Soon Bodywerkz

Tel:

9367 8159.

of

Blok 1002 Bukit Merah Lane 3

01-83

Policy No:

Claim No:

CMT01704024 / THE

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 10.11.2017

CA / REV / REP. / REV 24 HRS 'wp'

14.11.2017

H.O.D. Endorsement:

Date/Time:

13.11.2017 3:30pm

Person Contacted:

Roger

Vehicle: IN / OUT

Date/Time

Action/Instruction (X) Estimate

SU 9881T - X

G88 7553R X

Dismantle Part: 16.11.2017

30.11.17 4:20pm

Email to Sherry Wong

Submit 24350/- lump sum, 14 days
(Red: 12550/-, 34%)

URGENT

Taufik,

Pls see my remarks & check
all parts prices

RECEIVED 20 JUN 2018

25/5/2018

480-160 = 290

Catherine Chong (LKK Auto)

From: Choo, Thelma <thelma.choo@sompo.com.sg>
Sent: Wednesday, 25 April, 2018 4:28 PM
To: Catherine Chong (LKK Auto); Wong, Shi Yi Shery; 'assignments'
Subject: RE: Our Reference: CMTD1704024/THE , Your Reference: SCU9881T (V) SBW , PRI
Attachments: 4660_001.pdf

Dear Catherine,

We refer to the your survey report CS3/SMO17021630/T1bs2

We attached herewith the third party survey report for your attention.

Please get your surveyor to do a paper re-survey based on the third party survey report

Best Regards
Thelma Choo
Claims Divisions
D: 6322 4681 | T: 6461 6555 | F: 6221 3147

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, December 12, 2017 4:59 PM
To: Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>; 'assignments' <assignments@lkkauto.com>
Cc: Henry, Irene James <irene.henry@sompo.com.sg>; Choo, Thelma <thelma.choo@sompo.com.sg>
Subject: RE: Our Reference: CMTD1704024/THE , Your Reference: SCU9881T (V) SBW , PRI

Dear Shery,

Enclosed Pre-repair Survey Report of SCU 9881T.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong, Shi Yi Shery [mailto:Shery.Wong@sompo.com.sg]
Sent: Friday, 8 December, 2017 1:46 PM
To: 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>; 'assignments' <assignments@lkkauto.com>

Cc: Henry, Irene James <irene.henry@sompo.com.sg>; Choo, Thelma <thelma.choo@sompo.com.sg>
Subject: RE: Our Reference: CMTD1704024/THE , Your Reference: SCU9881T (V) SBW , PRI

Hi Catherine,

Can we have the preliminary report for this mentioned claim?

Best Regards

Shery Wong

Claims Division

T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]

Sent: Thursday, November 30, 2017 4:22 PM

To: Wong, Shi Yi Shery; 'assignments'

Cc: Henry, Irene James; Choo, Thelma

Subject: RE: Our Reference: CMTD1704024/THE , Your Reference: SCU9881T (V) SBW , PRI

Dear Shery,

Refer to your assignment on 13.11.2017 at 3.07PM.

Please be informed that we have inspected the vehicle SCU 9881T on 14.11.2017 at 5.15PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]

Sent: Monday, 13 November, 2017 3:32 PM

To: 'Wong, Shi Yi Shery' ; 'assignments'

Cc: 'Henry, Irene James'; 'Choo, Thelma'

Subject: RE: Our Reference: CMTD1704024/THE , Your Reference: SCU9881T (V) SBW , PRI

Dear Shery,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong, Shi Yi Shery [<mailto:Shery.Wong@sompo.com.sg>]

Sent: Monday, 13 November, 2017 3:07 PM

To: 'riaz@justice.com.sg' <riaz@justice.com.sg>; assignments <assignments@lkkauto.com>

Cc: Henry, Irene James <irene.henry@sompo.com.sg>; Choo, Thelma <thelma.choo@sompo.com.sg>; 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>

Subject: FW: Our Reference: CMTD1704024/THE , Your Reference: SCU9881T (V) SBW , PRI

Our Reference: CMTD1704024/THE

Your Reference: SCU9881T (V) SBW

Date: 13TH November 2017 **Without Prejudice**

BY EMAIL ONLY

Attention:

M/S C RIAZ LLC

Accident involving GBB7553R and SCU9881T on 10/11/2017

Dear Sirs,

We refer to your email reply dated 13/11/2017.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Aside to LKK AUTO,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (SCU9881T).

Thank you.

Best Regards

Shery Wong

Claims Division

D: 6329 5339 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Huiling [<mailto:riaz@justice.com.sg>]

Sent: Monday, November 13, 2017 2:02 PM

To: Wong, Shi Yi Shery

Cc: Henry, Irene James; Choo, Thelma

Subject: RE: Our Reference: CMTD1704024/THE , Your Reference: SCU9881T (V) SBW , PRI

WITHOUT PREJUDICE

Dear sirs,

We refer to your below email.

On behalf of our client, we disagree with your appointment and nominates as the surveyor.

Please choose one out of the surveyor from the list below:-

1. Chang Fuh Keong, Dave
2. Ho Joo Loong, Danny
3. Dennis Yap
4. Michael Yap
5. Lee Kok Weng
6. Winson Goh

7. Ong Ah Keng, Kent
8. Ong Poh Meng
9. Seah Kwang Boon
10. Thor Teck Soon, David

Kindly revert within the allotted time pursuant to NIMA protocol.

Thanks and Best Regards,

HUILING
RIAZ LLC
133 NEW BRIDGE ROAD
09-09 CHINATOWN POINT
SINGAPORE 059413
TEL : 6534-0110 FAX : 6534-0220

**** DISCLAIMER****

THIS EMAIL AND ANY FILES TRANSMITTED WITH IT ARE CONFIDENTIAL AND SUBJECT TO LEGAL PROFESSIONAL PRIVILEGE AND INTENDED SOLELY FOR THE USE OF THE INDIVIDUAL OR ENTITY TO WHO THEY ARE ADDRESSED. IF YOU HAVE RECEIVED THIS EMAIL IN ERROR PLEASE NOTIFY THE SYSTEM MANAGER. THIS MESSAGE CONTAINS CONFIDENTIAL INFORMATION AND IS INTENDED ONLY FOR THE INDIVIDUAL NAMED. IF YOU ARE NOT THE NAMED ADDRESSEE YOU SHOULD NOT DISSEMINATE, DISTRIBUTE OR COPY THIS EMAIL. PLEASE NOTIFY THE SENDER IMMEDIATELY BY EMAIL IF YOU HAVE RECEIVED THIS EMAIL BY MISTAKE AND DELETE THIS EMAIL FROM YOUR SYSTEM. IF YOU ARE NOT THE INTENDED RECIPIENT YOU ARE NOTIFIED THAT DISCLOSING, COPYING, DISTRIBUTING OR TAKING ANY ACTION IN RELIANCE ON THE CONTENTS OF THIS INFORMATION IS STRICTLY PROHIBITED.

From: Wong, Shi Yi Shery [<mailto:Shery.Wong@sompo.com.sg>]
Sent: Monday, 13 November, 2017 12:57 PM
To: 'riaz@justice.com.sg' <riaz@justice.com.sg>
Cc: Henry, Irene James <irene.henry@sompo.com.sg>; Choo, Thelma <thelma.choo@sompo.com.sg>
Subject: Our Reference: CMTD1704024/THE , Your Reference: SCU9881T (V) SBW , PRI

Our Reference: CMTD1704024/THE
Your Reference: SCU9881T (V) SBW

Date: 13TH November 2017 Without Prejudice

BY EMAIL ONLY

Attention:

M/S C RIAZ LLC

Accident involving GBB7553R and SCU9881T on 10/11/2017

Dear Sir

We refer to your Notice of Accident via fax dated 13/11/2017.

Please be informed that Thelma is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Shery Wong

Claims Division

T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain

confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.



SINCERE APPRAISAL SERVICES

VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 677/TP/2017

Date: 2/1/2018

REFERENCE

Date of loss: 10/11/2017
Claimant: Lim Kheng Joo

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCU9881T	Make &	Honda
Reg date:	28/5/2015	Model	Vezel 1.5S
Colour:	Blue	Engine No:	L15B3519378
Type:	Motor Car	Chassis No:	RU11019363
Type of Claims:	Third Party	Odometer No:	62985km
		Engine Cap:	1496cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

(STATIC ONLY)

General Condition: Good	Steering: Good	Engine Modification: Nil
Paint work: Good	Handbrake: Good	Pre-accident
	Footbrake: Good	Damage: Nil

CONDITION OF TYRES

Front Left Size: Yokohama 225/45R18 70%	Front Right Size: Yokohama 225/45R18 70%
Rear Left Size: Yokohama 225/45R18 70%	Rear Right Size: Yokohama 225/45R18 70%

The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS


	Repairer S\$	Adjuster S\$
Parts	\$ 39,375.20	\$ 38,524.00
Labour	\$ 8,770.00	\$ 7,550.00
Calculated Cost (S\$):	<u>\$ 48,145.20</u>	<u>\$ 46,074.00</u>

Recommended Lump Sum Repair Cost (S\$): \$ 36,900.00

Date of Assignment: 11/11/2017
Date Inspected: 11/11/2017
Est. repair Period: 16 days

Inspected At: Soon Bodywerkz Auto Pte Ltd
1002 Bukit Merah Lane 3
#01-83
Singapore 159719

POINT OF IMPACT



BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle along PIE Expressway towards BKE Expressway.

GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the front and rear portion.

SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$48,145.20. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$36,900.

We have not authorised the repair. Under normal circumstances, estimated **16** working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Dave Chang
Automotive Appraiser
AUTO. ENG, CAE, CGI
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Front bumper assy	dented/cracked	\$ 1,290.00	\$ 1,290.00 900
2	2	Front bumper bracket	bent/necessary	\$ 186.00	\$ 186.00 XNS
3	2	Front bumper retainer	bent/necessary	\$ 188.00	\$ 188.00 120
4	1	Front bumper reinforcement	deformed	\$ 352.00	\$ 352.00
5	1	Front bumper lower grille	bent	\$ 194.00	\$ 194.00
6	1	Front bumper tow cover	warped/necessary	\$ 88.00	\$ 88.00
7	1	Front grille complete assy	cracked	\$ 482.00	\$ 482.00
8	1	Front grille emblem	necessary	\$ 105.00	\$ 105.00
9	1	Front left fog lamp	bent/dislodged	\$ 280.00	\$ 280.00
10	1	Front right fog lamp	bent/dislodged	\$ 280.00	\$ 280.00
11	1	Front left fog lamp garnish	bent	\$ 121.00	\$ 121.00
12	1	Front right fog lamp garnish	bent	\$ 121.00	\$ 121.00
13	1	Front left HID headlamp	cracked	\$ 1,678.00	\$ 1,678.00 1450
14	1	Front right HID headlamp	cracked	\$ 1,678.00	\$ 1,678.00 1450
15	1	Front bonnet assy	dented	\$ 1,681.00	\$ 1,681.00 1130
16	1	Front bonnet lock	bent	\$ 186.00	\$ 186.00
17	1	Front bonnet lock bracket	bent	\$ 76.00	\$ 76.00
18	2	Front bonnet hinges	bent	\$ 188.00	\$ 188.00 XNN
19	1	Front bonnet lock cover	bent	\$ 75.00	\$ 75.00
20	1	Front support panel	repair	\$ 1,064.00	\$ -
21	1	Front support panel top garnish	bent/warped	\$ 205.00	\$ 205.00
22	2	Front support panel side garnish	warped/cracked	\$ 160.00	\$ 160.00
23	1	Front left air duct	bent	\$ 178.00	\$ 178.00
24	1	Front radiator assy	bent	\$ 1,670.00	\$ 1,670.00 1100.50
25	1	Front radiator fan cowling assy	bent	\$ 378.00	\$ 378.00 XNN
26	1	Front air con condenser assy	bent	\$ 1,120.00	\$ 1,120.00 900
27	1	Front ambient sensor	malfunction	\$ 298.00	\$ 298.00 ✓
28	1	Front air con condenser fan cowling assy	bent	\$ 376.00	\$ 376.00
29	1	Front radiator fan motor assy	malfunction	\$ 310.00	\$ 310.00 XNN
30	1	Front air con fan motor assy	malfunction	\$ 310.00	\$ 310.00 XNN
				\$ 15,318.00	\$ 14,254.00 91675
Less 20%				\$ 3,063.60	\$ 2,850.80
				\$ 12,254.40	\$ 11,403.20 7334
<u>Special Nett Items</u>					
1	10	Front bumper clips	necessary	\$ 50.00	\$ 50.00
2	6	Front support panel top garnish clips	necessary	\$ 30.00	\$ 30.00
3	1	Front no plate with garnish	necessary	\$ 120.00	\$ 120.00 60
4	6	Front grille clips	necessary	\$ 30.00	\$ 30.00
5	1	Front bumper lower spoiler	bent/warped	\$ 1,250.00	\$ 1,250.00 ← 600
6	10	Front bumper lower spoiler clips	necessary	\$ 40.00	\$ 40.00
7	1	Front bumper lower spoiler sealant	necessary	\$ 80.00	\$ 80.00 50
8	1	Front left LED lamp	malfunction	\$ 350.00	\$ 350.00 XNN
9	1	Front right LED lamp	malfunction	\$ 350.00	\$ 350.00 XNN
				\$ 2,300.00	\$ 2,300.00 1650
Total Parts				\$ 14,554.40	\$ 13,703.20

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Rear bumper assy	deformed	\$ 1,098.00	\$ 1,098.00 880
2	1	Rear bumper left retainer	bent/necessary	\$ 83.00	\$ 83.00
3	1	Rear bumper right retainer	bent/necessary	\$ 83.00	\$ 83.00
4	1	Rear bumper left reflector	bent/warped	\$ 93.00	\$ 93.00
5	1	Rear bumper right reflector	bent/warped	\$ 93.00	\$ 93.00
6	1	Rear bumper left side lower panel	dented	\$ 687.00	\$ 687.00
7	1	Rear bumper right side lower panel	dented	\$ 687.00	\$ 687.00
8	2	Rear bumper reflector	bent/necessary	\$ 190.00	\$ 190.00
9	2	Rear bumper mud flap	bent	\$ 180.00	\$ 180.00
10	1	Rear left side bumper	warped/bent	\$ 355.00	\$ 355.00 195
11	1	Rear right side bumper	warped/bent	\$ 355.00	\$ 355.00 195
12	1	Rear tailgate assy	deformed	\$ 1,887.00	\$ 1,887 1200
13	1	Rear tailgate outer handle	deformed	\$ 98.00	\$ 98.00
14	1	Rear tailgate lock	bent	\$ 175.00	\$ 175.00
15	1	Rear tailgate inner trim board	warped/necessary	\$ 476.00	\$ 476.00 295
16	1	Rear tailgate weatherstrip	warped/necessary	\$ 188.00	\$ 188.00
17	2	Rear tailgate damper	malfunction	\$ 296.00	\$ 296.00 XNN
18	1	Rear tailgate centre logo	necessary	\$ 105.00	\$ 105.00
19	1	Rear left tailgate taillamp	cracked	\$ 342.00	\$ 342.00
20	1	Rear right tailgate taillamp	cracked	\$ 342.00	\$ 342.00
21	1	Rear tailgate outer garnish	warped/bent	\$ 378.00	\$ 378.00
22	1	Rear left taillamp	cracked	\$ 866.00	\$ 866.00 660
23	1	Rear right taillamp	cracked	\$ 866.00	\$ 866.00 660
24	1	Rear left fender inner garnish	warped/bent	\$ 475.00	\$ 475.00
25	1	Rear right fender inner garnish	warped/bent	\$ 475.00	\$ 475.00
26	1	Rear left fender protector	bent/warped	\$ 197.00	\$ 197.00
27	1	Rear right fender protector	bent/warped	\$ 197.00	\$ 197.00
28	1	Rear floor panel	deformed	\$ 1,670.00	\$ 1,670.00 1230
29	1	Rear wiper motor	malfunction	\$ 298.00	\$ 298.00 XNN
30	1	Rear spare tyre top cover	bent	\$ 278.00	\$ 278.00
31	1	Rear lower duct cover	warped/bent	\$ 380.00	\$ 380.00
32	1	Rear windscreen glass assy	shattered	\$ 1,880.00	\$ 1,880.00 1472
33	1	Rear windscreen glass moulding	necessary	\$ 188.00	\$ 188.00 XNN
34	1	Rear windscreen glass inner side garnish	necessary/bent	\$ 280.00	\$ 280.00 XNN
35	1	Rear windscreen glass centre garnish	necessary/bent	\$ 165.00	\$ 165.00 XNN
36	1	Rear end lower panel	deformed	\$ 976.00	\$ 976.00
37	1	Rear end lower panel top garnish	warped/cut/bent	\$ 185.00	\$ 185.00
38	1	Rear exhaust muffler assy	bent/cut	\$ 1,297.00	\$ 1,297.00 925
39	4	Rear exhaust muffler rubber mounting	necessary	\$ 66.00	\$ 66.00
40	1	Rear exhaust centre pipe	warped/bent	\$ 1,679.00	\$ 1,679.00 1250
41	1	Rear exhaust tail end pipe	necessary/bent	\$ 180.00	\$ 180.00
			17322	\$ 20,789.00	\$ 20,789.00
		Less 20%	13857.60	\$ 4,157.80	\$ 4,157.80
				\$ 16,631.20	\$ 16,631.20

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
42	1	Rear wiper blade assy	malfunction	\$ 166.00	\$ 166.00 XNN
43	1	Rear right fender assy	buckled	\$ 2,167.00	\$ 2,167.00 / 250
44	1	Rear lower centre cover	warped/bent	\$ 350.00	\$ 350.00 250
45	1	Rear exhaust muffler heat shield	warped/bent	\$ 179.00	\$ 179.00
				\$ 2,862.00	\$ 2,862.00 / 845
Less 20%				\$ 572.40	\$ 572.40
				\$ 2,289.60	\$ 2,289.60 / 476
<u>Special Nett Items</u>					
1	10	Rear bumper clips	necessary	\$ 50.00	\$ 50.00
2	1	Rear bumper lower spoiler assy	bent/warped	\$ 1,250.00	\$ 600 1,250.00
3	10	Rear bumper lower spoiler clips	necessary	\$ 40.00	\$ 40.00
4	1	Rear bumper lower spoiler sealant	necessary	\$ 80.00	\$ 80.00 50
5	16	Rear tailgate inner trim board clips	necessary	\$ 30.00	\$ 30.00
6	6	Rear end lower panel top garnish clips	necessary	\$ 20.00	\$ 20.00
7	1set	Rear windscreen glass centre garnish clips	necessary	\$ 30.00	\$ 30.00
8	1	Rear windscreen glass sealant	necessary	\$ 80.00	\$ 80.00 50
9	1set	Rear windscreen glass inner side garnish clips	necessary	\$ 30.00	\$ 30.00
10	8	Rear lower duct cover clips	necessary	\$ 30.00	\$ 30.00
11	1	Rear right fender sealant	necessary	\$ 80.00	\$ 80.00 XNN
12	8	Rear left fender inner garnish clips	necessary	\$ 30.00	\$ 30.00
13	8	Rear right fender inner garnish clips	necessary	\$ 30.00	\$ 30.00
14	6	Rear left fender protector clips	necessary	\$ 20.00	\$ 20.00
15	6	Rear right fender protector clips	necessary	\$ 20.00	\$ 20.00
16	6	Rear tailgate outer garnish clips	necessary	\$ 30.00	\$ 30.00
17	1	Rear view camera	malfunction	\$ 300.00	\$ 200 300.00
18	4	Rear bumper reverse sensor	malfunction	\$ 500.00	\$ 250 500.00
19	1	Rear no plate with garnish	necessary	\$ 120.00	\$ 60 120.00
20	1	Rear sub woofer assy	malfunction	\$ 750.00	\$ 750.00
21	1	Rear sub woofer amplifier	malfunction	\$ 650.00	\$ 650.00 XNN
22	1set	Front speaker amplifier	malfunction	\$ 850.00	\$ 850.00
23	1set	Rear speaker amplifier	malfunction	\$ 850.00	\$ 850.00
24	8	Rear lower centre cover clips	necessary	\$ 30.00	\$ 30.00
				\$ 5,900.00	\$ 5,900.00 550
Total Parts				\$ 24,820.80	\$ 24,820.80

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,400.00	\$ 1,200.00 700
2	To putty and spray painting front portion.	\$ 1,400.00	\$ 1,200.00 1000
3	To check wiring and focus front headlamp.	\$ 50.00	\$ 30.00
4	To remove and install front bonnet lock mechanism.	\$ 80.00	\$ 60.00 30
5	To apply anti rust proofing to front affected area.	\$ 120.00	\$ 100.00 80
6	To remove and install front cooling system to facilitate the repair.	\$ 140.00	\$ 120.00 80
7	To remove and install front air con system to facilitate the repair.	\$ 140.00	\$ 120.00 100
8	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,800.00	\$ 1,600.00 1400
9	To putty and spray painting rear portion.	\$ 1,800.00	\$ 1,600.00 1200
10	To check rear lighting and wiring.	\$ 50.00	\$ 30.00
11	To remove and install rear tailgate lock mechanism.	\$ 80.00	\$ 60.00
12	To remove and install rear exhaust muffler and centre pipe.	\$ 140.00	\$ 120.00 80
13	To remove and install rear inner trim and garnish to facilitate the repair.	\$ 140.00	\$ 120.00 80
14	To apply anti rust proofing to rear affected area.	\$ 140.00	\$ 120.00 90
15	To remove and install rear bumper reverse sensor.	\$ 80.00	\$ 60.00 30
16	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	\$ 120.00 ✓
17	To repair, straighten and align rear left fender assy.	\$ 180.00	\$ 150.00 } X
18	To repair, straighten and align both rear door assy.	\$ 350.00	\$ 300.00 } X
19	Towing service.	\$ 100.00	\$ 80.00 ✓
20	To remove and install rear speaker board to facilitate the repair.	\$ 180.00	\$ 150.00 X
21	To remove and install rear speaker amplifier and sub woofer.	\$ 180.00	\$ 150.00 60
22	To remove and install rear view camera.	\$ 80.00	\$ 60.00 30
Total labour :		\$ 8,770.00	\$ 7,550.00 6330

35 997.60
4328.200

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 39,375.20	\$ 38,524.00
Total labour :	\$ 8,770.00	\$ 7,550.00
Total repair cost :	\$ 48,145.20	\$ 46,074.00

Adjusted Repair Cost (Lump Sum Repair)

\$ 36,900.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO17021630/T1tbs2-1	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 20-06-2018	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBB 7553R	Veh. Inspected	SCU 9881T
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704024/THE	Excess (\$)	0.00
Assign From	THELMA CHOO	Assign Date	25/04/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	RU11019363	Colour	BLUE
Odometer	062985	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45R18	YOKOHAMA	6 mm
L/H Front Tyre	225/45R18	YOKOHAMA	6 mm
R/H Rear Tyre	225/45R18	YOKOHAMA	6 mm
L/H Rear Tyre	225/45R18	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/11/2017	Inspection Date	14/11/2017
Survey held at	BLK 1002 BUKIT MERAH LANE 3 #01-83		
Repairer	SOON BODYWERKZ		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCU 9881T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FROTN BUMPER ASSY	DENTED / CRACKED	1,290.00	900.00
2	FRONT BUMPER BRACKET	NO SUCH PARTS	186.00	-
2	FRONT BUMPER RETAINER	BENT / NECESSARY	188.00	120.00
1	FRONT BUMPER REINFORCEMENT	DEFORMED	352.00	352.00
1	FRONT BUMPER LOWER GRILLE	BENT	194.00	194.00
1	FRONT BUMPER TOW COVER	WARPED / NECESSARY	88.00	88.00
1	FRONT GRILLE COMPLETE ASSY	CRACKED	482.00	482.00
1	FRONT GRILLE EMBLEM	NECESSARY	105.00	105.00
1	FRONT LEFT FOG LAMP	BENT / DISLODGE	280.00	280.00
1	FRONT RIGHT FOG LAMP	BENT / DISLODGE	280.00	280.00
1	FRONT LEFT FOG LAMP GARNISH	BENT	121.00	121.00
1	FRONT RIGHT FOG LAMP GARNISH	BENT	121.00	121.00
1	FRONT LEFT HID HEADLAMP	CRACKED	1,678.00	1,450.00
1	FRONT RIGHT HID HEADLAMP	CRACKED	1,678.00	1,450.00
1	FRONT BONNET ASSY	DENTED	1,681.00	1,130.00
1	FRONT BONNET LOCK	BENT	186.00	186.00
1	FRONT BONNET LOCK BRACKET	BENT	76.00	76.00
2	FRONT BONNET HINGES	NOT NECESSARY	188.00	-
1	FRONT BONNET LOCK COVER	BENT	75.00	75.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	1,064.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	BENT / WARPED	205.00	205.00
2	FRONT SUPPORT PANEL SIDE GARNISH	WARPED / CRACKED	160.00	160.00
1	FRONT LEFT AIR DUCT	BENT	178.00	178.00
1	FRONT RADIATOR ASSY	BENT	1,670.00	1,100.50
1	FRONT RADIATOR FAN COWLING ASSY	NOT NECESSARY	378.00	-
1	FRONT AIR CON CONDENSER ASSY	BENT	1,120.00	900.00
1	FRONT AMBIENT SENSOR	MALFUNCTION	298.00	298.00
1	FRONT AIR CON CONDENSER FAN COWLING ASSY	BENT	376.00	376.00
1	FRONT RADIATOR FAN MOTOR ASSY	NOT NECESSARY	310.00	-
1	FRONT AIR CON FAN MOTOR ASSY	NOT NECESSARY	310.00	-

Report Ref No. CS3/SMO17021630/T1tbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER ASSY	DEFORMED	1,098.00	880.00
1	REAR BUMPER LEFT RETAINER	BENT / NECESSARY	83.00	83.00
1	REAR BUMPER RIGHT RETAINER	BENT / NECESSARY	83.00	83.00
1	REAR BUMPER LEFT REFLECTOR	BENT / WARPED	93.00	93.00
1	REAR BUMPER RIGHT REFLECTOR	BENT / WARPED	93.00	93.00
1	REAR BUMPER LEFT SIDE LOWER PANEL	DENTED	687.00	687.00
1	REAR BUMPER RIGHT SIDE LOWER PANEL	DENTED	687.00	687.00
2	REAR BUMPER REFLECTOR	BENT / NECESSARY	190.00	190.00
2	REAR BUMPER MUD FLAP	BENT	180.00	180.00
1	REAR LEFT SIDE BUMPER	WARPED / BENT	355.00	195.00
1	REAR RIGHT SIDE BUMPER	WARPED / BENT	355.00	195.00
1	REAR TAILGATE ASSY	DEFORMED	1,887.00	1,200.00
1	REAR TAILGATE OUTER HANDLE	DEFORMED	98.00	98.00
1	REAR TAILGATE LOCK	BENT	175.00	175.00
1	REAR TAILGATE INNER TRIM BOARD	WARPED / NECESSARY	476.00	295.00
1	REAR TAILGATE WEATHERSTRIP	WARPED / NECESSARY	188.00	188.00
2	REAR TAILGATE DAMPER	NOT NECESSARY	296.00	-
1	REAR TAILGATE CENTRE LOGO	NECESSARY	105.00	105.00
1	REAR LEFT TAILGATE TAILLAMP	CRACKED	342.00	342.00
1	REAR RIGHT TAILGATE TAILLAMP	CRACKED	342.00	342.00
1	REAR TAILGATE OUTER GARNISH	WARPED / BENT	378.00	378.00
1	REAR LEFT TAILLAMP	CRACKED	866.00	660.00
1	REAR RIGHT TAILLAMP	CRACKED	866.00	660.00
1	REAR LEFT FENDER INNER GARNISH	WARPED / BENT	475.00	475.00
1	REAR RIGHT FENDER INNER GARNISH	WARPED / BENT	475.00	475.00
1	REAR LEFT FENDER PROTECTOR	BENT / WARPED	197.00	197.00
1	REAR RIGHT FENDER PROTECTOR	BENT / WARPED	197.00	197.00
1	REAR FLOOR PANEL	DEFORMED	1,670.00	1,230.00
1	REAR WIPER MOTOR	NOT NECESSARY	298.00	-
1	REAR SPARE TYRE TOP COVER	BENT	278.00	278.00
1	REAR LOWER DUCT COVER	WARPED / BENT	380.00	380.00
1	REAR WINDSCREEN GLASS ASSY	SHATTERED	1,880.00	1,472.00
1	REAR WINDSCREEN GLASS MOULDING	NOT NECESSARY	188.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN GLASS INNER SIDE GARNISH	NOT NECESSARY	280.00	-
1	REAR WINDSCREEN GLASS CENTRE GARNISH	NOT NECESSARY	165.00	-
1	REAR END LOWER PANEL	DEFORMED	976.00	976.00
1	REAR END LOWER PANEL TOP GARNISH	WARPED / CUT / BENT	185.00	185.00
1	REAR EXHAUST MUFFLER ASSY	BENT / CUT	1,297.00	925.00
4	REAR EXHAUST MUFFLER RUBBER MOUNTING	NECESSARY	66.00	66.00
1	REAR EXHAUST CENTRE PIPE	WARPED / BENT	1,679.00	1,250.00
1	REAR EXHAUST TAIL END PIPE	NECESSARY / BENT	180.00	180.00
1	REAR WIPER BLADE ASSY	NOT NECESSARY	166.00	-
1	REAR RIGHT FENDER ASSY	BUCKLED	2,167.00	1,250.00
1	REAR LOWER CENTRE COVER	WARPED / BENT	350.00	250.00
1	REAR EXHAUST MUFFLER HEAT SHIELD	WARPED / BENT	179.00	179.00
	LESS 20% DISCOUNT		-7,793.80	-5,680.30
			31,175.20	22,721.20
<u>SPECIAL NETT ITEMS</u>				
10	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
6	FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT NO PLATE WITH GARNISH (SN)	NECESSARY	120.00	60.00
6	FRONT GRILLE CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT BUMPER LOWER SPOILER (SN)	BENT / WARPED	1,250.00	600.00
10	FRONT BUMPER LOWER SPOILER CLIPS (SN)	NECESSARY	40.00	40.00
1	FRONT BUMPER LOWER SPOILER SEALANT (SN)	NECESSARY	80.00	50.00
1	FRONT LEFT LED LAMP (SN)	NOT NECESSARY	350.00	-
1	FRONT RIGHT LED LAMP (SN)	NOT NECESSARY	350.00	-
10	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER LOWER SPOILER ASSY (SN)	BENT / WARPED	1,250.00	600.00
10	REAR BUMPER LOWER SPOILER CLIPS (SN)	NECESSARY	40.00	40.00
1	REAR BUMPER LOWER SPOILER SEALANT (SN)	NECESSARY	80.00	50.00
16	REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	30.00	30.00
6	REAR END LOWER PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR WINDSCREEN GLASS CENTRE GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	80.00	50.00
1	SET REAR WINDSCREEN GLASS INNER SIDE GARNISH CLIPS (SN)	NECESSARY	30.00	30.00

Report Ref No. CS3/SMO17021630/T1tbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
8	REAR LOWER DUCT COVER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR RIGHT FENDER SEALANT (SN)	NOT NECESSARY	80.00	-
8	REAR LEFT FENDER INNER GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
8	REAR RIGHT FENDER INNER GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
6	REAR LEFT FENDER PROTECTOR CLIPS (SN)	NECESSARY	20.00	20.00
6	REAR RIGHT FENDER PROTECTOR CLIPS (SN)	NECESSARY	20.00	20.00
6	REAR TAILGATE OUTER GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR VIEW CAMERA (SN)	MALFUNCTION	300.00	200.00
4	REAR BUMPER REVERSE SENSOR (SN)	MALFUNCTION	500.00	250.00
1	REAR NO PLATE WITH GARNISH (SN)	NECESSARY	120.00	60.00
1	REAR SUB WOOFER ASSY (SN)	NOT NECESSARY	750.00	-
1	REAR SUB WOOFER AMPLIFER (SN)	NOT NECESSARY	650.00	-
1	SET FRONT SPEAKER AMPLIFER (SN)	NOT NECESSARY	850.00	-
1	SET REAR SPEAKER AMPLIFER (SN)	NOT NECESSARY	850.00	-
8	REAR LOWER CENTRE COVER CLIPS (SN)	NECESSARY	30.00	30.00
			8,200.00	2,460.00
LABOUR				
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.			1,400.00	700.00
TO PUTTY AND SPRAY PAINTING FRONT PORTION.			1,400.00	1,000.00
TO CHECK WIRING AND FOCUS FRONT HEADLAMP.			50.00	30.00
TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM.			80.00	30.00
TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA.			120.00	80.00
TO REMOVE AND INSTALL FRONT COOLING SYSTEM TO FACILITATE THE REPAIR.			140.00	80.00
TO REMOVE AND INSTALL FRONT AIR CON SYSTEM TO FACILITATE THE REPAIR.			140.00	100.00
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS.			1,800.00	1,400.00
TO PUTTY AND SPRAY PAINTING REAR PORTION.			1,800.00	1,200.00
TO CHECK REAR LIGHTING AND WIRING.			50.00	30.00
TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM.			80.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER AND CENTRE PIPE.		140.00	80.00
	TO REMOVE AND INSTALL REAR INNER TRIM AND GARNISH TO FACILITATE THE REPAIR.		140.00	80.00
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.		140.00	90.00
	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR.		80.00	30.00
	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR.		140.00	120.00
	TO REPAIR, STRAIGHTEN AND ALIGN REAR LEFT FENDER ASSY.	NOT NECESSARY	180.00	-
	TO REPAIR, STRAIGHTENING AND ALIGN BOTH REAR DOOR ASSY.	NOT NECESSARY	350.00	-
	TOWING SERVICE.		100.00	80.00
	TO REMOVE AND INSTALL REAR SPEAKER BOARD TO FACILITATE THE REPAIR.	NOT NECESSARY	180.00	-
	TO REMOVE AND INSTALL REAR SPEAKER AMPLIFIER AND SUB WOOFER.		180.00	60.00
	TO REMOVE AND INSTALL REAR VIEW CAMERA.		80.00	30.00
			8,770.00	5,280.00
GRAND TOTAL			48,145.20	30,461.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				24,350.00

Report Ref No. CS3/SMO17021630/T1tbs2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.