



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MS TING SHEAU MING BLK 691B CHOA CHU KANG CRESCENT #07-60 SINGAPORE 682691 Contact No Mobile: 90291389	Cust No/Name	/MS TING SHEAU MING
	Reg No/Reg Date	SLH8161G / 21/11/2016
	Date In/Mileage	/ 0
	Chassis No	JMYXTGF3WGZ004222
	Engine No	4B12RR3685
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (G43)
	Colour/Trim	A03 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	24/04/2018/ 12:24		265 / AndreChow	24769			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								✓ 80.00
SUPPLY REAR WINDSCREEN SEALANT								✓ 240.00
M SUNDRY								✓ 240.00
SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS								bt ✓ 120.00
M SUNDRY								✓ 160.00
SUPPLY FRONT AND REAR NUMBER PLATE WITH FRAME								✓ 240.00
M SUNDRY								✓ 240.00
SUPPLY BODY SEALANT								275 550.00
E PNT88000								275 550.00
REMOVE AND INSTALL REAR WINDSCREEN GLASS								275 550.00
E PNT88000								275 550.00
REMOVE AND INSTALL REAR TAILGATE TRIM, MECHANISM AND ELECTRONICS TO FACILITATE REPAIRS								80 150.00
E PNT88000								60 100.00
REMOVE AND INSTALL REAR COMPARTMENT TRIM, SPARE TYRE TO FACILITATE REPAIRS								✓ 200.00
E PNT88000								X 550.00
REMOVE AND INSTALL REAR PARKING SENSORS								hw ✓ 220.00
A 54900099								2475 4950.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								550
A 10028901								420
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								2100 2940.00
A 54900099								
RENEW REAR EXHAUST								
M SUNDRY								
SUPPLY REVERSE SENSORS TO FACILITATE REPAIRS								
E PNT88000								
RENEW ACCIDENT DAMAGED PORTION ON FRONT BUMPER, FRONT BUMPER REINFORCEMENT, REAR BUMPER, REAR TAILGATE, REAR END PANEL, REPAIR REAR FLOOR PANEL, LH REAR FENDER AND REALIGN TO THE SAME								
E PNT98000								
RESPRAY FRONT BUMPER, REAR BUMPER, REAR TAILGATE, REAR END PANEL, REAR								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MS TING SHEAU MING BLK 691B CHOA CHU KANG CRESCENT #07-60 SINGAPORE 682691 Contact No Mobile: 90291389	Cust No/Name	/MS TING SHEAU MING
	Reg No/Reg Date	SLH8161G / 21/11/201
	Date In/Mileage	/ 0
	Chassis No	JMYXTGF3WGZ004222
	Engine No	4B12RR3685
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (G43)
	Colour/Trim	A03 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	24/04/2018/ 12:24		265 / AndreChow	24769			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
FLOOR PANEL, LH REAR FENDER AND OTHER AFFECTED PORTIONS								new 40.00
M	SUNDRY							30 60.00
	SUNDRY							de 873.00
	SUNDRY							bt 78.00
M	FACE,RR BUMPER			1.00	873.00	00.00		? 78.00
M	REINFORCEMENT,RR BUMPER,LH			1.00	78.00	00.00		new 12.00
M	REINFORCEMENT,RR BUMPER,RH			1.00	78.00	00.00		new 12.00
M	BRKT,R/BMPR FACE SIDE,RH			1.00	12.00	00.00		new 20.00
M	BRKT,R/BMPR FACE SIDE,LH			1.00	12.00	00.00		de 230.00
M	CLIP,FR BUMPER			10.00	2.00	00.00		? 105.00
M	EXTENSION,RR BUMPER			1.00	230.00	00.00		de 105.00
M	MOULDING,RR BUMPER,RH			1.00	105.00	00.00		cut 211.00
M	MOULDING,RR BUMPER,LH			1.00	105.00	00.00		i x 196.00
M	W/STRIP,TAILGATE OPENING			1.00	211.00	00.00		x 196.00
I	GAS SPRING,TAILGATE,LH			1.00	196.00	00.00		de 489.00
M	GAS SPRING,TAILGATE,RH			1.00	196.00	00.00		bt 924.00
M	GARNISH,TAILGATE			1.00	489.00	00.00		new 12.00
M	PANEL ASSY,TAILGATE			1.00	924.00	00.00		new 54.00
M	DAM,TAILGATE,UPR			1.00	12.00	00.00		new 41.00
P	DAM,TAILGATE SIDE			2.00	27.00	00.00		new 6.00
M	DAM,TAILGATE,LWR			1.00	41.00	00.00		bt 470.00
M	STOPPER,WINDSHIELD GLASS			2.00	3.00	00.00		new 71.00
M	LATCH,TAILGATE			1.00	470.00	00.00		new 12.00
M	SWITCH,POWER T/GATE CLOSE			1.00	71.00	00.00		bt 243.00
M	FASTENER,WINDSHIELD			2.00	6.00	00.00		? 110.00
M	PANEL,RR END			1.00	243.00	00.00		new 218.00
M	GARNISH,FR BUMPER SIDE			1.00	110.00	00.00		? 48.00
M	GARNISH,FR BUMPER SIDE			1.00	218.00	00.00		de 421.00
M	GARNISH,FR BUMPER SIDE			1.00	48.00	00.00		? 18.00
M	EXTENSION,FR BUMPER			1.00	421.00	00.00		? 2.00
M	CLIP,INST PANEL CONSOLE			6.00	3.00	00.00		
M	CLIP,ENG ROOM COVER			1.00	2.00	00.00		

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for MS TING SHEAU MING and vehicle specifications like SLH8161G, JMYXTGF3WGZ004222.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Values include CSM00041, Cash, 24/04/2018/ 12:24, 265 / AndreChow, 24769.

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts like GARNISH, FR BUMPER, LAMP ASSY, etc.

Estimate

SURVEYOR NAME: Taufik 97495749
SURVEYOR SIGNATURE: [Signature]
DATE: 7/5/18 @ 1130
REMARKS: Resurvey before paint sw @ 11kauto.com. 9 days.

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Summary table: Net 24,838.00, 7% GST on 24838.00 (1738.66), Total Payable 26,576.66.

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.