

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC18007661/K1vbn2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	07-05-2018 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	XD 2498D	Veh. Ir	nspected	SH 6778H	
	Policy No.	5080290852-01	Coverage (\$)		0.00	
	Claim No.	MT/0991820-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	25/04/2018	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI SONATA	c.c		1991	
	Engine No.	HIDDEN	Year o	f Reg.	2012	
	Chassis No.	KMHET41VMCA821772	Colou	r	BLUE	
	Odometer	527633	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	MAXXI	5	7 mm	
	L/H Front Tyre	215/60 R16	MAXXI		7 mm	
	R/H Rear Tyre	215/60 R16	MAXXI		7 mm	
	L/H Rear Tyre	215/60 R16	MAXXI		7 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	24/04/2018	Inspec	tion Date	25/04/2018	
	Survey held at	d at COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					