

ASS. REC. BY:

REF: CS3 / CTU 8007689 / mlz462

Special Instruction:

Survivor: Ma

ASSIGNMENT (Office)

From (Person): Adeline Chng

of CTU

Date/Time: 25042018 5:08pm

Estimated Cost:

Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJN 6781Y

Insured: GDD 8979D

at Workshop m/s Hong Motor

Tel: 6282 2052

of Bik 5035 AMK Ind Park 2 #01-365

Policy No: DMCVSN152781170

Claim No: SNM18D02699C02

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 23042018

CA / REV / REP. / REV 24 HRS 1wp

26042018 @ after 4pm

Date/Time: 25042018 5:28pm

Person Contacted: An Huat

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SJN 6781Y - X</u>
	<u>GDD 8979D - X</u>

Surveyor

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJN 67814 Yr Regn: _____ /
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai Avante c.c _____
 Colour: Beige A/C: Insured / Std / NI / NA
 Sp. Reading: 216479 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KM1DU41BR9U689066
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 185/65/R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or 21EX
 Front R/Bal. 2 mm Rear R/Bal. 2 mm
 L/Bal. 2 mm L/Bal. 2 mm
 D.O.A. _____ D.O.I. 26/4/2018
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
as above
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	No Document upon Survey.
	* Repair Estimate : S\$ 7000 - 8000
	* 4 days
7/5/18	Submit PRS Report.

RECEIVED 08 MAY 2018

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: _____

1) Date/Time, File Return to? _____

Resurvey No. of Trip: _____

2) _____

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee:	150
Transportation:	
\$ + RS, SI	
Photos	
Others	
TOTAL	150

Report Format :

Lump Sum / I.B.I: (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Apr 2018		25 Apr 2018 17:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	M/S KIM TIONG ENTERPRISES PTE LTD , Co. Reg. No.: 198301901G								
Main Claimant:	CHONG MOK KIM @ CHONG YEE YUEN , ID: S15441731								
Vehicle Reg. No.:	SJN6781Y	Date of Loss:	23/04/2018 14:00 - :59						
Claim Type:	TP / SNM18D02099C02	Policy/Cover Note No.:	DMCVSN1527811702 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBD8979D	Policy No. (Claimant):	5057948978-05						
		Excess:	S\$0.00						
Repairer:	Hong Motor Service (HQ) Blk 5035 Ang Mo Kio Industrial Park 2, (off Ave 3) #01-365 Singapore 569538, 569538 Ang Mo Kio - Tel: 62822052								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/05/2018]								
Driver/Custodian (Insured):	WANG JUNYING (31 / Male), NRIC: G2666036Q, Tel: +6597284096								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Apr 2018		25 Apr 2018 17:08 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	M/S KIM TIONG ENTERPRISES PTE LTD, Co. Reg. No.: 198301901G								
Main Claimant:	CHONG MOK KIM @ CHONG YEE YUEN, ID: S15441731								
Vehicle Reg. No.:	SJN6781Y	Date of Loss: 23/04/2018 14:00 - :59 [109 Months and 29 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / SNM18D02099C02	Policy/Cover Note No.: DMCVSN1527811702 (Comprehensive)							
Vehicle Reg. No. (Insured):	GBD8979D	Policy No. (Claimant): 5057948978-05							
		Excess: S\$0.00							
Repairer:	Hong Motor Service (HQ) Blk 5035 Ang Mo Kio Industrial Park 2, (off Ave 3) #01-365 Singapore 569538, 569538 Ang Mo Kio - Tel: 62822052								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 07/05/2018]								
Driver/Custodian (Insured):	WANG JUNYING (31 / Male), NRIC: G2666036Q, Tel: +6597284096								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJN6781Y (SNM18D02099C02)
 [GBD8979D]
 TP
CHONG MOK KIM @ CHONG YEE YUEN
 Apr 23 2018 2:00PM
[M/S KIM TIONG ENTERPRISES PTE LTD]
 Hong Motor Service

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>		
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)			Thumbnail	Print		
1	24/04/18 17:40	Accident Statement		1	Load HTM			
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)			Thumbnail	Print		
1	24/04/18 17:40	Accident Photo [Linked Accident Report Documents]		1	Load JPG	<input checked="" type="checkbox"/>		
2	24/04/18 17:40	Accident Photo [Linked Accident Report Documents]		1	Load JPG	<input checked="" type="checkbox"/>		
3	24/04/18 17:40	Accident Photo [Linked Accident Report Documents]		1	Load JPG	<input checked="" type="checkbox"/>		
4	24/04/18 17:40	Accident Photo [Linked Accident Report Documents]		1	Load JPG	<input checked="" type="checkbox"/>		
5	24/04/18 17:40	Accident Photo [Linked Accident Report Documents]		1	Load JPG	<input checked="" type="checkbox"/>		
6	24/04/18 17:40	Accident Photo [Linked Accident Report Documents]		1	Load JPG	<input checked="" type="checkbox"/>		
7	24/04/18 17:40	Accident Photo [Linked Accident Report Documents]		1	Load JPG	<input checked="" type="checkbox"/>		
8	24/04/18 17:40	Accident Photo [Linked Accident Report Documents]		1	Load JPG	<input checked="" type="checkbox"/>		
9	24/04/18 17:40	Accident Photo [Linked Accident Report Documents]		1	Load JPG	<input checked="" type="checkbox"/>		
10	24/04/18 17:40	Accident Photo [Linked Accident Report Documents]		1	Load JPG	<input checked="" type="checkbox"/>		
11	24/04/18 17:40	Accident Photo [Linked Accident Report Documents]		1	Load JPG	<input checked="" type="checkbox"/>		
12	24/04/18 17:40	Accident Photo [Linked Accident Report Documents]		1	Load JPG	<input checked="" type="checkbox"/>		
Documentation							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print		
1	25/04/18 17:07	PRS		1	Load PDF			
2	25/04/18 17:07	OI GIA REPORT		1	Load PDF			
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)			Thumbnail	Print		
1	24/04/18 17:40	Sketch Plan [Linked Accident Report Documents]		1	Load TIF			
2	24/04/18 17:40	Sketch Plan #2 [Linked Accident Report Documents]		1	Load TIF			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print		
1	07/05/18 09:47	LKKPhotosIn6-1		1	Load PDF			

Linked Accident Report Documents

						View <input type="button" value="View in Browser"/>		
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)			Thumbnail	Print		
1	24/04/18 17:40	Accident Statement		1	Load HTM			
Photos/Images								

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	24/04/18 17:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	24/04/18 17:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	24/04/18 17:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	24/04/18 17:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	24/04/18 17:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	24/04/18 17:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	24/04/18 17:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	24/04/18 17:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	24/04/18 17:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	24/04/18 17:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	24/04/18 17:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	24/04/18 17:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	24/04/18 17:40	Sketch Plan	Load TIF	
2	24/04/18 17:40	Sketch Plan #2	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118007689/M1Z4BE2
Date: 08/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN1527811702	
Claimant Vehicle No: SJN6781Y	Insured Vehicle No: GBD8979D	
Date of Loss: 23/04/2018	Nature of Claim: TP	Claim No: SNM18D02099C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJN6781Y	Engine No: G4FC9U603301
Make & Model: HYUNDAI AVANTE, 1.6 (A)	Chassis No: KMH DU41BR9U689066
Reg. Date: 25/02/2009 (Man. Year: 2009)	Odometer: 216479 km
Colour: Beige	
Engine Capacity: 1591 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	ZIEX 8 mm	Rear Left Side:	ZIEX 8 mm
Front Right Side:	ZIEX 8 mm	Rear Right Side:	ZIEX 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	25/04/2018	
Date Inspected:	26/04/2018 Inspected At:	Hong Motor Service (HQ) Blk 5035 Ang Mo Kio Industrial Park 2, (off Ave 3) #01-365 Singapore 569538

Estimated Period of Repair: 4.0 days

Adjuster: MA CHIN FOOK

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2018)
Parts: 143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN6781Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >