

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Apr 2018)

Parts: M1-MPV TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ETHOZ Protect Pte Ltd/SGQ4288M/26/04/2018 12:12

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	PA *240.00 F
2	1		*FRONT BONNET HINGE LH	0.00	0.00	X *30.00 F
3	1		*FRONT BONNET HINGE RH	0.00	0.00	X *30.00 F
4	1		*FRONT BONNET LOCK	0.00	0.00	PA *45.00 F
5	1		*FRONT BONNET LOGO	0.00	0.00	PA *30.00 F
6	1		*FRONT FENDER LH	0.00	0.00	-
			REPAIR			
7	1		*FRONT FENDER RH	0.00	0.00	-
			REPAIR			
8	1		*HEADLAMP LH	0.00	0.00	? *280.00 F
9	1		*HEADLAMP RH	0.00	0.00	PA *280.00 F
10	1		*FRONT GRILLE	0.00	0.00	? *70.00 F
11	10		*FRONT GRILLE CLIP	0.00	0.00	PA *15.00 F
12	1		*FRONT BUMPER	0.00	0.00	PA *280.00 F
13	10		*FRONT BUMPER CLIP	0.00	0.00	PA *15.00 F
14	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	PA *35.00 F
15	1		*FRONT BUMPER SIDE RETAINER RH	0.00	0.00	PA *35.00 F
16	1		*FRONT BUMPER LOWER GRILLE LH	0.00	0.00	? *35.00 F
17	1		*FRONT BUMPER LOWER GRILLE RH	0.00	0.00	? *35.00 F
18	1		*FOG LAMP COVER LH	0.00	0.00	X *38.00 F
19	1		*FOG LAMP COVER RH	0.00	0.00	X *38.00 F
20	1		*FOG LAMP LH	0.00	0.00	X *95.00 F
21	1		*FOG LAMP RH	0.00	0.00	X *95.00 F
22	1		*FRONT BUMPER FOAM	0.00	0.00	? *45.00 F
23	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	? *95.00 F
24	1		*BRACE PANEL	0.00	0.00	? *50.00 F
25	1		*SUPPORT PANEL	0.00	0.00	? *500.00 F
26	1		*SUPPORT PANEL TOP GARNISH	0.00	0.00	X *40.00 F
27	10		*SUPPORT PANEL TOP GARNISH CLIP	0.00	0.00	X *20.00 F
28	1		*CONDENSER SIDE COVER LH	0.00	0.00	? *35.00 F
29	1		*CONDENSER SIDE COVER RH	0.00	0.00	? *35.00 F
30	1		*CONDENSER	0.00	0.00	? *180.00 F
31	1		*RADIATOR	0.00	0.00	? *550.00 F
32	1		*RADIATOR TOP GARNISH	0.00	0.00	? *48.00 F
33	1		*RADIATOR FAN COWLING	0.00	0.00	? *90.00 F
34	1		*RADIATOR FAN BLADE	0.00	0.00	? *80.00 F
35	1		*RADIATOR FAN MOTOR	0.00	0.00	? *150.00 F

F=Franchise part.

Total Parts (S\$)

3,639.00

ETHOZ Protect Pte Ltd/SGQ4288M/26/04/2018 12:12. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT NUMBER PLATE	35.00
2	1	RADIATOR COOLANT	30.00
Sub Total (S\$)			65.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR TO CARRY OUT FRONT REPAIR	New	700.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	35.00
3	TO SPRAY PAINTING ON FRONT AFFECTED AREA	New	600.00
4	TO REMOVE & FIX AIR COND CONDENSER INCLUDING TOP UP AIR COND GAS	New	150.00
Gross Labour Cost (S\$)			1,585.00

ETHOZ Protect Pte Ltd/SGQ4288M/26/04/2018 12:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

Company Registration No. 199005791M

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>

Rasul
 HP 90010068
 5 days - P/P
 27/04/18 @ 1630
 excess: 600
 Revert
 Resurvey by paint

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date: