

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG18007709/AUA3S2**Date:** 31/10/2018REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100186682
Claimant Vehicle No :	SJL422J	Insured Vehicle No :	SJV2070A
Date of Loss:	22/04/2018	Nature of Claim:	TP
		Claim No:	1972223361SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL422J	Engine No:	G4FC8U533577
Make & Model:	HYUNDAI AVANTE, 1.6 HD (A)	Chassis No:	KMH DU41BR8U611615
Reg. Date:	13/11/2008 (Man. Year: 2008)	Odometer:	437746 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,284.76	3,737.84	6,546.92	63.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,620.00	1,690.00	1,930.00	53.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,904.76	5,427.84	8,476.92	60.96
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	13,904.76	4,300.00	9,604.76	69.08
+ GST 7.00/7.00% (S\$)	973.33	301.00	672.33	69.08
Nett Amount (S\$)	14,878.09	4,601.00	10,277.09	69.08
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,088.45		

INSPECTION

Date of Assignment:	25/04/2018	MG Solution Pte Ltd (HQ)
Date Inspected:	25/04/2018 Inspected At:	23 Kaki Bukit Avenue 4 #02-03B, VICOM
		Inspection Centre
		Singapore 415933
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	985.90 FL	*985.90 FL
2	1		*BOOTLID LOGO	Necessary	67.50 FL	*67.50 FL
3	1		*BOOTLID EMBLEM AVANTE	Necessary	58.50 FL	*58.50 FL
4	1		*BOOTLID EMBLEM S	Necessary	58.50 FL	*58.50 FL
5	1		*BOOTLID KEY LOCK	Not Necessary	219.60 FL	*- FL
6	1		*BOOTLID TOP LOCK	Damaged	168.90 FL	*168.90 FL
7	1		*BOOTLID LOWER CATCH	Not Necessary	67.50 FL	*- FL
8	2		*BOOTLID HINGE	Not Necessary	241.60 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Cut	169.00 FL	*169.00 FL
10	2		*BOOTLID REFLECTOR	Not Necessary	509.00 FL	*- FL
11	1		*SET BOOTLID NUMBER PLATE LAMP	Not Necessary	68.90 FL	*- FL
12	1		*BOOTLID OUTER GARNISH	Not Necessary	217.40 FL	*- FL
13	1		*REAR BUMPER	Deformed	625.00 FL	*489.00 FL
14	2		*REAR BUMPER RETAINER	Necessary	105.20 FL	*72.00 FL
15	1		*REAR BUMPER REINFORCEMENT	Cracked	298.70 FL	*298.70 FL
16	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent	91.80 FL	*91.80 FL
17	1		*REAR BUMPER SPONGE	Cracked	168.50 FL	*168.50 FL
18	2		*TAILLAMP	Cracked	917.00 FL	*495.60 FL
19	2		*TAILLAMP PANEL	Repair	437.80 FL	*- FL
20	2		*REAR FENDER	Repair	2,040.00 FL	*- FL
21	2		*REAR FENDER INNER TRIM	Torn	857.40 FL	*466.00 FL
22	1		*REAR WINDSCREEN MOULDING	Not Necessary	183.90 FL	*- FL
23	1		*REAR END PANEL	Distorted	580.90 FL	*580.90 FL
24	1		*REAR END PANEL TOP GARNISH	Deformed	229.50 FL	*89.00 FL
25	1		*REAR FLOOR PANEL	Repair	786.50 FL	*- FL
26	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	341.50 FL	*- FL
27	1		*REAR TOOLS SPONGE	Not Necessary	229.50 FL	*- FL
28	1		*REAR SPARE TYRE BOLT	Not Necessary	67.50 FL	*- FL
29	1		*REAR EXHAUST PIPE	Not Necessary	779.20 FL	*- FL
30	2		*REAR EXHAUST MOUNTING	Not Necessary	90.00 FL	*- FL
31	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
32	1		*BOOT LID SEALANT	Not Necessary	60.00 FS	*- FS
33	1		*SET BOOTLID OUTER MOULDING CLIP	Not Necessary	20.00 FS	*- FS
34	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
35	1		*SET TAIL LAMP CLIP	Necessary	20.00 FS	*20.00 FS
36	2		*TAIL LAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
37	1		*REAR FENDER INNER TRIM CLIPS	Necessary	20.00 FS	*20.00 FS
38	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
39	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
40	1		*SET REAR END PANEL TOP GARNISH	Necessary	20.00 FS	*10.00 FS
41	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*60.00 FS
42	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
43	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,617.20	4,589.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,332.44	851.96
Total Parts (\$\$)	10,284.76	3,737.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS.	New	1,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREA.	New	1,400.00	800.00
3	TO APPLY RUST PROOFING AND TUFF COAT.	New	150.00	40.00
4	TRANSFER BOOTLID MECHANISM.	New	150.00	0.00
5	CONDUCT WATER LEAKAGE TEST.	New	150.00	0.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	New	150.00	50.00
7	REMOVE AND REFIX REAR EXHAUST PIPE.	New	220.00	0.00
Gross Labour Cost (\$\$)			3,620.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >