

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18007720/ASBS2**Date:** 04/12/2018REFERENCE

Insured/Claimant: PREMIUM AUTOMOBILES PTE LTD Policy No: 0999994629
Date of Loss: 25/04/2018 Nature of Claim: OD Claim No: 1909359392SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ465Y**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN017657
Reg. Date: 25/11/2016 (Man. Year: 2016) Chassis No: WAUZZZF43HA024629
Colour: Silver Odometer: 20148 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$135,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 23,553.20 | 17,257.64 | 6,295.56 | 26.73 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 7,252.00 | 4,152.00 | 3,100.00 | 42.75 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 30,805.20 | 21,409.64 | 9,395.56 | 30.50 |
| - Excess (S\$) | 3,000.00 | 3,000.00 | 0.00 | 0.00 |
| (S\$) | 27,805.20 | 18,409.64 | 9,395.56 | 33.79 |
| + GST 7.00/7.00% (S\$) | 1,946.36 | 1,288.67 | 657.69 | 33.79 |
| Nett Amount (S\$) | 29,751.56 | 19,698.31 | 10,053.25 | 33.79 |

INSPECTION

Date of Assignment: 26/04/2018
Date Inspected: 26/04/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|---------------------------|--------------|---------------|
| 1 | 1 | | *FRONT BUMPER | Deformed | 1,849.00 FS | *1,479.20 FS |
| 2 | 2 | | *FRONT BUMPER SECURING STRIP | Damaged | 60.00 FS | *47.84 FS |
| 3 | 1 | | *FRONT BUMPER GRILLE - CENTRE | Not Necessary | 171.00 FS | *- FS |
| 4 | 1 | | *RADIATOR GRILLE | Cracked | 972.00 FS | *777.20 FS |
| 5 | 1 | | *FOAM FILLER PIECE | Cracked | 107.00 FS | *85.20 FS |
| 6 | 2 | | *FRONT BUMPER SUPPORT - LH/RH | Damaged | 48.00 FS | *38.24 FS |
| 7 | 1 | | *FRONT BUMPER LOCK CARRIER BRACKET | Cracked | 118.00 FS | *94.00 FS |
| 8 | 1 | | *FRONT BUMPER COVER | Deformed | 109.00 FS | *87.20 FS |
| 9 | 1 | | *RELEASE LEVER | Not Necessary | 12.00 FS | *- FS |
| 10 | 1 | | *BOWDEN CABLE | Damaged | 50.00 FS | *40.00 FS |
| 11 | 1 | | *SIGN CAUTION | Necessary | 12.00 FS | *9.28 FS |
| 12 | 2 | | *LED HEADLIGHT - LH/RH | O/s Chipped / N/s Cracked | 13,946.00 FS | *11,156.80 FS |
| 13 | 1 | | *BONNET | Distorted | 2,163.00 FS | *1,730.40 FS |
| 14 | 1 | | *BONNET ATTACHMENT PARTS | Not Necessary | 105.00 FS | *- FS |
| 15 | 1 | | *IMPACT PROTECTION - LH | Necessary | 24.00 FS | *18.88 FS |
| 16 | 1 | | *IMPACT PROTECTION - RH | Necessary | 24.00 FS | *18.88 FS |
| 17 | 1 | | *IMPACT PROTECTION - CENTER | Necessary | 24.00 FS | *18.88 FS |
| 18 | 2 | | *BONNET STRIKER - LH/RH | Damaged | 88.00 FS | *69.92 FS |
| 19 | 2 | | *BONNET LID LOCK | Not Necessary | 376.00 FS | *- FS |
| 20 | 1 | | *BONNET LOCK CARRIER | Not Necessary | 891.00 FS | *- FS |
| 21 | 2 | | *AIR GUIDE - LH/RH | Not Necessary | 46.00 FS | *- FS |
| 22 | 2 | | *RADIATOR INNER DUCT - LH/RH | Deformed | 20.00 FS | *15.36 FS |
| 23 | 1 | | *AIR GUIDE - UPPER | Not Necessary | 14.00 FS | *- FS |
| 24 | 1 | | *A/C CONDENSER WITH FLUID RESERVOIR | Dented | 540.00 FS | *432.00 FS |
| 25 | 1 | | *COOLER FOR COOLANT | Dented | 585.00 FS | *468.00 FS |
| 26 | 4 | | *RUBBER BUSH - LOWER | Not Necessary | 38.00 FS | *- FS |
| 27 | 4 | | *COOLANT CONCENTRATE | Not Necessary | 133.00 FS | *- FS |
| 28 | 1 | | *FRONT NO. PLATE | Necessary | 25.00 FS | *25.00 FS |
| 29 | 1 | | *SUNDRIES | Necessary | 400.00 FS | *42.16 FS |
| 30 | 1 | | *FRONT REINFORCEMENT BEAM | Bent | 561.60 FS | *561.60 FS |
| 31 | 2 | | *BONNET STOP BUFFER | Necessary | 13.28 FS | *13.28 FS |
| 32 | 3 | | *BONNET BUNGS | Necessary | 28.32 FS | *28.32 FS |

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 23,553.20 17,257.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|-------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY. | New | 360.00 | 360.00 |
| 2 | TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURE COOLING SYSTEM. | New | 1,000.00 | 1,000.00 |
| 3 | TO DISMANTLE FRONT BUMPER, BOTH HEADLIGHTS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | New | 4,200.00 | 1,500.00 |
| 4 | TO RESPRAY FRONT BUMPER AND BONNET. | New | 1,500.00 | 1,100.00 |
| 5 | TO CARRY OUT DIAGNOSTIC CHECK. | New | 192.00 | 192.00 |
| | | | Gross Labour Cost (\$) | 7,252.00 |
| | | | | 4,152.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >