

ASS. REC. BY:

REF: CS/FCL18007771 /Kgbnz

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): AWB Luene Jaw of FCL Date/Time: 27/04/2018 9:30am

Estimated Cost: _____ Bill to: _____

OD / ~~W~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKH 266C Insured: SHC 740L

at Workshop m/s: Alan's United Tel: 6453 5686

of Blk 7 Sin Ming Ind Est #01-76

Policy No: _____ Claim No: D18003208MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 21/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS DS1 H.O.D. Endorsement: _____

Date/Time: 27/04/2018 10:28am Person Contacted: Kenny Vehicle IN / OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SKH 266C - x
	SHC 740L - CS/FCL18006713 /Krd3 D.O.A: 06/04/18
<u>03/5/18 @ 7:07pm</u>	<u>revised to Luene by email.</u>
<u>10/5</u>	<u>\$1390.45 Confirmed by email (ded \$626.00, 31%) no lump sum</u>

ASS. REC. BY:

REF: 1402 /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Alan's

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 8811c

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1-B,1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKH 266C Yr Regn: 09, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or MPV

Make: Toy Estima c.c. 2362

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 105938 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACR 50 . 0151441

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 2/14/18 D.O.I. 2/5/18

Survey held at _____

Des. of Damages: FR / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>3/5</u>	<u>File pass to Car horn</u>

[Signature]
16/2018

RECEIVED 8 JUN 2018

Date/Time, File Pass to?

: Prell. Report

: Final Report

Days Of Repair: 2

Resurvey No. of Trlp: 2

Survey Fee:

Transportation: _____

S + RS, SI _____

Photos _____

Others _____

TOTAL

110
50
50 + 50
18
278

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Date/Time, File Return to?

11/06/18

Date/Time, File Return to?

21

Report Format: TP

Lump Sum / I.B.I. (\$ 1390.45)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003208MFSH

Date: 03 May 2018

Our Ref: CS/FCI18007771/Kqb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKH 266C .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/05/2018 at the premises of M/s ALAN'S UNITED, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,016.67</u> .
Revised Estimate Amount	: S\$ <u>1,306.90</u> .
"Check" Items Amount	: S\$ <u>115.50</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the rear n/s portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	24-04-2018	Our Ref No. D18003208MFSH
Accident Date	21-04-2018	Claim Type. Third Party
Insured Vehicle	SHC0740L	Third Party Vehicle. SKH266C
Survey Location	BLK 7 SIN MING INDUSTRIAL ESTATE #01-76	
Contact Person.	KENNY	
Contact No.	64538686/ 64538686	Fax No. 00
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ALAN'S UNITED AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 3 May 2018 3:07 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18003208MFSH/1
Attachments: CSFC18007771Kqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SKH 266C.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 27 April 2018 10:30 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003208MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 27 April, 2018 9:23 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003208MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05769

Vehicle Insured : SHC740L
Accident Date : 21-Apr-2018

Date : 25-Apr-2018

Our Ref : 218075 (FIRST) / CHAN

PAGE : 1

YIONG YIM MING
BLK 3 ANTHONY ROAD
#03-03
Singapore 229953

*Not withair
Resurvey B4 paint
@ 1390.45 2 days*

ESTIMATED COST OF REPAIR FOR TOYOTA ESTIMA 2.4 SKH266C

1 pc Rear bumper fascia	<i>Bu/nd</i>	541.70	✓
1 pc Rear bumper n/s sponge	<i>cm</i>	65.70	✓
1 pc Rear bumper n/s reflector	<i>cm</i>	52.30	✓
1 pc Rear bumper n/s retainer (L)	<i>sn</i>	51.90	X
1 pc Rear bumper n/s retainer (S)	<i>sn</i>	36.40	X
1 pc Rear bumper n/s tow cover	<i>my</i>	45.70	X
4 pcs Rear bumper lower clip	<i>nu</i>	15.20	✓
	@ S\$	3.80	
		808.90	
	Less 25% :	202.23	
		606.67	
1 pc Rear bumper reverse sesnor(4pcs	<i>cm</i>	400.00	sn ✓
To apply undersealing	<i>nu</i>	60.00	X
To putty and spray replaced parts		450.00	250
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts		500.00	200
	Total :	S\$ 2,016.67	

Singapore Dollars Two Thousand and Sixteen and
Cents Sixty Seven Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007771/Kqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-06-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 740L	Veh. Inspected	SKH 266C
Policy No.		Coverage (\$)	0.00
Claim No.	D18003208MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	27/04/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ESTIMA (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	ACR500151441	Colour	METALLIC PEARL WHITE
Odometer	105938	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R19	BRIDGESTONE	6 mm
L/H Front Tyre	225/45 R19	BRIDGESTONE	6 mm
R/H Rear Tyre	225/45 R19	BRIDGESTONE	6 mm
L/H Rear Tyre	225/45 R19	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/04/2018	Inspection Date	02/05/2018
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 266C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER FASCIA	BUCKLED / DENTED	541.70	541.70
1	REAR BUMPER N/S SPONGE	CRACKED	65.70	65.70
1	REAR BUMPER N/S REFLECTOR	CRACKED	52.30	52.30
1	REAR BUMPER N/S RETAINER (L)	SERVICEABLE	51.90	-
1	REAR BUMPER N/S RETAINER (S)	SERVICEABLE	36.40	-
1	REAR BUMPER N/S TOW COVER	MTG DENTED	45.70	45.70
4	REAR BUMPER LOWER CLIP @\$3.80 LESS 25% DISCOUNT	NECESSARY	15.20 -202.23	15.20 -180.15
			606.67	540.45
SPECIAL NETT ITEMS				
1	REAR BUMPER REVERSE SENSOR (4 PCS)(SN)	CRACKED	400.00	400.00
			400.00	400.00
LABOUR				
TO APPLY UNDERSEALING.		NOT NECESSARY	60.00	-
TO PUTTY AND SPRAY REPLACED PARTS.			450.00	250.00
TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS.			500.00	200.00
			1,010.00	450.00
GRAND TOTAL			2,016.67	1,390.45
RECOMMENDED COST OF REPAIRS				1,390.45

Report Ref No. CS/FCI18007771/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.