


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG1042K
 Ref. No : BUS/04/18/7007
 Reg. Date : 01/01/1900
 Vehicle Type : BUS -12M
 Make : MB CITARO MERCEDES
 Model : MB CITARO O530
 Name of Driver : Ma Pengcheng
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 06/04/2018 12:25:00 PM
 Accident Reported Date / Time : 09/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : AIG
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 left front portion damaged
 TP: SLH457G (AIG)
 Prepared Date : 09/04/2018 12:01:28 PM



Sebastian
 25/4/18

- Part by part repair
 - Photo After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	795.00	0.00
Total Spray Painting Charges :	262.00	0.00
Total Material Charges :	139.77	139.77
Other Charges :	0.00	0.00
TOTAL :	1,196.77	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	2.00	0.00
Prepared / Adjusted By :		1 day
Arc / Surveyor Sign Off Date :	24/04/2018 06:30:03 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 24/04/2018 06:30:03 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	795.00	0.00 530
Total Labour	795.00	0.00


Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	262.00	0.00 200
Total Spray Painting & Panel Beating	262.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	VE	6009700	FRONT SIGNAL LAMP LH	1	155.30	10.00	139.77	Replace	Replace	No 
TOTAL MATERIALS							139.77	139.77		
TOTAL MATERIALS(Discounted)							139.77	139.77		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG1042K
Ref. No : BUS/04/18/7007
Reg. Date : 01/01/1900
Vehicle Type : BUS -12M
Make : MB CITARO MERCEDES
Model : MB CITARO O530
Name of Driver : Ma Pengcheng
Type of Accident : SIDE SWIPE
Date / Time of Accident : 06/04/2018 12:25:00 PM
Accident Reported Date / Time : 09/04/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : AIG
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No :
Special Instruction to ARC,if any :
left front portion damaged
TP: SLH457G (AIG)
Prepared Date : 09/04/2018 12:01:28 PM

