



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18007803/T1ja3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 10-10-2018



ATTN: STACEY NG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 6660X	Veh. Inspected	XE 3805P
Policy No.	P1844389	Coverage (\$)	0.00
Claim No.	S8M00F80	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	26/04/2018

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI FUSO	c.c	11967
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	FP51SDA20245	Colour	RED
Odometer	26880	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/90 R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	295/90 R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	295/90 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	295/90 R22.5 (D)	BRIDGESTONE	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/04/2018	Inspection Date	11/06/2018
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------