

2/20/2018

ASS. REC. BY:

REF:

CS/msh18007881/Krbn2

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

Medmen

From (Person):

Fievel Foo

of

msh

Date/Time:

30042018 11:02am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBA 3107C

Insured:

GBF 2399G

at Workshop m/s

Serve you motor

Tel:

6481 8652

of

Blk 5053 Amk Ind Park 2 #01-265

Policy No:

28994971 MKC

Claim No:

556942

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26042018

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement:

Date/Time:

30042018 11am

Person Contacted:

Elaine

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBA 3107C - X

GBF 2399G - X

Revert the menmen

11/5 11:02 8145d email & confirm (Red: \$4911.50, 77%).

ASS. REC. BY:

REF: MS6/Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

03 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

5/22

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

GBA 31070Yr Regn: 05, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Ty Dynac.c. 2982

Colour: _____

Silver

A/C: Insured / Std / NI / NA

Sp. Reading _____

329822

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JTFAT354003000761

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: OTHR 195R15X8R: Dun 155R12X8 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. _____

mm

Rear

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

2614118

D.O.I. _____

30/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/5File p51 to Carmin

RECEIVED 15 MAY 2018

Data/Time, File Pass to?



: Prell. Report



: Final Report

1) typist

Data/Time, File Return to?

Days of Repair: 3

Resurvey No. of Trlp: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

15010160Report Format: TPLump Sum / LB.L: (\$ 1450)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Apr 2018		30 Apr 2018 11:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	KSY MARKETING PTE LTD , Co. Reg. No.: 200000065H								
Main Claimant:	A&S TRANSIT PTE LTD , Co. Reg. No.: 201216917G								
Vehicle Reg. No.:	GBA3107C	Date of Loss:	26/04/2018 00:00 - :59 [131 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 556942	Policy/Cover Note No.:	28994979MKC (Comprehensive) Coverage: 17/08/2017 - 16/08/2018						
Vehicle Reg. No. (Insured):	GBF2399G	Policy No. (Claimant):							
		Excess:	\$5600.00						
Repairer:	Serve You Motor Service (HQ) BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-265, 569536 Ang Mo Kio - Tel: 64815652								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/05/2018]								
Adj Asg. Remarks:	REQUEST KENNETH KONG TO CONDUCT SURVEY								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 03 May 2018

Preliminary Advice

Insured Vehicle : GBF2399G
No

TP Vehicle No : GBA3107C

Make : TOYOTA DYNA 150

Date of : 30/04/2018

Inspection

Inspection At : SERVE YOU MOTOR SERVICE (HQ)
BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-265
SINGAPORE 569536

Accident Date : 26/04/2018

Assignment Date : 30/04/2018

Est. Duration of : 3.00
Repair

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,361.50
Revised Amount	:S\$	3,064.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,064.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.



70
km/h

3107

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport /Company Cert No.: 201216917G
 Owner ID Type: Company
 Owner Name: A&S TRANSIT PTE. LTD.
 Registered Address: 46C HILLSIDE DRIVE SINGAPORE 548993
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: GBA3107C
 Previous Vehicle No.: -
 Effective Date of Ownership: 04 Dec 2017
 Original Regn Date: 15 May 2007
 Registration Date: 15 May 2007
 Year of Manufacture: 2007
 Vehicle Type: Goods (Closed) Van/Van Panel (Delivery)
 Vehicle Scheme: -
 Vehicle Attachment 1: No Attachment
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: TOYOTA
 Vehicle Model: DYNA 150 MANUAL
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 1
 Chassis No.: JTFAT35Y003000761
 Engine No.: 1KD1624956
 Engine Capacity /Power Rating: 2982 cc / -
 Maximum Power Output: -
 Propellant: Diesel

SERVE YOU MOTOR SERVICE

BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-265, SINGAPORE 569536

TEL. NO: 64810555 / FAX NO. 64831654

E-MAIL: serveyou5033@gmail.com

*Not Notation
11 Apr @ 1450h
Resurvey After Paint
3 days*

Ins: MSIG INSURANCE (SINGAPORE) PTE LTD

COMPANY: A & S TRANSIT PTE LTD

Registration no. : GBA 3107 C / TOYOTA DYNA 150 MANUAL

Date : 27-Apr-18

Quotation No. : 18427-1

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	2	Rear swing door	\$1380 each	NLSB	\$2,760.00	✓
2	1	Rear swing door window glass LH		Br	\$380.00	✓
3	1	Rear swing door window glass LH rubber		m 90	\$180.00	✓
4	3	Rear swing door window glass LH safety bar	\$138 each	✓	\$414.00	✓
5	1	Rear swing door lower LH side hinge		✓	\$188.00	✓
6	1	Rear swing door pillar LH		✓	\$850.00	✓
7	1 set	Rear swing door centre rod		(B)	\$950.00	✓
8	2	Rear swing door centre rod holder	\$105 each	✓	\$210.00	✓
9	1	Rear swing door under lock		✓	\$145.00	✓
10	1	Rear lamp LH		✓	\$165.00	✓
					\$6,242.00	
Less 25%					\$1,560.50	
					\$4,681.50	

SPECIAL NETT ITEMS

1	1	Window glass protection		m	\$120.00	✓
2	1	70 km/h sticker		m	\$30.00	✓
					\$150.00	

LABOUR & MISC CHARGES

1	To dismantle / renew the rear accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	30d.	\$1,200.00	
2	Supply spray paint material and necessary items to respray on rear accident damage area.	NW	\$250.00	✓
3	To remove and to refix the rear swing door window glass	5d	\$80.00	

TOTAL

Total Parts and Labour Cost of Repair

Date:		\$1,530.00
Signature:		\$6,361.50
Acknowledged by Reparer		
is subject to final approval from Insurance Company		
• Supplementary item(s) must be reserved and		
• No illegal modification(s) is allowed		
• Third party survey is on a "Without Prejudice" basis		
• Parts prices are subject to confirmation		
• To display damaged part(s) during resurvey		
• To resurvey before/after spray painting		
the Reparer of the following:		
LKK Auto Consultants hence notify		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18007881/KRBN2

Date: 18/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28994979MKC
Claimant Vehicle No :	GBA3107C	Insured Vehicle No :	GBF2399G
Date of Loss:	26/04/2018	Nature of Claim:	TP
		Claim No:	556942

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA3107C	Engine No:	1KD1624956
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y003000761
Reg. Date:	15/05/2007 (Man. Year: 2007)	Odometer:	329822 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	155R12X8 (D)
Front Left Side:	OHTSU 8 mm	Rear Left Side:	Dunlop 6/6 mm
Front Right Side:	OHTSU 8 mm	Rear Right Side:	Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,831.50	1,482.00	3,349.50	69.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	350.00	1,180.00	77.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,361.50	1,832.00	4,529.50	71.20
Approved Total (Overridden) (S\$)		1,450.00		
Nett Amount (S\$)	6,361.50	1,450.00	4,911.50	77.21

INSPECTION

Date of Assignment:	30/04/2018	
Date Inspected:	30/04/2018 Inspected At:	Serve You Motor Service (HQ) BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-265 Singapore 569536
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 May 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA3107C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SWING DOOR	N/s Bent	2,760.00 FL	*1,380.00 FL
2	1		*REAR SWING DOOR WINDOW GLASS LH	Broken	380.00 FL	*380.00 FL
3	3		*REAR SWING DOOR WINDOW GLASS LH SAFETY BAR	Repair	414.00 FL	*- FL
4	1		*REAR SWING DOOR LOWER LH SIDE HINGE	Repair	188.00 FL	*- FL
5	1		*REAR SWING DOOR PILLAR LH	Repair	850.00 FL	*- FL
6	1		*SET REAR SWING DOOR CENTRE ROD (BENT)	Not Consistent With The Impact	950.00 FL	*- FL
7	2		*REAR SWING DOOR CENTRE ROD HOLDER	Serviceable	210.00 FL	*- FL
8	1		*REAR SWING DOOR UNDER LOCK	Repair	145.00 FL	*- FL
9	1		*REAR LAMP LH	Serviceable	165.00 FL	*- FL
10	1		*REAR SWING DOOR WINDOW GLASS LH RUBBER (50%)	Necessary	135.00 FS	*90.00 FS
11	1		*WINDOW GLASS PROTECTION	Necessary	120.00 FS	*60.00 FS
12	1		*70KM/H STICKER	Necessary	30.00 FS	*12.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,347.00	1,922.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,515.50	440.00
Total Parts (\$\$)	4,831.50	1,482.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW THE REAR ACCIDENT DAMAGED PORTION.TO PANEL BEATING,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,200.00	300.00
2	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS.TO RESPRAY ON REAR ACCIDENT DAMAGED AREA	New	250.00	-
3	TO REMOVE AND TO REFIX THE REAR SWING DOOR WINDOW GLASS	New	80.00	50.00
Gross Labour Cost (\$\$)			1,530.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >