

Your Ref: 17.23231.S.CK.jt

Date: 27<sup>th</sup> July 2018

Our Ref: CS1/LAW18007903/Asbs2

**M/s Seah Ong & Partners LLP**

36 Robinson Road

#12-03 City House

Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SJJ 75M INSURED VEHICLE: SKF 4493Y ACCIDENT DATE: 10/11/2016**

We thank you for your instruction on 01/12/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJJ 75M from M/s PAR Automotive Consultancy.
- b) Survey report by Chow Automobile Assessor & Surveyor with colour photographs.
- c) Final Repair Bill of SJJ 75M from M/s H S Automotive Services.
- d) Singapore Accident Statement of Vehicles SJJ 75M and SKF 4493Y.
- e) Colour damaged vehicle photographs of SJJ 75M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJJ 75M
Make & Model	: Toyota Lexus GS300 A
Year of Registration	: 2007
Chassis Number	: JTHBH96S605053270

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.