

CHOW AUTOMOBILE ASSESSOR & SURVEYOR

BLK 299, BUKIT BATOK ST 22, #02-10, SINGAPORE 650299.

(Business Reg.No. 282126/00K)

Tel: 62941864, Fax: 66654133

Email: chowauto@singnet.com.sg

OUR REF.: C/AXA/M289/17

WITHOUT PREJUDICE

YOUR REF.: C0423637MC/NPS (D.O.A. 10/11/16)
INSURED VEH.: SKF 4493 Y

DATE: 30.5.17

AXA INSURANCE SINGAPORE PTE LTD
8, SHENTON WAY
#27-01
SINGAPORE 068811.

Dear Sir,

Re: Reinspection Of 3rd Party Vehicle
VEHICLE NO.: SJJ 75 M
MODEL : TOYOTA LEXUS GS300 AUTO
CHASSIS NO.: JTHBH96S605053270
ODOMETER : 144,540KM
YEAR : 2007

As instructed by Miss Stacey Ng on 08/3/17, I had proceeded to M/s. H.S. Automotive Services, at No.2, Kaki Bukit Ave 2, #01-15 Kaki Bukit Autohub on 22/4/17 @ 1100hrs.to reinspect the vehicle with the following documents attached.

- (1) Photocopies of M/s. Par Automotive Consultancy Survey Report.
- (2) Photocopies photographs of above vehicle. (taken by 3rd Party's Surveyor)
- (3) Photocopies of both parties SAS report.

Having read the above documents and reinspected the vehicle, I have revised the cost of repairs to \$1,786.00 net on a part by part basis. (Please refer to "Appendix A") attached.

I believe the above recommendations in my opinion is fair and reasonable instead of lump sum \$12,100.00 nett as recommended by the 3rd party's surveyor.

I estimated that the repairs will take about 5 days instead of 7 days to complete.

I had offered the repairer our recommendation but they had not agreed to accept it.

....2/-

CHOW AUTOMOBILE ASSESSOR & SURVEYOR
BLK 299, BUKIT BATOK ST 22, #02-10, SINGAPORE 650299.
(Business Reg.No. 282126/00K)
Tel: 62941864, Fax: 66654133
Email: chowauto@singnet.com.sg

...2/-

OUR REF.: C/AXA/M289/17

YOUR REF.: C0423637MC/NPS (D.O.A. 10/11/16)
INSURED VEH.: SKF 4493 Y

I enclosed 39 copies photograph taken at the time of reinspection for your perusal.

I now revert the above matter to your Insurance Co. for the final decision.

Thank you

Yours faithfully
CHOW AUTOMOBILE ASSESSOR AND SURVEYOR

Chow Cher Pow

C.P.CHOW
VEHICLE APPRAISER

<u>REPLACEMENT OF PARTS</u>	<u>REPAIRER'S ESTIMATE</u>	<u>REMARKS</u>	<u>REVISED</u>
TO SUPPLY (SJJ 75 M TOYOTA LEXUS GS300A)		YEAR : 2007 (D.O.A. 10/11/16)	
1 pc. Front fender R/H	1,013.30	Repair	
1 pc. Front fender signal lamp R/H	46.10	Serviceable	
10pcs. Front fender mud shield clips R/H	21.00	Not necessary	
1 pc. Front headlamp assy R/H	1,404.10	Not damage	
1 pc. Front bumper	978.80	Repair	
1 pc. Front bumper sponge	108.00	Not consistent	
2pcs. Front bumper side retainer R/H L/H	105.50	Not necessary	
8pcs. Front bumper clips	40.00	replace	40.00
1 pc. Side mirror R/H	1,873.20	not damage	
1 pc. Side mirror glass	687.20	"	
1 pc. Front door R/H	1,019.20	Repair	
1 pc. Front door lock	561.80	Serviceable	
1 pc. Front door w/strip	168.30	Not necessary	
1 pc. Front door protector	278.70	"	
1 pc. Front door glass outer moulding	261.30	"	
1 pc. Front shock absorber top mounting	132.80	Not consistent	
1 pc. Front top arm R/H	891.80	"	
1 pc. Front knuckle arm R/H	700.30	"	
1 pc. Front wheel bearing R/H	142.90	"	
1 pc. Front wheel hub R/H	241.10	"	
1 pc. Front lower arm R/H	599.40	"	
1 pc. Front lower arm ball joint R/H	195.50	"	
1 pc. Front torsion arm R/H	236.00	"	
1 pc. Front ABS sensor RH	268.30	"	
1 pc. front anti roll link R/H	216.60	"	
	12,191.20		40.00
Less 10%	1,219.12	Less 10%	4.00
	10,972.08		36.00
1 pc. Front sport rim	1,200.00	sn	
1 pc. Front tyre	500.00	"	
	12,672.08		36.00
<u>LABOUR CHARGES :</u>			
Remove damaged parts, jack out and cut out panels, realign R/H body, replace damaged parts, weld where necessary and refit same.	880.00	Necessary	800.00
Spray paint the exterior and interior of replacement parts and respray damaged parts to same colour.	800.00	Necessary	800.00
Balance C/F	14,352.08	Balance C/F	1,636.00

<u>REPLACEMENT OF PARTS</u>	<u>REPAIRER'S ESTIMATE</u>	<u>REMARKS</u>
TO SUPPLY (SJJ 75 M TOYOTA LEXUS GS300A)		YEAR : 2007 (D.O.A. 10/11/16)
Balance B/F	14,352.08	Balance B/F 1,636.00
Remove front lamps, replace damaged lamps, refit same, refocus headlamps and check lights system.	50.00	Necessary 30.00
To remove and refit tyre/rim and balanced.	60.00	Not necessary
Check and realign both front wheel alignment.	180.00	Necessary 120.00
Remove and dismantle R/F axle and suspensions, steering gear and linkages, replace damaged parts, reassemble and refit same, bleed brakes system.	400.00	Not consistent
To respray rust-proof under-seal to affected areas.	60.00	Not necessary
Remove R/F door fittings and mechanisms, transfer to new door, replace damaged parts and refit same.	120.00	Not necessary
TOTAL :	15,222.08	1,786.00

ADJUSTED AMOUNT	\$ 1,786.00
LUMP SUM REPAIR AT	\$ N.A
LESS EXCESS	\$ N.A
NETT TOTAL	\$ 1,786.00

IT IS ESTIMATED THAT THE REPAIRS WILL TAKE FIVE DAYS TO COMPLETE.



















