

SMRT Accident Vehicle Repair Estimates

Axa

CIB

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF362D
 Ref. No : TAX/04/18/2132
 Reg. Date : 14/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : POH SWEE KHENG
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 27/04/2018 07:35:00 PM
 Accident Reported Date / Time : 28/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095794
 Special Instruction to ARC,if any :
 GBH1411A
 Prepared Date : 28/04/2018 08:41:54 AM



Sebastian.
 30/4/18.
 - Part by part repair.
 - Question Mark Item
 Photo
 - Photo Before Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU603576608

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	1,314.00	0.00
Total Material Charges :	4,032.82	4,032.82
Other Charges :	460.00	0.00
TOTAL :	6,820.82	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	6.00	0.00
Prepared / Adjusted By :		3 days
Arc / Surveyor Sign Off Date :	28/04/2018 10:51:00 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/04/2018 10:49:59 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	1,014.00	0.00 400
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO RESPRAY FRONT DOOR RH	378.00	0.00 200
TO RESPRAY VIEW MIRROR	180.00	0.00 50
Total Spray Painting & Panel Beating	1,314.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X
TO TRANSFER DOOR MECHANISM	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	460.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5211947962			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace R	No
5211547050			SUPPORT, FR BUMPER RH	1	76.90	25.00	57.67	Replace	Replace ?	No
5380147080			FENDER SUB-ASSY, FR , RH	1	933.10	25.00	699.82	Replace	Replace R	No
7537447140			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace ✓ NRC	No
5387547070			LINER, FR FENDER, RH	1	198.40	25.00	148.80	Replace	Replace X	No
6700147152			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	25.00	937.20	Replace	Replace R	No
6871012151			HINGE ASSY, FRONT DOOR , UPPER RH	1	82.10	25.00	61.57	Replace	Replace X	No
6873012120			HINGE ASSY, FRONT DOOR , LOWER RH	1	92.10	0.00	92.10	Replace	Replace X	No
6861047040			CHECK ASSY, FRONT DOOR	1	153.50	25.00	115.12	Replace	Replace X	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace ✓ NRC	No
8791047450			MIRROR ASSY, OUTER REAR VIEW , RH	1	1,373.50	10.00	1,236.15	Replace	Replace X	No
8173047010			LAMP ASSY, SIDE MIRROR TURN SIGNAL , RH	1	162.20	10.00	145.98	Replace	Replace X	No
8791547070A1			COVER, OUTER MIRROR, RH	1	89.50	25.00	67.12	Replace	Replace R	No
TOTAL MATERIALS								4,032.86	4,032.82	
TOTAL MATERIALS(Discounted)								4,032.82	4,032.82	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									