

Surveyor:

REF: CSI/LAW18007911/Veeber

Special Instruction:

1/s: \$ 17420.00

ASSIGNMENT (Office)

From (Person): Heng Xinyi of Seah Ong Date/Time: 30042018  
Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

Third Parties:

Claimant:

Surveyor: RW Automotive

Workshop: SAT Motors

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SGT 2635S Insured: STY 5121B

at Workshop m/s SAT Motors

Tel: \_\_\_\_\_

of 24 Debu Lane 12

Policy No: \_\_\_\_\_

Claim No: 162060.S-CK.XY

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_

D.O.A. 1308.2015

(Client's Record)

H.O.D. Endorsement/Date: \_\_\_\_\_

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT

Date/Time: \_\_\_\_\_ Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_\_ days (Red \$ \_\_\_\_\_ / \_\_\_\_\_ %; Original 28 days)

Date/Time: 12/6/18 Submit Final Fig 4514500, 22 days (Red \$ 4920 / 25 %; Original 28 days)

Date/Time	Action/Instruction
	SGT 2635S - C93 / DMC15014006/Yb
	STY 5121B - X
	photo 192 pcs. Reel 16 f116 = 22h.
	45 814500 22h.
	RECEIVED 12 JUN 2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : \_\_\_\_\_  
Salvage Value : \_\_\_\_\_  
Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by: \_\_\_\_\_

Fee Charged:

Basic & Add  
Transport  
Photos  
Others  
Total

Date:

700

700

1) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

2) Date/Time \_\_\_\_\_

File Return to \_\_\_\_\_

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

4) Date/Time \_\_\_\_\_

File Return to \_\_\_\_\_

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

6) Date/Time \_\_\_\_\_

File Return to \_\_\_\_\_

**Catherine Chong (LKK Auto)**

---

**From:** Xin Yi <xinyi@seahong.com.sg>  
**Sent:** Monday, 30 April, 2018 2:10 PM  
**To:** 'assignments'  
**Cc:** Chee Kiong  
**Subject:** [Your file ref: SGT 2635S] [Our file ref: 16.22060.S.CK.xy]  
**Attachments:** LKKPhotosIn6-1.pdf; PF survey photos.pdf; PF survey report-30.04.18.pdf; Letter to LKK-30.04.18.pdf  
  
**Importance:** High

Dear Catherine,

**ISSUE PAPER SURVEY REPORT OF SGT 2635S**

**MC / MC SUIT NO. 4951 OF 2017 – CLAIM BY KUMARAN S/O SATHIANANTHEN (OWNER & DRIVER OF SGT 2635S)**

**ACCIDENT ALONG PIE TOWARDS TUAS INVOLVING SJY 5121B AND SGX 8892E AND SGT 2635S AND SHB 7589S AND GY 6809E ON 13 AUGUST 2015**

1. We act for AXA Singapore Pte Ltd, the insurer of motor vehicle no. SJY 5121B at the material time of the abovesaid accident.
2. Attached please find our letter dated 30 April 2018 together with its enclosures, for your attention.

Thanks & Best Regards

**Heng Xinyi**

(Secretary to Mr Tan Chee Kiong)

Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

Tel: 6536 5369

Fax: 6536 5811

This message is intended for the recipient named above. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Thank you.

Disclaimer: Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has not been tampered with, Seah Ong & Partners LLP cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this message for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the company shall be understood as neither given nor endorsed by Seah Ong & Partners LLP.

Your reference : SGT 2635S  
Our reference : 16.22060.S.CK.xy  
Date : 30 April 2018  
Writer's email : cheekiong@seahong.com.sg  
Secretary's email : xinyi@seahong.com.sg



We do not accept service  
of court documents via facsimile

**LKK AUTO CONSULTANTS PTE LTD**  
51 Ubi Avenue 1  
#01 – 25, Paya Ubi Industrial Park  
Singapore 408933

By fax wo enc (6256 4315) & Email

(assignments@lkkauto.com)

Dear Sir,

**ISSUE PAPER SURVEY REPORT OF SGT 2635S**  
**MC / MC SUIT NO. 4951 OF 2017 – CLAIM BY KUMARAN S/O SATHIANANTHEN**  
**(OWNER & DRIVER OF SGT 2635S)**  
**ACCIDENT ALONG PIE TOWARDS TUAS INVOLVING SJY 5121B AND SGX 8892E AND**  
**SGT 2635S AND SHB 7589S AND GY 6809E ON 13 AUGUST 2015**

1. We act for AXA Singapore Pte Ltd, the insurer of motor vehicle no. SJY 5121B at the material time of the abovesaid accident.
2. We note that you have previously been instructed by M/s United Legal Alliance, appointed through the motor insurers of motor vehicle no. SGX 8892E to conduct pre-repair inspection on the Plaintiff's vehicle.
3. We attach herewith the following documents in respect of vehicle No. SGT 2635S for your attention :-
  - (1) the survey report of RW Automotive Appraisers Services; and
  - (2) Copies of the pre repair photographs taken by your surveyor.
4. Please let us have your paper survey report urgently.

Yours faithfully



TAN CHEE KIONG  
SEAH ONG & PARTNERS LLP

Encl

cc client



Our Ref : CY.7607.15.PD(SAT).wp(Lh)

Your Ref : Your insured vehicle **SJY 5121B**

30 November 2015



60929629

The Motor Claims Department  
**AXA Insurance Singapore Pte Ltd**  
8 Shenton Way #27-01  
Singapore 068811

WITHOUT PREJUDICE  
BY HAND

Dear Sirs

**Accident Involving SGT 2635S; SGX 8892E & SJY 5121B ON 13.08.2015 @ 18:00HRS  
ALONG PIE TOWARDS TUAS BEFORE EXIT 12**

We are instructed by **Mr. Kumaran S/O Sathiananthen** to claim damages and losses against you in connection with the above-captioned road traffic accident which our client's vehicle **SGT 2635S** was damaged by vehicle **SJY 5121B** driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense. **Without prejudice to insurer's subrogated claim and/or personal injury claim**, particulars of our client's uninsured losses claim are as follows:-

1)	Repair costs	\$19,420.00
2)	Rental (55 days @ \$150.00 per day)	\$ 8,250.00
3)	Survey fee	\$ 872.00
4)	LTA fee	\$ 5.35
5)	Accident report fee	\$ 29.00
6)	Costs & Incidental	\$ 1,500.00
7)	GST on costs & Incidentals	\$ 105.00
		<u>\$30,181.35</u>

A copy each of the following supporting documents is enclosed:-

- 6) Traffic Police report of our client's vehicle
- 7) Survey report on SGT 2635S, together with **192** coloured photographs
- 8) Final repair bill
- 9) Rental invoice / agreement
- 10) LTA report on SGX 8892E

Please let us know within the next seven (7) days upon receipt of this letter whether you intend to re-inspect our client's vehicle failing which the said vehicle will no longer be available for the same.

(CY.7607.15.PD(SAT).wp(Lh)

Page 2

Please note that you should send to us an acknowledgment of receipt of this letter within fourteen(14) days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you.


Please note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

Yours faithfully

  
**C. YOGARAJAH LLC**  
Enc

cc **Chow Xin Yi**  
c/o PolyTech Component Pte Ltd  
10 Ubi Crescent  
#04 – 68 Ubi Teckpark  
Singapore 408564  
**(Documents were enclosed to your insurers)**

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999



T/20150814/2013

1 of 4

Report No. T/20150814/2013

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 14/08/2015 04:20	Vide Report No.:	Station Diary No.: 17
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: KUMARAN S/O SATHIANANTHEN	Address: APT BLK 548B SEGAR ROAD #15-672 SINGAPORE 672548		
ID Type / ID No.: NRIC NO / S8517522Z	Contact No.: Home/Office: Mobile: 97230055		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 30	Date of Birth: 23/05/1985	Type of Informant: Driver
Race: Indian	Language: English		Institution / School Name:
Occupation: SALES ENGINEER	Driving Licence Information: Class: 3 .Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 13/08/2015 18:00	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE towards Tuas before exit 12				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Chain collision			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GY6809E	Van					0
SGT2635S	Car	SUZUKI	SWIFT 1.6 MT	Yellow	Seriously Damaged	0
SGX8892E	Car					0
SHB7589S	TAXI				Slightly Damaged	0
SJY5121B	Car					0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective Date	Expiry Date
-------------	-------------------	--------------	----------------	-------------

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999



T/20150814/2013

2 of 4

Report No. T/20150814/2013

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective Date	Expiry Date
SGT2635S	AXA INSURANCE SINGAPORE PTE LTD	GA042751	05/06/2015	04/06/2016

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	Muhammad Farhan Bin Abd Rashid		ID No.	S8726375D
Related Vehicle	GY6809E (Van)		Contact No.	90416508
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL		Degree of Injury	NIL
Driver				
Name	KUMARAN S/O SATHIANANTHEN		ID No.	S8517522Z
Related Vehicle	SGT2635S (Car)		Contact No.	97230055
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	13/08/2015		Date Discharge	14/08/2015
No. of Days granted Medical Leave (MC)	03		Degree of Injury	Slight
Driver				
Name	Yusfarah Ain binte Yusoff		ID No.	S8729365C
Related Vehicle	SGX8892E (Car)		Contact No.	98587047
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL		Degree of Injury	NIL



Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999



T/20150814/2013

3 of 4

Report No. T/20150814/2013

CONTINUATION OF REPORT

<b>Driver</b>			
Name	Chia song Heng	ID No.	S0043181H
Related Vehicle	SHB7589S (TAXI)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	Chow xin yi	ID No.	S9341609J
Related Vehicle	SJY5121B (Car)	Contact No.	91192122
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL

**Brief Details.**

On 13/08/2015 at about 1800hrs, I was travelling along PIE towards Tuas before exit 12 on the most right lane with my vehicle bearing with SGT2635S. While I was travelling, I notice the road in front of me was gradually slope and I could not visual the movement of the vehicle after the slope as there was a Taxi bearing with SHB7589S namely Chia song Heng, NRIC S0043181H in front of me. Suddenly, the said taxi had a hard break, however I managed to break in time without knocking onto him. But after a split seconds, I felt a huge impact from my rear right and the impact causes my vehicle to hit the said taxi and also my car swing to the left and collided onto right rear side of the van bearing with GY6809E driver namely Muhammad Farhan Bin Abd Rashid, NRIC S8726375D HP: 90416508 who was trying to avoid my vehicle on the 2nd lane from the right. Later I get down from my vehicle to know that the vehicle bearing with SGX8892E driver namely Yusfarah Ain binte Yusoff, NRIC S8729365C HP: 98587047 is the one who collided onto me from the rear however the said vehicle ended up in front of the taxi. I also notice there was another car involve in the accident which is SJY5121B driver namely Chow xin yi, NRIC S9341609J HP: 91192122. I wish to state that I did not install in-car CCTV however driver of SJY5121B informed that she has installed front view in-car CCTV and I suffered soreness and aching on my shoulder, lower back and stiff neck. My vehicle was damaged on the front left side and rear right side.

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999



T/20150814/2013

4 of 4

Report No. T/20150814/2013

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Leo Junwei Alvin

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Goh Geok Lye Pamela

Contact No.: 65476148

Signature Of Informant:

Date/Time:

14/08/2015 04:20


Classification Of Case:

Authentication Stamp

NP 168



SN 117

Signature : 

Singapore Police Force

**RW AUTOMOTIVE APPRAISERS SERVICES**

(Licensed Appraisers & Claims Adjusters)  
256 Bishan St. 22 #12-472 Singapore 570256  
Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912  
Reg. No. 52821270B

CY-7007

**INVOICE**

SAT Motors  
Blk 20, Sin Ming Industrial Estate  
Sector A, #01-10  
Singapore 575678  
On behalf of Kumaran S/O Sathiananthan

Invoice No : 150281

Date : 10.09.2015

Being:		
Survey Fees (including 192 photographs and transport charges)		\$ 872.00
S'pore Dollars	: Eight Hundred and Seventy-Two only.	<u>\$ 872.00</u>
Our Reference No.	: RW/0281/15TP	
Vehicle No.	: SGT 2635 S	

**SURVEYED WITHOUT PREJUDICE**

**RICHARD WONG**  
(Licensed Appraiser)



# RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

Kumaran S/O Sathiananthen  
c/o SAT Motors  
Blk 20, Sin Ming Industrial Estate  
Sector A, #01-10  
Singapore 575678

Report No RW/0281/15TP

Date 10.09.2015

## VEHICLE INSPECTION REPORT

### REFERENCE

Requested by Workshop, owner's behalf  
Date of Request 20.08.2015  
Date of Accident 13.08.2015  
Date of Inspection 20.08.2015  
Inspected at SAT Motors  
Blk 20, Sin Ming Industrial Estate Sector A  
#01-10, Singapore 575678

### VEHICLE DETAILS

Vehicle No.	SGT 2635 S	Make & Model	Suzuki Swift
Year Make	2007	Colour	Yellow
Engine No.	M16A1232955	Chassis No.	JSAEZC31S00101665
Engine Capacity	1586 cc	Mileage	163,719 km
Air-Con	Yes	Radio/CD/Cassette	Yes
Seat Belt	Yes	Rims	Sport

### GENERAL CONDITION OF VEHICLE

General Condition	Good	Modification	Nil
Brakes	Affected	Handbrake	Serviceable
Steering	Serviceable		

Tyres	Make	Size	Rim	Tread Balance
Front Right	Federal	205/45 ZR16	Sport	5 mm
Front Left	Federal	205/45 ZR16	Sport	5 mm
Rear Right	Federal	205/45 ZR16	Sport	5 mm
Rear Left	Federal	205/45 ZR16	Sport	5 mm

### ASSESSMENT

	Repairer's Estimate	Recommendation
Spare Parts	\$ 15,944.12	\$ 15,183.83
Labour Charges	\$ 7,310.00	\$ 6,240.00
Paint Work	\$ 3,000.00	\$ 2,750.00
Towing Charges	\$ 120.00	\$ 100.00
Total	<u>\$ 26,374.12</u>	<u>\$ 24,273.83</u>
Recommend lump sum repairs		\$ 19,420.00
Reduction		<u>\$ 6,954.12</u>
Estimated Period Required for Repair		<u>28 days</u>



# RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

Page 1

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SGT 2635 S

Report No.: RW/0281/15TP

S/No	QTY	Description	Condition/ Remarks	Repairer's Estimates	My Recommendation
<b>REPLACEMENT OF DAMAGED PARTS</b>					
1)	2	Rear number plate lamps	Cracked <i>11</i>	\$ 83.60	\$ 83.60 <i>X</i>
2)	1	Rear bumper	Torn <i>D.S</i>	\$ 605.00	\$ 605.00 <i>X</i>
3)	1set	Rear bumper clips	Necessary <i>neu</i>	\$ 50.00	\$ 50.00 <i>/</i>
4)	2	Rear bumper side holders	Necessary <i>neu</i>	\$ 70.20	\$ 70.20 <i>/</i>
5)	1	Rear bumper lower garnish	Torn <i>neu</i>	\$ 411.10	\$ 411.10 <i>/</i>
6)	2	Rear bumper lower garnish lamps	Cracked <i>neu</i>	\$ 242.00	\$ 242.00 <i>/</i>
7)	1	Rear bumper impact bracket RH	Dented <i>neu</i>	\$ 47.20	\$ 47.20 <i>/</i>
8)	1	Rear end panel	Dented <i>neu</i>	\$ 305.00	\$ 305.00 <i>/</i>
9)	1	Rear end panel top garnish	Cracked <i>neu</i>	\$ 73.40	\$ 73.40 <i>/</i>
10)	2	Rear tail lamps	Cracked <i>neu</i>	\$ 579.40	\$ 579.40 <i>/</i>
11)	1	Rear tail lamp panel RH	Dented <i>neu</i>	\$ 114.50	\$ 114.50 <i>/</i>
12)	1	Rear tail gate	Dented/Bent <i>neu</i>	\$ 580.20	\$ 580.20 <i>/</i>
13)	1	Rear tail gate lock	Dented <i>neu</i>	\$ 149.50	\$ 149.50 <i>/</i>
14)	1	Rear tail gate weatherstripe	Cut <i>neu</i>	\$ 76.60	\$ 76.60 <i>/</i>
15)	1	Rear tail gate outer handle	Distorted <i>neu</i>	\$ 78.60	\$ 78.60 <i>X</i>
16)	1	Rear tail gate inner trim	Cracked <i>neu</i>	\$ 172.20	\$ 172.20 <i>/</i>
17)	1set	Rear tail gate inner trim clips	Necessary <i>neu</i>	\$ 50.00	\$ 50.00 <i>/</i>
18)	2	Rear tail gate dampers	Bent <i>neu</i>	\$ 257.20	\$ 257.20 <i>X</i>
19)	1	Rear tail gate glass moulding	Necessary <i>neu</i>	\$ 100.20	\$ 100.20 <i>/</i>
20)	1	Rear 'Suzuki' logo	Necessary <i>neu</i>	\$ 25.30	\$ 25.30 <i>/</i>
21)	1	Rear 'Suzuki' wording	Necessary <i>neu</i>	\$ 23.40	\$ 23.40 <i>/</i>
22)	1	Rear 'Swift' wording	Necessary <i>neu</i>	\$ 25.90	\$ 25.90 <i>/</i>
23)	1	Rear 'Sports' emblem	Necessary <i>neu</i>	\$ 22.80	\$ 22.80 <i>/</i>
24)	1	Rear fender RH	Dented <i>neu</i>	\$ 380.70	\$ 380.70 <i>/</i>
25)	1	Rear fender inner shield RH	Torn <i>neu</i>	\$ 76.50	\$ 76.50 <i>/</i>
26)	1set	Rear fender inner shield clips RH	Necessary <i>neu</i>	\$ 25.00	\$ 25.00 <i>/</i>
27)	1	Rear fender inner trim RH	Torn <i>neu</i>	\$ 110.60	\$ 110.60 <i>/</i>
28)	1set	Rear fender inner trim clips RH	Necessary <i>neu</i>	\$ 30.00	\$ 30.00 <i>/</i>
29)	1	Rear fender wheelhouse RH	Dented <i>neu</i>	\$ 346.00	\$ 346.00 <i>/</i>
30)	1	Rear spare tyre panel	Dented <i>neu</i>	\$ 589.50	\$ 589.50 <i>X</i>
31)	1	Rear spare tyre panel top board	Distorted <i>neu</i>	\$ 220.60	\$ 220.60 <i>/</i>
32)	1	Rear door RH	Distorted/Bent <i>neu</i>	\$ 575.10	\$ 575.10 <i>X</i>
33)	1	Rear door lock RH	Dented <i>neu</i>	\$ 152.50	\$ 152.50 <i>/</i>
34)	1	Rear door weatherstripe RH	Necessary <i>neu</i>	\$ 89.70	\$ 89.70 <i>X</i>
35)	2	Roof panel mouldings	Necessary <i>neu</i>	\$ 310.00	\$ 310.00 <i>/</i>
36)	1	Rear axle	Repairable <i>neu</i>	\$ 812.10	\$ 812.10 <i>X</i>
37)	1	Rear wheel hub	Distorted <i>neu</i>	\$ 179.00	\$ 179.00 <i>/</i>
38)	1	Rear shock absorber RH	Bent <i>neu</i>	\$ 277.50	\$ 277.50 <i>/</i>
39)	1	Rear exhaust pipe	Bent <i>neu</i>	\$ 579.30	\$ 579.30 <i>/</i>
40)	4	Rear exhaust mountings	Torn <i>neu</i>	\$ 112.00	\$ 112.00 <i>/</i>
				\$ 9,009.40	\$ 8,197.30



# RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

Page : 2

Vehicle No: SGT 2635 S

Report No.: RW/0281/15TP

Balance brought forward			\$ 9,009.40	\$ 8,197.30
41)	1	Front bumper	Tom \$ 518.70	\$ 518.70 ✓
42)	1set	Front bumper clips	Necessary \$ 50.00	\$ 50.00 ✓
43)	2	Front bumper side holders	Necessary \$ 58.40	\$ 58.40 ✓
44)	1	Front bumper tow cover	Missing \$ 24.30	\$ 24.30 ✓
45)	1	Front bumper lower grille	Cracked \$ 124.40	\$ 124.40 ✓
46)	2	Front bumper fog lamps	Cracked \$ 438.40	\$ 438.40 ✓
47)	2	Front bumper fog lamp covers	Cracked \$ 118.60	\$ 118.60 ✓
48)	2	Front bumper lower side garnishes	Cracked \$ 312.20	\$ 312.20 ✓
49)	1	Front bumper reinforcement upper	Bent \$ 143.70	\$ 143.70 ✓
50)	1	Front bumper reinforcement cover upper	Dented \$ 76.70	\$ 76.70 ✓
51)	1	Front bumper reinforcement lower	Bent \$ 125.70	\$ 125.70 ✓
52)	1	Front bumper reinforcement cover lower	Dented \$ 76.70	\$ 76.70 ✓
53)	1	Front bumper undercover	Toe \$ 86.10	\$ 86.10 ✓
54)	1	Front grille	Toe \$ 171.20	\$ 171.20 ✓
55)	1	Front grille logo	Necessary \$ 23.20	\$ 23.20 ✓
56)	2	Front headlamps	Cracked \$ 772.00	\$ 772.00 ✓
57)	1	Front bonnet	Dented/Bent \$ 473.80	\$ 473.80 ✓
58)	1	Front bonnet lock	Dented \$ 68.60	\$ 68.60 ✓
59)	1	Front bonnet weatherstripe	Cut \$ 26.10	\$ 26.10 ✓
60)	2	Front bonnet hinges	Bent \$ 57.80	\$ 57.80 ✓
61)	1	Front bonnet insulator	Necessary \$ 112.80	\$ 112.80 ✓
62)	1set	Front bonnet insulator clips	Necessary \$ 50.00	\$ 50.00 ✓
63)	2	Front fenders	Dented/Bent \$ 560.20	\$ 560.20 X
64)	2	Front VVT' emblems	Necessary \$ 55.20	\$ 55.20 ✓
65)	1	Front support panel	Bent \$ 551.50	\$ 551.50 ✓
66)	1	Air duct	Distorted \$ 89.00	\$ 89.00 ✓
67)	1	Engine top cover	Cracked \$ 268.30	\$ 268.30 ✓
68)	1	Wiper washer tank neck	Dented \$ 42.10	\$ 42.10 ✓
69)	1	Air con condenser	Dented/Bent \$ 471.70	\$ 471.70 ✓
70)	2	Air con condenser brackets	Bent \$ 31.00	\$ 31.00 ✓
71)	1	Front radiator	Dented \$ 632.40	\$ 632.40 ✓
72)	2	Front radiator top brackets	Bent \$ 32.40	\$ 32.40 ✓
73)	1	Front radiator fan cowling	Dented \$ 117.20	\$ 117.20 ✓
74)	1	Front radiator fan blade	Distorted \$ 55.40	\$ 55.40 ✓
75)	1	Front radiator fan motor	Dented \$ 352.20	\$ 352.20 ✓
76)	1	Front radiator side cover	Distorted \$ 37.60	\$ 37.60 ✓
77)	1set	Front radiator side cover clips	Necessary \$ 20.00	\$ 20.00 ✓
78)	1	Air con discharge pipe	Bent \$ 85.70	\$ 85.70 X
79)	1	Air con suction pipe	Bent \$ 115.70	\$ 115.70 X
80)	1	Air con liquid pipe	Bent \$ 155.60	\$ 155.60 X
81)	1	Front exhaust heat shield	Dented \$ 59.90	\$ 59.90 ✓
			\$ 16,651.90	\$ 15,839.80
Less 15%			\$ 2,497.79	\$ 2,375.97
			\$ 14,154.12	\$ 13,463.83



# RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

Page : 3

Vehicle No: SGT 2635 S

Report No.: RW/0281/15TP

Balance brought forward			\$ 14,154.12	\$ 13,463.83
82)	1	Rear number plate	Cracked <i>CR</i> \$ 30.00	SN \$ 30.00 ✓
83)	1	Rear end panel sealant	Necessary <i>NE</i> \$ 60.00	SN \$ 60.00 <i>50</i>
84)	1	Rear reverse sensors	Failed <i>SHUB</i> \$ 350.00	SN \$ 280.00 <i>200</i>
85)	1	Rear tail gate glass sealant	Necessary <i>NE</i> \$ 60.00	SN \$ 60.00 <i>40</i>
86)	1	Rear spare tyre panel sealant	Necessary <i>NE</i> \$ 100.00	SN \$ 100.00 <i>X</i>
87)	1	Rear spare tyre panel insulation pad	Necessary <i>NE</i> \$ 250.00	SN \$ 250.00 <i>120</i>
88)	1	Rear door visor RH	Necessary <i>NE</i> \$ 80.00	SN \$ 80.00 <i>X</i>
89)	1	Rear tyre RH	Cut <i>47</i> \$ 250.00	SN \$ 250.00 <i>125</i>
90)	1	Rear wheel rim RH	Dented <i>NE</i> \$ 550.00	SN \$ 550.00 <i>X</i>
91)	1	Front number plate	Missing <i>50</i> \$ 30.00	SN \$ 30.00 <i>20</i>
92)	1	Front number plate holder	Torn <i>30</i> \$ 30.00	SN \$ 30.00 <i>10</i>
Total (Parts):			\$ 15,944.12	\$ 15,183.83

## LABOUR CHARGES

93)	Remove and reinstall air cond condenser and recharge gas (134a).	\$ 150.00	\$ 120.00	<i>100</i>
94)	Remove and reinstall front radiator assy and conduct pressure test.	\$ 120.00	\$ 80.00	<i>80</i>
95)	Cut out, replace and weld rear end panel, rear right wheel house panel, rear right tail lamp panel, rear right fender, rear spare tyre panel and front support panel. Panel beat rear left fender and roof top panel. Straighten front chassises and rear right chassis. Remove and replace all damaged parts.	\$ 4,000.00	\$ 3,700.00	<i>2200</i>
96)	Check wiring and lightings.	\$ 200.00	\$ 150.00	<i>30</i>
97)	Remove and reinstall rear windscreen glass.	\$ 150.00	\$ 120.00	<i>✓</i>
98)	Remove and reinstall rear upholstery and cushion seats to enable repair.	\$ 380.00	\$ 300.00	<i>80</i>
99)	Remove and reinstall rear right undercarriage.	\$ 380.00	\$ 280.00	<i>150</i>
100)	Remove and reinstall rear exhaust silencer.	\$ 150.00	\$ 120.00	<i>80</i>
101)	Transfer rear tail gate fittings.	\$ 150.00	\$ 120.00	<i>60</i>
102)	Transfer rear right door fittings.	\$ 150.00	\$ 120.00	<i>X</i>
103)	Remove and replace rear reverse sensors.	\$ 100.00	\$ 60.00	<i>50</i>
104)	Mount vehicle on measuring bench to correct chassis alignment.	\$ 380.00	\$ 300.00	<i>✓</i>
		\$ 22,254.12	\$ 20,653.83	



# RW AUTOMOTIVE APPRAISERS SERVICES

(Licensed Appraisers & Claims Adjusters)

256 Bishan St. 22 #12-472 Singapore 570256

Tel: +65 6996 9988 Hp: +65 8338 9988 Fax: + 65 6553 3912

Reg. No. 52821270B

Page : 4

Vehicle No: SGT 2635 S

Report No.: RW/0281/15TP

Balance brought forward	\$ 22,254.12	\$ 20,653.83	
105) Computerise wheel alignment.	\$ 150.00	\$ 120.00	60
106) Remove and reinstall fuel tank.	\$ 150.00	\$ 120.00	60
107) Remove and reinstall roof lining to enable repair.	\$ 180.00	\$ 150.00	✓
108) Conduct waterproof test after repair.	\$ 120.00	176 80.00	X
109) Rust proofing treatment on affected area.	\$ 400.00	\$ 300.00	150
110) Spray painting on affected area.	\$ 3,000.00	\$ 2,750.00	1800
111) Towing charge.	\$ 120.00	\$ 100.00	✓
Total (Labour):	\$ 10,430.00	\$ 9,090.00	
Total:	<u>\$ 26,374.12</u>	<u>\$ 24,273.83</u>	

## POINT OF IMPACT

At the rear portion right side and front portion of the vehicle.

2803930

## RECOMMENDATION

The vehicle was inspected thoroughly based on the repairer's estimate against the actual damages found on the vehicle. My findings and recommendation are listed as per attached.

My adjusted amount for the cost of repair is \$24,273.83.

## CONCLUSION

The repairer has agreed to undertake repairs at a lump sum of \$19,420.00 corresponding to labour charges, spray painting, replacement of parts and towing charges.

SURVEYED WITHOUT PREJUDICE


RICHARD WONG  
(Licensed Appraiser)





# SAT MOTORS

Blk 20 Sin Ming Industrial Estate Sector A, #01-10

Singapore 575678

Tel: 6748 1141 Fax: 6749 1141

## Invoice

Date: September 16, 2015

Vehicle Model: Suzuki Swift

Car Plate No: SGT2635S

To: KUMARAN S/O SATHIANANTHEN  
S8517522Z (NRIC)  
- (ADDRESS)  
-  
- (PHONE)

No.	Description	Unit Price	Line Total
1	Repair Cost		\$19,420

Subtotal \$ 19,420.00

Sales Tax

Total \$ 19,420.00

### Terms & Conditions:

The deposit will be used in the event of loss of or damage to the vehicle where the Renter will be fully liable on the cost of necessary repairs or replacement and the deposit will be credited towards the Owner. The Renter shall top up for any excess amount for the repair or replacement cost if the deposit amount was insufficient.

In the absence of damage or loss, the deposit will be return to the Renter after handling over the vehicle.

The Renter agree to compensate the Owner for the sum of deposit in the event of breach of contract.

Kindly make all cheque payable to SAT Motors

and mail to 20 Sin Ming Industrial Estate #01-10 Singapore 575678

# Singapore Automobile Trading Pte Ltd



1 Kaki Bukit Road 1, #03-47 Enterprise One, Singapore 415934

Tel: 6748 1141 Fax: 6749 1141

Website: [www.singaporeautomobiletrading.com.sg](http://www.singaporeautomobiletrading.com.sg)

Biz Reg No.: 200915171E

## Invoice

Date: September 16, 2015

Invoice #: Satpl 154

Vehicle Model: Mitsubishi Lancer

Car Plate No: SJH4843Y

To: KUMARAN S/O SATHIANANTHEN (RENTER NAME)

S8517522Z (NRIC)

(ADDRESS)

(PHONE)

No.	Description	Unit Price	Line Total
1	Rental Cost for the period of 55days starting from 20/08/2015 to 14/10/2015	\$150	\$8,250

Subtotal \$ 8,250.00

Sales Tax

Total \$ 8,250.00

### Terms & Conditions:

The deposit will be used in the event of loss of or damage to the vehicle where the Renter will be fully liable on the cost of necessary repairs or replacement and the deposit will be credited towards the Owner. The Renter shall top up for any excess amount for the repair or replacement cost if the deposit amount was insufficient.

In the absence of damage or loss, the deposit will be return to the Renter after handling over the vehicle.

The Renter agree to compensate the Owner for the sum of deposit in the event of breach of contract.

Kindly make all cheque payable to Sat Motors

and mail to 20 Sin Ming Industrial Estate #01-10 Singapore 575678

# VEHICLE RENTAL AGREEMENT

INVOICE : SATPL

## HIRER'S PARTICULAR

Name (as in I/C) KUMARAN S/D SATHIANANDH  
NRIC / PASSPORT No S45H5222  
Address (Res) : \_\_\_\_\_

Name & Address of Employer : \_\_\_\_\_

Occupation : \_\_\_\_\_ Email : \_\_\_\_\_  
D/L No : \_\_\_\_\_ D/L Type : Local / International  
Pass Date : \_\_\_\_\_ Date of Birth : \_\_\_\_\_  
Tel : (O) \_\_\_\_\_ (R) \_\_\_\_\_ HP : \_\_\_\_\_


## ADDITIONAL DRIVER'S PARTICULARS

Name (as in I/C) : \_\_\_\_\_  
NRIC / PASSPORT No : \_\_\_\_\_  
Address (Res) : \_\_\_\_\_

D/L No : \_\_\_\_\_ D/L Type : Local / International  
Pass Date : \_\_\_\_\_ Date of Birth : \_\_\_\_\_  
Occupation : \_\_\_\_\_ Email : \_\_\_\_\_  
Tel : (O) \_\_\_\_\_ (R) \_\_\_\_\_ HP : \_\_\_\_\_

## Refundable Deposits

Cash / Nets / Cheque / Visa / MC Card No : \_\_\_\_\_



Vehicle No 3H4431  
Mileage Out : \_\_\_\_\_  
Make & Model Mitsubishi Lancer  
☒ Auto ☐ Manual  
Date : \_\_\_\_\_  
HIRE EXPIRY : \_\_\_\_\_

RENTAL CHARGE	AMOUNT
Daily @ \$ <u>150</u>	
Weekly @ \$	
Hours @ \$	
Others @ \$	
CDW @ \$	
PAI @ \$	
Delivery Service	
<b>SUB - TOTAL</b>	
Extension	
Collection Service	
Misc	
Estimated Total Rental \$	

Hirer is responsible for the first \$ \_\_\_\_\_ excess for collision / damage to first party. SAT MOTORS vehicle (including windscreen) and also first \$ \_\_\_\_\_ excess for collision / damage to third party's vehicle for each every accident / damage.

Hirer's Signature \_\_\_\_\_  
Hirer agrees not to SMOKE in the vehicle and not use it in any ILLEGAL ACTIVITIES.

I / We agree to the terms and conditions above. Overleaf and that all information given is true & correct in all respect.  
My / Our Driving license (s) is / are current and not disqualified from driving. You may charge all amount due in the rental to my / our credit card.

## IMPORTANT

- ONLY PERSONS ABOVE 26 YEAR OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVING OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY SAT MOTORS.
- IN THE EVENT OF AN ACCIDENTS, THE HIRER OR AUTHORISED DRIVER:
  - shall report all accident involving the said vehicle to the Owner immediately.
  - shall take immediate steps to complete and sign. From Mar 1 (Motor Accident Report Form) and do all other acts required in compliance with the "NON-INJURY MOTOR ACCIDENT REPORT SCHEME" (the form will be made available when the accident is reported to the owner.
  - shall report to the police within 24 hours from the occurrence. The following types of accidents -
    - injury case;
    - non-injury case involving a Government vehicle of damage to Government property
    - non-injury case involving a foreign vehicle (to obtain their motor insurance policy, Passport No. / Name
    - non-injury case involving a pedestrian or cyclist.

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN THE COLUMN SIGNATURE OF HIRER / DRIVER FILING WHICH THE DAY AND THE TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND THE TIME THE VEHICLE IS RETURNED TO SAT MOTORS AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN TIME IN MILEAGE CHECK BY REMARK DEPOSIT REFUND

SIGNATURE OF HIRER/DRIVER

**Enquire Vehicle & Owner Information ( Vehicle No. SJY5121B As At 13 Aug 2015 / 18:00:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CY.7607.15.SAT.WP(LH)

**Current Owner Details**

Owner ID Type: Company

Owner ID: 200415559G

Owner Name: POLYTECH COMPONENT PTE. LTD.

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 10

Registered Street Name: UBI CRESCENT

Registered Unit No.: # 04 - 68

Registered Building Name: UBI TECHPARK

Registered Postal Code: 408564

**Current Vehicle Details**

Vehicle No.: SJY5121B

Make Description/Model: AUDI / Q5 2.0L TFSI QU (PANORAMIC ROOF)

Insurance Company Name: AXA INSURANCE SINGAPORE PTE LTD



Please read through the Privacy Statement, Terms of Use and Disclaimer.  
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.  
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution  
Copyright © 2015 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

Your Ref: 16.22060.S.CK.xy

Date: 13<sup>th</sup> June 2018

Our Ref: CS1/LAW18007911/Usbe2

**M/s SEAH ONG & PARTNERS LLP**

36 Robinson Road  
#12-03 City House  
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SGT 2635S**

**INSURED VEHICLE: SJY 5121B**

**ACCIDENT DATE: 13/08/2015**

We thank you for your instruction on 30/04/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGT 2635S from M/s RW Automotive Appraisers Services.
- b) Survey report by RW Automotive Appraisers Services.
- c) Final Repair Bill of SGT 2635S from M/s Sat Motors.
- d) Singapore Accident Statement of Vehicles SGT 2635S.
- e) Colour damaged vehicle photographs of SGT 2635S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SGT 2635S
Make & Model	: Suzuki Swift
Year of Registration	: 2007
Chassis Number	: JSAEZC31S00101665
Engine Capacity	: 1586 cc

2. We recommend that the repairs of the entire damage require about 22 (Twenty Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 2635S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
2	REAR NUMBER PLATE LAMPS	NOT NECESSARY	83.60	-
1	REAR BUMPER	DISTORTED	605.00	605.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE HOLDERS	BENT	70.20	70.20
1	REAR BUMPER LOWER GARNISH	TORN	411.10	411.10
2	REAR BUMPER LOWER GARNISH LAMPS	CRACKED	242.00	242.00
1	REAR BUMPER IMPACT BRACKET RH	BENT	47.20	47.20
1	REAR END PANEL	BADLY DENTED	305.00	305.00
1	REAR END PANEL TOP GARNISH	TWISTED	73.40	73.40
2	REAR TAIL LAMPS	N/S NOT NECESSARY / O/S BROKEN	579.40	289.70
1	REAR TAIL LAMP PANEL RH	DENTED	114.50	114.50
1	REAR TAIL GATE	DENTED	580.20	580.20
1	REAR TAIL GATE LOCK	TWISTED	149.50	149.50
1	REAR TAIL GATE WEATHERSTRIPE	CUT	76.60	76.60
1	REAR TAIL GATE OUTER HANDLE	NOT NECESSARY	78.60	-
1	REAR TAIL GATE INNER TRIM	CRACKED	172.20	172.20
1	SET REAR TAIL GATE INNER TRIM CLIPS	NECESSARY	50.00	50.00
2	REAR TAIL GATE DAMPERS	NOT NECESSARY	257.20	-
1	REAR TAIL GATE GLASS MOULDING	NECESSARY	100.20	100.20
1	REAR 'SUZUKI' LOGO	NECESSARY	25.30	25.30
1	REAR 'SUZUKI' WORDING	NECESSARY	23.40	23.40
1	REAR 'SWIFT' WORDING	NECESSARY	25.90	25.90
1	REAR 'SPORTS' EMBLEM	NECESSARY	22.80	22.80
1	REAR FENDER RH	DISTORTED	380.70	380.70
1	REAR FENDER INNER SHIELD RH	TORN	76.50	76.50
1	SET REAR FENDER INNER SHIELD CLIPS RH	NECESSARY	25.00	25.00
1	REAR FENDER INNER TRIM RH	TORN	110.60	110.60
1	SET REAR FENDER INNER TRIM CLIPS RH	NECESSARY	30.00	30.00
1	REAR FENDER WHEELHOUSE RH	DENTED	346.00	346.00

Report Ref No. CS1/LAW18007911/Usbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	589.50	-
1	REAR SPARE TYRE PANEL TOP BOARD	TORN	220.60	220.60
1	REAR DOOR RH	TO REPAIR SEE LABOUR	575.10	-
1	REAR DOOR LOCK RH	NOT NECESSARY	152.50	-
1	REAR DOOR WEATHERSTRIP RH	NOT NECESSARY	89.70	-
2	ROOF PANEL MOULDINGS	NECESSARY	310.00	310.00
1	REAR AXLE	TO REPAIR SEE LABOUR	812.10	-
1	REAR WHEEL HUB	BENT	179.00	179.00
1	REAR SHOCK ABSORBER RH	BENT	277.50	277.50
1	REAR EXHAUST PIPE	BENT	579.30	579.30
4	REAR EXHAUST MOUNTINGS	NECESSARY	112.00	112.00
1	FRONT BUMPER	TORN	518.70	518.70
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
2	FRONT BUMPER SIDE HOLDERS	NECESSARY	58.40	58.40
1	FRONT BUMPER TOW COVER	MISSING	24.30	24.30
1	FRONT BUMPER LOWER GRILLE	TORN	124.40	124.40
2	FRONT BUMPER FOG LAMPS	CRACKED	438.40	438.40
2	FRONT BUMPER FOG LAMP COVERS	CRACKED	118.60	118.60
2	FRONT BUMPER LOWER SIDE GARNISHES	CRACKED	312.20	312.20
1	FRONT BUMPER REINFORCEMENT UPPER	DISTORTED	143.70	143.70
1	FRONT BUMPER REINFORCEMENT COVER UPPER	DISTORTED	76.70	76.70
1	FRONT BUMPER REINFORCEMENT LOWER	DISTORTED	125.70	125.70
1	FRONT BUMPER REINFORCEMENT COVER LOWER	DISTORTED	76.70	76.70
1	FRONT BUMPER UNDERCOVER	TORN	86.10	86.10
1	FRONT GRILLE	BENT	171.20	171.20
1	FRONT GRILLE LOGO	NECESSARY	23.20	23.20
2	FRONT HEADLAMP	CRACKED	772.00	772.00
1	FRONT BONNET	BUCKLED	473.80	473.80
1	FRONT BONNET LOCK	TWISTED	68.60	68.60
1	FRONT BONNET WEATHERSTRIPE	NECESSARY	26.10	26.10
2	FRONT BONNET HINGES	BENT	57.80	57.80

Report Ref No. CS1/LAW18007911/Usbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BONNET INSULATOR	DEFORMED	112.80	112.80
1	SET FRONT BONNET INSULATOR CLIPS	NECESSARY	50.00	50.00
2	FRONT FENDERS	TO REPAIR SEE LABOUR	560.20	-
2	FRONT VVT EMBLEMS	NECESSARY	55.20	55.20
1	FRONT SUPPORT PANEL	BENT	551.50	551.50
1	AIRDUCT	TWISTED	89.00	89.00
1	ENGINE TOP COVER	CRACKED	268.30	268.30
1	WIPER WASHER TANK NECK	DEFORMED	42.10	42.10
1	AIR CON CONDENSER	BENT	471.70	471.70
2	AIR CON CONDENSER BRACKETS	BENT	31.00	31.00
1	FRONT RADIATOR	BENT	632.40	632.40
2	FRONT RADIATOR TOP BRACKETS	BENT	32.40	32.40
1	FRONT RADIATOR FAN COWLING	DENTED	117.20	117.20
1	FRONT RADIATOR FAN BLADE	BENT	55.40	55.40
1	FRONT RADIATOR FAN MOTOR	JAMMED	352.20	352.20
1	FRONT RADIATOR SIDE COVER	DISTORTED	37.60	37.60
1	SET FRONT RADIATOR SIDE COVER CLIPS	NECESSARY	20.00	20.00
1	AIR CON DISCHARGE PIPE	NOT NECESSARY	85.70	-
1	AIR CON SUCTION PIPE	NOT NECESSARY	115.70	-
1	AIR CON LIQUID PIPE	NOT NECESSARY	155.60	-
1	FRONT EXHAUST HEAT SHIELD	TO REPAIR SEE LABOUR	59.90	-
	LESS 5% DISCOUNT		-832.60	-637.34
			15,819.30	12,109.46
	<b>SPECIAL NETT ITEMS</b>			
1	REAR NUMBER PLATE (SN)	CRACKED	30.00	30.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	50.00
1	REAR REVERSE SENSORS (SN)	SHORTED	350.00	200.00
1	REAR TAIL GATE GLASS SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR SPARE TYRE PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	REAR SPARE TYRE PANEL INSULATION PAD (SN)	NECESSARY	250.00	120.00
1	REAR DOOR VISOR RH (SN)	NOT NECESSARY	80.00	-

Report Ref No. CS1/LAW18007911/Usbe2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TYRE RH (SN) (50%)	CUT	250.00	125.00
1	REAR WHEEL RIM RH (SN)	NOT NECESSARY	550.00	-
1	FRONT NUMBER PLATE (SN)	BROKEN	30.00	20.00
1	FRONT NUMBER PLATE HOLDER (SN)	BROKEN	30.00	20.00
			1,790.00	605.00
	<b>LABOUR</b>			
	REMOVE AND INSTALL AIR COND CONDENSER AND RECHARGE GAS (134A). }		150.00	100.00
	REMOVE AND REINSTALL FRONT RADIATOR ASSY AND CONDUCT PRESSURE TEST. }		120.00	-
	CUT OUT, REPLACE AND WELD REAR END PANEL, REAR RIGHT WHEEL HOUSE PANEL, REAR RIGHT TAIL LAMP PANEL, REAR RIGHT FENDER, REAR SPARE TYRE PANEL AND FRONT SUPPORT PANEL. PANEL BEAT REAR LEFT FENDER AND ROOF TOP PANEL. STRAIGHTEN FRONT CHASSISES AND REAR RIGHT CHASSIS. REMOVE AND REPLACE ALL DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL, REAR DOOR RH, REAR AXLE, FRONT FENDERS AND FRONT EXHAUST HEAT SHIELD.		4,000.00	2,200.00
	CHECK WIRING AND LIGHTINGS.		200.00	30.00
	REMOVE AND REINSTALL REAR WINDSCREEN GLASS.		150.00	120.00
	REMOVE AND REINSTALL REAR UPHOLSTERY AND CUSHION SEATS TO ENABLE REPAIR.		380.00	80.00
	REMOVE AND REINSTALL REAR RIGHT UNDERCARRIAGE.		380.00	150.00
	REMOVE AND REINSTALL REAR EXHAUST SILENCER.		150.00	80.00
	TRANSFER REAR TAIL GATE FITTINGS.		150.00	60.00
	TRANSFER REAR RIGHT DOOR FITTINGS.	NOT NECESSARY	150.00	-
	REMOVE AND REPLACE REAR REVERSE SENSORS.		100.00	50.00
	MOUNT VEHICLE ON MEASURING BENCH TO CORRECT CHASSIS ALIGNMENT.		380.00	300.00
	COMPUTERISE WHEEL ALIGNMENT.		150.00	60.00
	REMOVE AND REINSTALL FUEL TANK.		150.00	60.00
	REMOVE AND REINSTALL ROOF LINING TO ENABLE REPAIR.		180.00	150.00
	CONDUCT WATERPROOF TEST AFTER REPAIR.	NOT NECESSARY	120.00	-
	RUST PROOFING TREATMENT ON AFFECTED AREA.		400.00	150.00

Report Ref No. CS1/LAW18007911/Usbe2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING ON AFFECTED AREA.		3,000.00	1,800.00
	TOWING CHARGE.		120.00	100.00
			10,430.00	5,490.00
GRAND TOTAL			28,039.30	18,204.46
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				14,500.00

Report Ref No. CS1/LAW18007911/Usbe2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.