

ASS. REC. BY:

REF: CS/FCL18007931 / Tltbn2

Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person):

CWS Luene Jaw

of

FCL

Date/Time:

30/4/2018 5:57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 1871X

Insured:

SHC 836U

at Workshop m/s

Sin Sheng

Tel:

6863 9595

of

3 Tech Park Crescent Tuas Tech Park

Policy No:

Claim No:

D13003326MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/4/2018

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

30/4/2018

Person Contacted:

Susan

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBE 1871X - NA / AT 17009339 / K4

DA: 16/4/2018

SHC 836U - CS / FCL18004178 / Tld3

DA: 28/2/18

lump sum \$2000, 7 days (Red: 3538.21 ; 36%)


Signature: *Taufik*

REF: FCI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop no/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **GRE1871X** Yr Regn: **2015 Sep.**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Toyota Dyna 150** cc **2982.**
 Colour: **Red.** A/C Insured / Std / NI / NA
 Sp. Reading: **106270** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **JTFAT35Y20K204628.**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Modi: **NA** / S/Rim / STD A/Rim or
 Tyre Size: F: **195/R15**
 R: **155/R12**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: **Susan**
 Vehicle: IN / OUT

Front: _____ Rear: **6/L**
 R/Bal: **6** mm R/Bal: _____ mm
 L/Bal: **6** mm L/Bal: **6/L** mm
 D.O.A. _____ D.O.I: **30/4/18 @ 3pm**
 Survey held at: **Sin Sheng Two**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt N/S
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
w/p will email estimate

RECEIVED 24 MAY 2018

Date/Time File Pass to? Preli. Report
 Final Report

Days Of Repair: **7**
 Resurvey No. of Trip: **1**

2954
 Date/Time File Pass to?

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech Invt (\$)
 Weekend (\$)

Report Format: **TP**
 Lum Sum: **6200**

Survey Fee	170
Transportation	50
_____ + P.S. _____	
Photis	26

TOTAL	246

MOTOR SURVEY ASSIGNMENT

Date	27-04-2018	Our Ref No. D18003326MFSH
Accident Date	25-04-2018	Claim Type. Third Party
Insured Vehicle	SHC0836U	Third Party Vehicle. GBE1871X
Survey Location	3 TECH PARK CRESCENT TUAS TECH PARK	
Contact Person.	SUSAN	
Contact No.	68639595/ 68639595	Fax No. 68636477
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIN SHENG ENGINEERING SERVICES	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002465

Date : 30/04/2018

Vehicle Num. : GBE1871X

Make/Model : TOYOTA DYNA-2015

Chassis/Eng# : JTFAT35Y20K204628/1KD2497815

Accident Date : 25/04/2018

Claim No. : D18003326MFSH

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		LIST ITEMS :		
1.	1	FRONT BUMPER		610.70 <i>bt ✓</i>
2.	1	HEADLAMP, LHS		978.50 <i>cut ✓</i>
3.	1	HEADLAMP BEZEL		65.80 <i>X M ✓</i>
4.	1	CORNER PANEL, LHS		256.20 <i>bt ✓</i>
5.	1	FRONT GRILLE		417.50 <i>Rp ✓</i>
6.	2	STEP GARNISH	295.20 ✓	590.40 <i>LH-cut ✓, RH-X ✓</i>
7.	1	FRONT DOOR, LHS		1,749.00 <i>bt ✓</i>
8.	2	DOOR HINGE	105.20 ✓	210.40 <i>top x an, lower bt ✓</i>
9.	1	DOOR WEATHERSTRIP		172.40 <i>cut ✓</i>
10.	1	DOOR RADIATOR, LH		453.20 <i>X M ✓</i>
11.	1	DOOR LOCK		245.60 <i>X M ✓</i>
12.	1	LOWER ARM, LH		398.40 <i>bt ✓</i>
13.	1	LOWER ARM, RHS		398.40 <i>bt ✓</i>
14.	2	BALL JOINT	145.20	290.40 <i>bt ✓</i>
15.	1	ENGINE CROSSMEMBER BIG		2,236.85 <i>bt ✓</i>
16.	1	ANTIROLL BAR		353.20 <i>bt ✓</i>
		List Total S\$:	7844.45	9,426.95
		25.00% Discount S\$:		2,356.74
			5883.34	7,070.21
		NETT ITEMS :		
1.	1	COMPANY REGISTRATION STICKER		20.00 <i>net ✓</i>
		Nett Total S\$:		20.00
		10.00% Discount S\$:		2.00
				18.00 ✓

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002465

Date : 30/04/2018

Vehicle Num. : GBE1871X

Make/Model : TOYOTA DYNA-2015

Chassis/Eng# : JTFAT35Y20K204628/1KD2497815

Accident Date : 25/04/2018

Claim No. : D18003326MFSH

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		TO PANEL BEAT/REPAIR LH BODY	700	850.00
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
		SPRAY PAINTING	650	750.00
		TO APPLY NEW LOGO	100	150.00
		TO APPLY TUFF KOTE	50	100.00
		TO REPAIR UNDERCARRIAGE		
		ALIGNMENT SERVICES	300	650.00
		RECOVERY SERVICES	100	150.00
		LOSS OF USE : 9 DAYS @ \$ 120/DAY		
		Labour Total S\$:	1900	2,650.00
			7801.34	
			45\$ 6200*	
		Total S\$:		9,738.21

Susan

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7 days.

Tanjong 97495749.

3-14/18 @ 3pm

'wp'




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007931/T11bn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-05-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 836U	Veh. Inspected	GBE 1871X
Policy No.		Coverage (\$)	0.00
Claim No.	D18003326MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	30/04/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA 150	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTFAT35Y20K204628	Colour	RED
Odometer	106270	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	DUNLOP	6 mm
L/H Front Tyre	195 R15	DUNLOP	6 mm
R/H Rear Tyre	155 R12 (D)	DUNLOP	6/6 mm
L/H Rear Tyre	155 R12 (D)	DUNLOP	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/04/2018	Inspection Date	30/04/2018
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 1871X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BENT	610.70	610.70
1	HEADLAMP,LHS	CUT	978.50	978.50
1	HEADLAMP BEZEL	NOT NECESSARY	65.80	-
1	CORNER PANEL,LHS	BENT	256.20	256.20
1	FRONT GRILLE	TO REPAIR SEE LABOUR	417.50	-
2	STEP GARNISH @\$295.20	N/S CUT / O/S NOT NECESSARY	590.40	295.20
1	FRONT DOOR,LHS	BENT	1,749.00	1,749.00
2	DOOR HINGE @\$105.20	LOWER BENT / TOP NOT NECESSARY	210.40	105.20
1	DOOR WEATHERSTRIP	CUT	172.40	172.40
1	DOOR RADIATOR,LH	NOT NECESSARY	453.20	-
1	DOOR LOCK	NOT NECESSARY	245.60	-
1	LOWER ARM,LH	BENT	398.40	398.40
1	LOWER ARM,RHS	BENT	398.40	398.40
2	BALL JOINT @\$145.20	BENT	290.40	290.40
1	ENGINE CROSSMEMBER BIG	BENT	2,236.85	2,236.85
1	ANTIROLL BAR	BENT	353.20	353.20
	LESS 25% DISCOUNT		-2,356.74	-1,961.11
			7,070.21	5,883.34
NETT ITEMS				
1	COMPANY REGISTRATION STICKER (N)	NECESSARY	20.00	20.00
	LESS 10% DISCOUNT		-2.00	-2.00
			18.00	18.00
LABOUR				
	TO PANEL BEAT/REPAIR LH BODY.TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS.INCLUSIVE OF THE REPAIR OF FRONT GRILLE.		850.00	700.00
	SPRAY PAINTING.		750.00	650.00
	TO APPLY NEW LOGO.		150.00	100.00
	TO APPLY TUFF KOTE.		100.00	50.00

Report Ref No. CS/FCI18007931/T1tbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPAIR UNDERCARRIAGE ALIGNMENT SERVICES, RECOVERY SERVICES.		650.00	300.00
			150.00	100.00
			2,650.00	1,900.00
GRAND TOTAL			9,738.21	7,801.34
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,200.00

Report Ref No. CS/FC118007931/T1tbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.