

Surveyor: _____ REF: C83 / FWD 18001873 / Srb-1⁰²

Special Instruction: _____

From (Person): Clara Li of FWD Date/Time: 25/11/2018

Estimated Cost: _____ Bill to: _____

ASSIGNMENT (Office)

118: \$ 12200.00

Third Parties: _____

Claimant: _____

Surveyor: Constant Appraiser

Workshop: J.L Car Auto

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: GBB 8927P Insured: SFE 2231P

at Workshop m/s J.L Car Auto Tel: 6367 0790

of Blk 4 Kranji Loop #01-18

Policy No: _____ Claim No: 1201800001865-002

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 30012018

(Client's Record)

03052018 (Thursday) @ 11:30am

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 12 days)

Date/Time: 21/6/18 Submit Final Fig 9600, 9 days (Red \$ 2600 / 21 %; Original 12 days)

Date/Time	Action/Instruction
	GBB 8927P - C83 / FWD 18001873 / R1502
	SFE 2231P - C83 / FWD 18002829 / K103
	Submit TP Re-inspection via email.

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 21 JUN 2018

Para(3) : Nett Value

Market Value : _____	Inspected/ Evaluated by: _____	Fee Charged:	Date: 25/11/2018
Salvage Value : _____		Basic & Add	
Nett Value : _____		Transport	
1) Date/Time 21/6/18 File Pass to typist	2) Date/Time _____ File Return to _____	Photos	
3) Date/Time _____ File Pass to _____	4) Date/Time _____ File Return to _____	Others	
5) Date/Time _____ File Pass to _____	6) Date/Time _____ File Return to _____	Total	

Catherine Chong (LKK Auto)

From: clara.li@fwd.com
Sent: Wednesday, 25 April, 2018 3:25 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Subject: FW: [Request for Re-inspection] Your Ref: AM1-yly-Ins-J2-105722-18-er Our Ref: 1201800001865-002

Hi LKK team,

Please confirm the RI arrangement in the email below with TP lawyer.

Thank you.

Kind Regards

Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722
E clara.li@fwd.com
W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
--	--	---	--

From: Prestina Moh [mailto:prestina.moh@visionlawllc.com]
Sent: Wednesday, 25 April, 2018 2:27 PM
To: Clara Li Zirong - SGUser
Subject: RE: [Request for Re-inspection] Your Ref: AM1-yly-Ins-J2-105722-18-er Our Ref: 1201800001865-002

WITHOUT PREJUDICE

Our ref: AM1.yly.INS.J2.105722.18.pmv

Dear Sir/Mdm

We refer to your request for a re-inspection on our client's vehicle, **GBB 8927 P**.

Please be informed that the re-inspection as per your request has been arranged as follows:-

Date : 3 May 2018 (Thursday)

Time : At 11:30 a.m.
Venue : J.L. CAR AUTO SERVICE
Block 4 Kranji Loop
#01-18 Kranji Industrial Estate
Singapore 739540
Contact: Mr. Jason / Ms. Siew Lee (Tel: 6367 0790)

Accordingly, kindly ensure the attendance of your appointed surveyor at the above arranged re-inspection without fail.

Please let us have your written confirmation and the name and contact number of your appointed surveyor.

Regards,

Prestina Moh (Secretary)
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811 (Ext. 146)
Fax: 6535-6802

From: Yvonne Lim [<mailto:yvonnelim@visionlawllc.com>]
Sent: Wednesday, 25 April, 2018 2:25 PM
To: 'Prestina Moh'
Subject: FW: [Request for Re-inspection] Your Ref: AM1-ylv-Ins-J2-105722-18-er Our Ref: 1201800001865-002

From: clara.li@fwd.com [<mailto:clara.li@fwd.com>]
Sent: Tuesday, 3 April, 2018 11:55 AM
To: yvonnelim@visionlawllc.com
Cc: motorclaims.sg@fwd.com; assignments@lkkauto.com; sur@lkkauto.com
Subject: [Request for Re-inspection] Your Ref: AM1-ylv-Ins-J2-105722-18-er Our Ref: 1201800001865-002

WITHOUT PREJUDICE

Dear Yvonne,

We refer to the above matter.

We would like to conduct a physical re-inspection of your client's vehicle, GBB8927P.

Kindly assist with the necessary arrangement and revert to us at least 5 working days in advance.

In the meantime, kindly hold hands.

Thank you.

LKK team,

Please take note and liaise with Ms Yvonne for the physical re-inspection.

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg SAVE NOW
--	--	--	--

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Luxx Newhouse Pte Ltd
40 Sungei Kadut Street 2
Luxx Newhouse Design Centre
Singapore 729246

Date : 14/02/2018

Reference No : CAS/18-02/027

General Information

Registration No. : GBB 8927P
Accident Date : 30/01/2018

Particulars of Damaged Vehicle

Colour	: White	Make & Model	: Toyota Dyna 150 Manual
Engine Capacity	: 2982 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 331125	Engine No.	: 1KD2026285
Chassis No.	: JTFAT35Y70K201319	Steering	: In Order
Registration Date	: 16/08/2010	Brake	: In Order
		Undercarriage	: Affected

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	195R15	JOURNEY	90%
L/H Front Tyre	195R15	JOURNEY	90%
R/H Rear Tyre	155R12 (D)	HIFLY	90% / 90%
L/H Rear Tyre	155R12 (D)	JOURNEY	40% / 40%

Inspection

Repairer : J. L. Car Auto Service
Blk 4, Kranji Loop #01-18, Kranji Industrial Estate, Singapore 739540

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$18,549.14
Revised Amount : \$12,200.00
Less Excess : -
Nett Total : \$12,200.00

Remarks

- (A) Survey was done on 31/01/2018
- (B) Re-survey was done on 01/02/2018
- (C) Re-survey after repair was done on 12/02/2018
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : GBB 8927P

Our ref : CAS/18-02/027

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
<u>PARTS REPLACEMENT – LIST ITEMS</u>						
1	1pc	Front bumper	Dented/Twisted	481.60	481.60	✓ DIS
2	2pcs	Front bumper bracket @ \$98.00	Bent/Twisted <i>LY</i>	196.00	<i>98</i> 196.00	✓ BT
3	1pc	Front headlamp LH	Broken	1,015.34	1,015.34	✓ BR
4	1pc	Front headlamp lower rubber seal LH	Broken	22.00	22.00	✓ BR
5	1pc	Front headlamp socket LH	Broken	166.20	<i>R</i> 166.20	✓ BR
6	1pc	Front corner panel LH	Dented	376.50	<i>285</i> 376.50	✓ DD
7	1pc	Front grille	Broken	488.30	488.30	✓ CRK
8	1pc	Front panel	Dented/Warped	1,265.50	1,265.50	✓ DD
9	1pc	Front panel 'DYNA' emblem	Necessary	68.25	68.25	✓ CRK
10	1pc	Front panel top garnish LH	Grazed	107.40	107.40	✓ SCR
11	1pc	Front windscreen rubber	Necessary	303.60	303.60	✓ NEI
12	1pc	Front door LH	Dented/Buckled	1,568.30	1,568.30	✓ DM
13	1pc	Front door pillar LH	Dented/Twisted	711.50	711.50	<i>R</i> DD
14	1pc	Front door pillar inner member LH	Dented/Twisted	389.51	389.51	<i>R</i> DD
15	1pc	Front door weatherstrip LH	Torn	191.99	191.99	✓ NE
16	1pc	Front door arch rubber LH	Distorted	218.04	218.04	✓ NEI
17	1pc	Front door rubber stopper LH	Necessary	30.94	30.94	✓ NEI
18	1pc	Front door opening weatherstrip LH	Distorted	181.01	181.01	✓ CU
19	1pc	Front door glass run channel LH	Necessary	241.65	241.65	✓ NE
20	1pc	Front door hinge top LH	Bent	105.46	105.46	✓ BT
21	1pc	Front door hinge bottom LH	Bent	105.46	105.46	✓ BT
22	1pc	Front door check LH	Bent	77.65	77.65	✓ BT
23	1pc	Front door lock LH	Bent/Jammed	349.03	349.03	✓ BT
24	1pc	Front door board LH	Broken	657.34	657.34	✓ CRK
25	1pc	Front door glass regulator gear LH	Bent	393.07	393.07	✓ DM
26	1pc	Front door glass regulator motor LH	Jammed	678.04	678.04	✓ DM
27	1pc	Front wheel arch panel LH	Dented/Buckled	249.44	249.44	<i>R</i> DD
28	1pc	Front wheel arch panel top garnish LH	Deformed	139.84	139.84	✓ NEI
29	1pc	Front wheel arch inner side garnish LH	Deformed	99.70	99.70	✓ NEI
30	1pc	Aircon condenser	Dented/Twisted	1,261.30	1,261.30	✓ DT
31	1pc	Aircon condenser stay	Bent	381.60	381.60	✓ DT
32	1pc	Aircon condenser side bracket	Bent	91.50	91.50	✓ DT
33	1pc	Aircon aluminium pipe	Bent	162.75	162.75	✓ DT

Constant Appraiser Services

Vehicle No : GBB 8927P

Our ref : CAS/18-02/027

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
<u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u>						
34	1pc	Aircon electric fan assy	Broken	641.50	641.50	✓CRK
35	1pc	Aircon filter	Necessary	81.20	81.20	✓NEC
36	1pc	Front windscreen rubber	Necessary	303.60	303.60	X
37	1pc	Front shock absorber LH	Bent	114.77	114.77	✓DM
38	1pc	Front top arm LH	Serviceable	1,645.08	-	X
39	1pc	Front lower arm LH	Bent	987.16	987.16	✓OT
40	1pc	Front lower arm ball joint LH	Bent	250.93	250.93	✓NE
41	1pc	Front knuckle arm LH	Serviceable	799.60	-	X
42	1pc	Front step panel garnish LH	Broken	312.60	312.60	✓CRK
43	1pc	Front side mirror bracket assy	Repair	653.40	-	R
44	1pc	Front mirror garnish LH	Broken	165.20	165.20	✓BR
				18,730.85	15,632.77	
Less 25%				(4,682.71)	(3,908.19)	
Sub total				14,048.14	11,724.58	
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>						
1	1pc	Front tyre LH	Cut (90%)	280.00	252.00	✓CUT
2	1pc	Front door 'ROC' sticker LH	Necessary	50.00	45.00	✓NEC
3	1set	Front grille clip	Necessary	39.00	39.00	✓NEC
4	1set	Front door board clip	Necessary	42.00	42.00	✓NEC
5	1set	Front door 'corporate' sticker LH	Necessary	160.00	160.00	✓NEC
Sub total				14,619.14	12,262.58	
<u>LABOUR & MISC. CHARGES</u>						
1		To check all wiring & electrical component for proper function		50.00	50.00	30
2		Remove & reinstall dashboard, meter instruments, disconnect wiring & etc		280.00	250.00	200
3		Remove & reinstall windscreen glass to facilitate repairs & perform water test		120.00	80.00	✓
4		To remove, replace & transfer door panel, fitting & mechanism		100.00	70.00	60
5		To remove & refix aircon, refill aircon gas & test for leakage		140.00	120.00	100
6		Labour for panel beating, cut, weld, straighten & replacing parts etc		1,500.00	1,200.00	1000
7		To putty & spray painting & including touch up paint on accident affected area		1,500.00	1,000.00	800

Constant Appraiser Services

Vehicle No : GBB 8927P

Our ref : CAS/18-02/027

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>LABOUR & MISC. CHARGES (CONT'D)</u>			
8		To apply rust proofing, reseal tuff coating treatment on accident area		120.00	90.00 50
9		Check wheel alignment		120.00	100.00 60
		Grand total		18,549.14	15,222.58
Recommended cost of lump sum repair (To its pre-accident condition)					12,200.00

9 days

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$12,200.00** on a contractual basis. Under normal circumstances, the repair period would be about **12 (Twelve)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD			Ref : CS3/FWD18001873/Srbe2-1	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986			Date : 22-06-2018	
			Code : FWD	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SFE 2231P	Veh. Inspected	GBB 8927P	
Policy No.		Coverage (\$)	0.00	
Claim No.	1201800001865-002	Excess (\$)	0.00	
Assign From	CLARA LI	Assign Date	25/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JTFAT35Y70K201319	Colour	WHITE	
Odometer	339915	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	JOURNEY	6 mm	
L/H Front Tyre	195 R15C	JOURNEY	6 mm	
R/H Rear Tyre	155 R12C	JOURNEY	6 mm	
L/H Rear Tyre	155 R12C	JOURNEY	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	30/01/2018	Inspection Date	03/05/2018	
Survey held at	J.L.CAR AUTO SERVICE BLK 4 KRANJI LOOP #01-18 KRANJI INDUSTRIAL ESTATE SINGAPORE 739540			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 8927P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT MIRROR GARNISH LH	REPLACED	165.20	165.20
1	FRONT BUMPER	REPLACED	481.60	481.60
2	FRONT BUMPER BRACKET @\$98.00	N/S REPLACED	196.00	98.00
1	FRONT HEADLAMP LH	REPLACED	1,015.34	1,015.34
1	FRONT HEADLAMP LOWER RUBBER SEAL LH	REPLACED	22.00	22.00
1	FRONT HEADLAMP SOCKET LH	REPAIRED SEE LABOUR	166.20	-
1	FRONT CORNER PANEL LH	REPLACED	376.50	285.00
1	FRONT GRILLE	REPLACED	488.30	488.30
1	FRONT PANEL	REPLACED	1,265.50	1,265.50
1	FRONT PANEL 'DYNA' EMBLEM	REPLACED	68.25	68.25
1	FRONT PANEL TOP GARNISH LH	REPLACED	107.40	107.40
1	FRONT WINDSCREEN RUBBER	REPLACED	303.60	303.60
1	FRONT DOOR LH	REPLACED	1,568.30	1,568.30
1	FRONT DOOR PILLAR LH	REPAIRED SEE LABOUR	711.50	-
1	FRONT DOOR PILLAR INNER MEMBER LH	REPAIRED SEE LABOUR	389.51	-
1	FRONT DOOR WEATHERSTRIP LH	REPLACED	191.99	191.99
1	FRONT DOOR ARCH RUBBER LH	REPLACED	218.04	218.04
1	FRONT DOOR RUBBER STOPPER LH	REPLACED	30.94	30.94
1	FRONT DOOR OPENING WEATHERSTRIP LH	REPLACED	181.01	181.01
1	FRONT DOOR GLASS RUN CHANNEL LH	REPLACED	241.65	241.65
1	FRONT DOOR HINGE TOP LH	REPLACED	105.46	105.46
1	FRONT DOOR HINGE BOTTOM LH	REPLACED	105.46	105.46
1	FRONT DOOR CHECK LH	REPLACED	77.65	77.65
1	FRONT DOOR LOCK LH	REPLACED	349.03	349.03
1	FRONT DOOR BOARD LH	REPLACED	657.34	657.34
1	FRONT DOOR GLASS REGULATOR GEAR LH	REPLACED	393.07	393.07
1	FRONT DOOR GLASS REGULATOR MOTOR LH	NOT NECESSARY	678.04	-
1	FRONT WHEEL ARCH PANEL LH	REPAIRED SEE LABOUR	249.44	-

Report Ref No. CS3/FWD18001873/Srbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WHEEL ARCH PANEL TOP GARNISH LH	REPLACED	139.84	139.84
1	FRONT WHEEL ARCH INNER SIDE GARNISH LH	REPLACED	99.70	99.70
1	AIRCON CONDENSER	REPLACED	1,261.30	1,261.30
1	AIRCON CONDENSER TRAY	REPLACED	381.60	381.60
1	AIRCON CONDENSER SIDE BRACKET	REPLACED	91.50	91.50
1	AIRCON ALUMINIUM PIPE	REPLACED	162.75	162.75
1	AIRCON ELECTRIC FAN ASSY	REPLACED	641.50	641.50
1	AIRCON FILTER	REPLACED	81.20	81.20
1	FRONT WINDSCREEN RUBBER	REPEATED	303.60	-
1	FRONT SHOCK ABSORBER LH	NOT NECESSARY	114.77	-
1	FRONT TOP ARM LH	SERVICEABLE	1,645.08	-
1	FRONT LOWER ARM LH	REPLACED	987.16	987.16
1	FRONT LOWER ARM BALL JOINT LH	NOT NECESSARY	250.93	-
1	FRONT KNUCKLE ARM LH	SERVICEABLE	799.60	-
1	FRONT STEP PANEL GARNISH LH	REPLACED	312.60	312.60
1	FRONT SIDE MIRROR BRACKET ASSY	REPAIRED SEE LABOUR	653.40	-
	LESS 25% DISCOUNT		-4,682.71	-3,144.82
			14,048.14	9,434.46
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE LH (SN)	NOT NECESSARY	280.00	-
1	FRONT DOOR 'ROC' STICKER (SN)	REPLACED	50.00	25.00
1	SET FRONT GRILLE CLIP (SN)	REPLACED	39.00	25.00
1	SET FRONT DOOR BOARD CLIP (SN)	REPLACED	42.00	30.00
1	SET FRONT DOOR 'CORPORATE' STICKER LH (SN)	REPLACED	160.00	120.00
			571.00	200.00
	<u>LABOUR</u>			
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		50.00	30.00
	REMOVE & REINSTALL DASHBOARD, METER INSTRUMENTS, DISCONNECT WIRING & ETC.		280.00	200.00
	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS & PERFORM WATER TEST.		120.00	80.00

Report Ref No. CS3/FWD18001873/Srbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REPLACE & TRANSFER DOOR PANEL, FITTING & MECHANISM.		100.00	60.00
	TO REMOVE & REFIX AIRCON, REFILL AIRCON GAS & TEST FOR LEAKAGE.		140.00	100.00
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETC. INCLUSIVE OF THE REPAIR OF FRONT HEADLAMP SOCKET LH, FRONT DOOR PILLAR LH, FRONT DOOR PILLAR INNER MEMBER LH, FRONT WHEEL ARCH PANEL LH AND FRONT SIDE MIRROR BRACKET ASSY.		1,500.00	1,000.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA.		1,500.00	800.00
	TO APPLY RUST PROOFING, RESEAL TUFF COATING TREATMENT ON ACCIDENT AREA.		120.00	50.00
	CHECK WHEEL ALIGNMENT.		120.00	60.00
			3,930.00	2,380.00
GRAND TOTAL			18,549.14	12,014.46
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,600.00

Report Ref No. CS3/FWD18001873/Srbe2-1

YEANG WAI KEEN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.