

S. REC. BY:

REF: C3/CTU8007990/Kqbnz

Special Instruction:

SURVAYOR

Kenneth

ASSIGNMENT (Office)

From (Person):

Jocelyn Tay

of

CTL

Date/Time: 02052018 1:53pm

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 54626

Insured:

SBN 33H

at Workshop m/s

Hui Yang

Tel:

64515752

of

Blk 176 Sin Ming Drive #04-02

Policy No:

DMPCSN 3045591804

Claim No:

SNM18D 02267102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 28042018

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

02052018 2:29pm

Person Contacted:

Bel

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (☒) Estimate

SLH 54626 - x

SBN 33H - C3/AXA12033738/mjlv2

Df: 05/12/12

14/6 ✓ Rep 845501 email & confirm
(Red # 4336.09, 492)

ASS. REC. BY:

REF:

C721

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SUIT 59826 Yr Regn: 11, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or CA WagonMake: Toy Vellfire c.c. 2493Colour: M. Black A/C: Insured / Std / NI / NASp. Reading: 123042 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AG14 30 0048999Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: NII / S/Rim / STD / RIM orTyre Size: F: 235/50R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Westlake

Front

Rear

R/Bal. 9 mm R/Bal. 8 mmL/Bal. 9 mm L/Bal. 8 mmD.O.A. 28/4/18 D.O.I. 2/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/5 Pk pass to Catherine

RECEIVED 8 JUL 2018

Date/Time, File Pass to?

☐

: Prell. Report

1) 05/7/18

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

220

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

4550

辉 阳 汽 车 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

28/04/2018

Owner: EZGO LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA VELLFIRE - SLH5962G

1pc	rear tailgate	Rt	\$	1,956.25	✓
1pc	rear tailgate inner rubber	Sn	\$	374.45	X
1pc	rear tailgate LH inner rubber sensor	Sn	\$	591.60	X
1pc	rear taillamp LH lower garnish	Bul/Ln	\$	271.45	✓
1pc	rear taillamp LH lower garnish side retainer	D11	\$	132.25	✓
1pc	rear bumper	Bn	\$	1,711.10	✓
1pc	rear bumper LH side retainer 1	D11	\$	132.25	✓
1pc	rear bumper LH side retainer 2	D11	\$	141.45	✓
1pc	rear bumper LH side reflector	Cm	\$	174.25	✓
1pc	rear bumper LH towing cover	Sn	\$	43.70	X
1pc	rear bumper parking sensor wire	Cm	\$	371.45	✓
1pc	rear bumper LH side garnish	Ln	\$	274.75	X
1pc	rear end panel	R	\$	781.10	X
1pc	rear end panel LH side panel	R	\$	241.10	X
1pc	rear end panel LH side bracket	R	\$	131.35	X
1pc	rear LH fender inner garnish	Sn	\$	781.10	X
1pc	rear LH fender air duct	Cm	\$	95.85	✓
			\$	8,205.45	
	less 25%		\$	2,051.36	
	balance c/f		\$	6,154.09	
1set	rear windscreen glass moulding	net	\$	100.00	✓
1pc	rear bumper LH parking sensor	Cm	\$	380.00	✓
			\$	480.00	
	less 10%		\$	48.00	
			\$	432.00	
	remove & refit rear windscreen glass		\$	120.00	✓
	sealant		\$	80.00	✓
	wiring		\$	150.00	201
	tuffkote		\$	100.00	301
	spray painting		\$	900.00	8001
	labour charges		\$	950.00	500
	Total		\$	8,886.09	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Chin Epping
02/05/18 Wednesday

Not Authorized
11 Lm @ 4550p
Resurvey After Paint
5 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007970/KQBN2

Date: 09/07/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3045591804
Claimant Vehicle No :	SLH5962G	Insured Vehicle No :	SBN33H
Date of Loss:	28/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D02207C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH5962G	Engine No:	2ARH659954
Make & Model:	TOYOTA VELLFIRE, 3.5 G - Edition (A)	Chassis No:	AGH300048999
Reg. Date:	10/11/2016 (Man. Year: 2015)	Odometer:	123042 km
Colour:	Metallic Black		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	West Lake 9 mm	Rear Left Side:	West Lake 8 mm
Front Right Side:	West Lake 9 mm	Rear Right Side:	West Lake 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,666.09	4,211.72	2,454.37	36.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,470.00	750.00	33.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,886.09	5,681.72	3,204.37	36.06
Approved Total (Overridden) (\$\$)		4,550.00		
(\$\$)	8,886.09	4,550.00	4,336.09	48.80
+ GST 7.00/7.00% (\$\$)	622.03	318.50	303.53	48.80
Nett Amount (\$\$)	9,508.12	4,868.50	4,639.62	48.80

INSPECTION

Date of Assignment:	02/05/2018	
Date Inspected:	02/05/2018 Inspected At:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jul 2018)
Parts:	M1-MPV	TOYOTA VELLFIRE 3.5 G - Edition (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH5962G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,956.25 FL	*1,956.25 FL
2	1		*REAR TAILGATE INNER RUBBER	Serviceable	374.45 FL	*- FL
3	1		*REAR TAILGATE LH INNER RUBBER SENSOR	Serviceable	591.60 FL	*- FL
4	1		*REAR TAILLAMP LH LOWER GARNISH	Buckled/Cut	271.45 FL	*271.45 FL
5	1		*REAR TAILLAMP LH LOWER GARNISH SIDE RETAINER	Distorted	132.25 FL	*132.25 FL
6	1		*REAR BUMPER	Buckled	1,711.10 FL	*1,711.10 FL
7	1		*REAR BUMPER LH SIDE RETAINER 1	Distorted	132.25 FL	*132.25 FL
8	1		*REAR BUMPER LH SIDE RETAINER 2	Distorted	141.45 FL	*141.45 FL
9	1		*REAR BUMPER LH SIDE REFLECTOR	Cracked	174.25 FL	*174.25 FL
10	1		*REAR BUMPER LH TOWING COVER	Serviceable	43.70 FL	*- FL
11	1		*REAR BUMPER PARKING SENSOR WIRE	Cracked	371.45 FL	*371.45 FL
12	1		*REAR BUMPER LH SIDE GARNISH	Serviceable	274.75 FL	*- FL
13	1		*REAR END PANEL	Repair	781.10 FL	*- FL
14	1		*REAR END PANEL LH SIDE PANEL	Repair	241.10 FL	*- FL
15	1		*REAR END PANEL LH SIDE BRACKET	Repair	131.35 FL	*- FL
16	1		*REAR LH FENDER INNER GARNISH	Serviceable	781.10 FL	*- FL
17	1		*REAR LH FENDER AIR DUCT	Cracked	95.85 FL	*95.85 FL
18	1		*SET REAR WINDSCREEN GLASS MOULDING	Necessary	100.00 FN	*100.00 FN
19	1		*REAR BUMPER LH PARKING SENSOR	Cracked	380.00 FN	*380.00 FN
20	1		*SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	8,765.45	5,506.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,051.36	1,246.58
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	48.00	48.00
Total Parts (\$\$)	6,666.09	4,211.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
2	WIRING	New	150.00	20.00
3	TUFFKOTE	New	100.00	30.00
4	SPRAY PAINTING	New	900.00	800.00
5	LABOUR CHARGES	New	950.00	500.00
Gross Labour Cost (\$\$)			2,220.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >