

The insurer has given adjuster a maximum mandate of S\$0.00 to authorize directly on their behalf, but the adjuster has disabled direct offer mode.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18007988/M1SBE2
Date: 25/09/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3001681800
Claimant Vehicle No :	SGH1645H	Insured Vehicle No :	SLA535B
Date of Loss:	26/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D02219C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGH1645H	Engine No:	27186030369411
Make & Model:	MERCEDES-BENZ E200, 1.8 (A)	Chassis No:	WDD2120482A536253
Reg. Date:	01/02/2012 (Man. Year: 2011)	Odometer:	66725 km
Colour:	Brown		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	265/35 R18
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,814.91	7,610.12	1,204.79	13.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,220.00	6,140.00	1,080.00	14.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,034.91	13,750.12	2,284.79	14.25
+ GST 7.00/7.00% (S\$)	1,122.44	962.51	159.93	14.25
Nett Amount (S\$)	17,157.35	14,712.63	2,444.72	14.25

INSPECTION

Date of Assignment:	02/05/2018		
Date Inspected:	14/05/2018	Inspected At:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	8.0 days		

Adjuster: MA CHIN FOOK

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2018)
Parts:	143	MERCEDES-BENZ E200 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGH1645H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR CROSS MEMBER	Bent	789.45 FS	*789.45 FS
2	1		*RIGHT REAR BUMPER BOTTOM BRACKET	Bent	16.18 FS	*16.18 FS
3	1		*LEFT REAR BUMPER BOTTOM BRACKET	Bent	16.18 FS	*16.18 FS
4	4		*REAR PARKTRONIC SENSOR SPACER RING	Bent	27.72 FS	*27.72 FS
5	1		*REAR PARKING SENDER UNIT (4 PCS)	Shorted-3 pcs only	1,095.16 FS	*821.37 FS
6	1		*CENTRAL REAR BUMPER GARNISH MOULDING	Necessary	172.55 FS	*172.55 FS
7	1		*RIGHT REAR BUMPER GARNISH MOULDING	Necessary	128.17 FS	*128.17 FS
8	1		*LEFT REAR BUMPER GARNISH MOULDING	Necessary	128.17 FS	*128.17 FS
9	1		*REAR BUMPER	Dented	1,602.72 FS	*1,602.72 FS
10	2		*RUBBER STOPPER	Necessary	18.82 FS	*18.82 FS
11	1		*BOOT LID TYPE DESIGNATION EMBLEM	Necessary	75.34 FS	*75.34 FS
12	1		*BOOT LID E200 EMBLEM	Necessary	75.34 FS	*75.34 FS
13	1		*BOOT LID CHROME MOULDING	Necessary	113.13 FS	*113.13 FS
14	3		*MB STAR GROMMET	Necessary	6.69 FS	*6.69 FS
15	1		*BOOT LID MERCEDES STAR	Necessary	46.63 FS	*46.63 FS
16	1		*BOOT LID WEATHERSTRIP	Not Necessary	175.69 FS	*- FS
17	1		*BOOT LID HANDLE MOLDING	Dented	232.97 FS	*232.97 FS
18	1		*BOOT LID	Dented	2,709.70 FS	*2,709.70 FS
19	4		*RIVETED NUT	Necessary	14.64 FS	*14.64 FS
20	3		*PLUG	Necessary	2.76 FS	*2.76 FS
21	1		*LEFT TAIL LAMP	Scratched	611.59 FS	*611.59 FS
22	1		*TS TWO-COMPONENT ADHESIVE	Not Necessary	755.31 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **8,814.91** **7,610.12**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	2,400.00	1,920.00
2	RESPRAY BOOT LID AND REAR BUMPER	New	1,800.00	1,200.00
3	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
4	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
5	ADDITIONAL LABOUR TO REPAIR REAR END PANEL	New	1,440.00	1,440.00
6	ADDITIONAL LABOUR TO RESPRAY REAR END PANEL	New	600.00	600.00
7	ADDITIONAL LABOR TO REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS AND SEATS FOR NEC. REPAIRS.	New	480.00	480.00
Gross Labour Cost (S\$)			7,220.00	6,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >