

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18007989/AZ4BE2

Date: 09/07/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28910753MKC

Claimant Vehicle No : SKA9200U

Insured Vehicle No : GR6392B

Date of Loss: 28/04/2018

Nature of Claim: TP

Claim No: 557012

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA9200U**

Make &amp; Model: AUDI Q5, 3.2 FSI S-LINE QUATTRO D/AB HID (A)

Engine No: CAL080058

Reg. Date: 25/01/2011 (Man. Year: 2010)

Chassis No: WAUZZZ8R4BA062497

Colour: Brown

Odometer: 100615 km

Engine Capacity: 3197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 255/45 R20

Rear Tyre Size: 255/45 R20

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 11/06/2018

Date Inspected: 12/06/2018 Inspected At:

C.h.motor Vehicle Repair Training (HQ)

BLK 3019A UBI ROAD 1 #01-30

Singapore 408713

Estimated Period of Repair: 0.0 days

Adjuster: ADRIAN LING

Manager: Ho Zhao Tian

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,600.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 09 Jul 2018)

**Parts:**      M1-SUV      AUDI Q5 3.2 FSI S-LINE QUATTRO D/AB HID (A) (Catalogue:Merimen Singapore 1.0)

**Labour:**      Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SKA9200U)

**Validity:**      These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**