

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008016/T1TBE2

Date: 08/10/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29074028MKC

Claimant Vehicle No : YP3981T

Insured Vehicle No : GBC6070T

Date of Loss: 13/03/2018

Nature of Claim: TP

Claim No: 552670

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP3981T**

Make &amp; Model: ISUZU NMR85UH5A, 3.0 D (M)

Engine No: 4JJ12N6682

Reg. Date: 26/08/2016 (Man. Year: 2016)

Chassis No: JAANMR85HG7101771

Colour: Black

Odometer: 88406 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205 R16

Rear Tyre Size: 195/85 R16 (D)

Front Left Side: Continental 6 mm

Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Bridgestone 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	700.00	550.00	44.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,250.00</b>	<b>700.00</b>	<b>550.00</b>	<b>44.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	87.50	49.00	38.50	44.00
<b>Nett Amount (S\$)</b>	<b>1,337.50</b>	<b>749.00</b>	<b>588.50</b>	<b>44.00</b>

### INSPECTION

Date of Assignment: 02/05/2018

Date Inspected: 03/05/2018 Inspected At:

No. 4 Penjuru Close

Repairer : Aak Logistics Services Pte Ltd

(HQ)

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 08 Oct 2018)	
<b>Parts:</b>	N/A	ISUZU NMR85UH5A 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YP3981T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	650.00	300.00
2	SPRAY PAINT	New	500.00	300.00
3	LABOUR	New	100.00	100.00
<b>Gross Labour Cost (S\$)</b>			<b>1,250.00</b>	<b>700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >