

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46792
Date Estimated : 02/05/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Fiona Mary Ella Henderson
249 Holland Road

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 278599

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SKH6858E	VM22858	04/01/2013	135i-C(A)	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachment include knocking out dents caused by the accident	850.00		850.00 ✓
To respray front bumper	934.00		934.00 ✓
To replace LH bi xenon headlight include programming and conducting tests for proper function	451.00		451.00 ✓
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00 ✓
Sundries.	80.00		80.00 40

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
FRT BUMPER (M/HEADLAMP CLEANING) CRK	1,050.00	1.00		1,050.00
LH BI XENON HEADLIGHT SCR.	1,716.35	1.00		1,716.35

SUPPLEMENTARY ITEMS

Parts : \$ 2766.35
Labour : \$ 2425.00

5191.35 @ 3 days

Total Labour :	2,465.00
Total Parts :	2,766.35
Total Labour & Parts :	5,231.35
Deduction for Excess :	
Total Repair Costs less Excess:	5,231.35
GST @7%:	366.19
Grand Total :	5,597.54

2425.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Finalised by: Caroline DID: 63190174 Fax: 64794601