



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2825H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (CONSISTENT)	DEFORMED	580.00	580.00
1	SET REAR BUMPER CLIP (CONSISTENT)	NECESSARY	50.00	50.00
1	LEFT TAIL LAMP (CRACKED)	NOT CONSISTENT WITH THE IMPACT	720.00	-
1	THIRD BRAKE LAMP SPOILER (CRACKED)	NOT CONSISTENT WITH THE IMPACT	1,450.00	-
	LESS 25% DISCOUNT		-700.00	-157.50
			2,100.00	472.50
	<u>SPECIAL NETT ITEMS</u>			
1	'PRIME TAXI' STICKER (SN) (CONSISTENT)	NECESSARY	55.00	55.00
1	DIAL-A-CAB '6778 0808' STICKER (SN) (CONSISTENT)	NECESSARY	45.00	45.00
1	ANTI SLIP MAT (SN) (CONSISTENT)	NECESSARY	50.00	50.00
			150.00	150.00
	<u>LABOUR</u>			
	TO TUFF KOTE.		50.00	20.00
	TO REMOVE REAR BUMPER ,LEFT TAIL LAMP ,THIRD BRAKE LAMP SPOILER,KNOCK/WELDING TAIL GATE LOWER RIGHT & END PANEL .REPLACE LEFT TAIL LAMP ,REAR BUMPER & THIRD BRAKE LAMP SPOILER ,ALIGN & ADJUST REAR BUMPER .		850.00	300.00
	TO PUTTY ,RESPRAY PAINTING REAR BUMPER ,END PANEL & TAIL GATE .TO POLISH.		850.00	400.00
			1,750.00	720.00
GRAND TOTAL			4,000.00	1,342.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,050.00

Report Ref No. CC4/ASM18008043/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.