

INS CASE OWNER:

CC 4 / ASM1800

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

Is driver the owner?

(YES (X))

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s EMI.
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bail. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PCY3763 Yr Regn: JAN / 2002
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: SCANIA C.C. 8974
 Colour: MULTI A/C: Insured / Std / NI / NA
 Sp Reading: NO READING T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 154F4X20001840024
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 295/80/22'S
 R: mic.
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / QHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal: 8 mm R/Bal: 5 mm
 L/Bal: 8 mm L/Bal: 5 mm
 D.O.A. 27/04/2018 D.O.I. 4/5/2018
 Survey held at: _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S BODY
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/5/18 8.30 (RED) → 16/5/18 10.00 (67/0)

Date/Time: File Pass 10?

☐

Prel. Report

1)

Date/Time: File Return 10?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1) 3-PS, 3

1) Preco

1) 1000

TOTAL

Report Format:

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18008045/M1ua3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 02-05-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJS 191M	Veh. Inspected	PC 4376J	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00FLJ	Excess (\$)	0.00	
Assign From		Assign Date	02/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/04/2018	Inspection Date	04/05/2018	
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

1 1,800.00
 2 3,500.00 1,500.00
 3
 4 30.00
 5
 6 2,800.00
 7
 8 160.00
 9 185.00
 10
 11
 12
 13
 14
 15
 16
 17
 18
 19
 20
 21
 22
 23 325.00
 24

Total List Price	\$	-
Discount		25%
List Price (after Discount)	\$	-
Total Nett Price	\$	-
Discount		0%
Nett Price (after Discount)	\$	-
Total Special Nett	\$	6,970.00
Total Labour	\$	3,330.00
Grand Total	\$	10,300.00
Discount 20%		20%
Lump Sum Repair Cost	\$	8,240.00

\$ 8,250.00

Columns	
A	Serial No.
B	List Price
C	Nett Price
D	Special Nett
E	Labour

FILE NO. 1952

Vehicle No.
PC 4376J

DOA :
27.04.2018

Model No.
SCANIA

LOU -
7 W/DAYS

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: eml1autopteltd@gmail.com

COMPANY REG. NO. : 53105453E

Vehicle Number : PC 4376J

Date : 04.05.2018

Vehicle Model : SCANIA

Chassis : YS4K4X20001840024

Accident Date : 27.04.2018

TP Ins. AXA

Original Reg Date : 03.01.2002 (31.12.2021)

ESTIMATE

1	1 pc	Side Fiber Fender (Top) LH	X	X		\$ 4500	SN R
2	1 pc	Side Fiber Fender (Lower) LH	✓	X		\$ 3500	SN
3	1 pc	Side Fiber Fender Glass Moulding LH	X	X		\$ 300	SN
4	6 pcs	Side Fiber Fender Glass Inner Seal LH	X	X	@ 60	\$ 360	SN
5	6 pcs	Side Fiber Fender Glass Sealant LH	X	X	@ 60	\$ 360	SN
6	1 pc	Rear Wheel Arch Fiber Cover LH	✓	✓		\$ 2500	SN DD
7	2 pcs	Rear Wheel Arch Fiber Cover Hinge LH	X	X	@ 85	\$ 170	SN NN
8	1 pc	Rear Wheel Arch Fiber Cover Key Lock LH	✓	✓		\$ 160	SN
9	1 pc	Rear Wheel Arch Fiber Cover Lamp LH	✓	✓		\$ 155	SN
10	1 pc	Rear Bottom Side Gate LH	X	X		\$ 1800	SN
11	2 pcs	Rear Bottom Side Gate Hinge LH	X	X	@ 85	\$ 170	SN
12	1 pc	Rear Bottom Side Gate Key Lock LH	✓	✓		\$ 160	SN
13	2 set	Rear Bottom Side Gate Air Vent LH	X	X	@ 320	\$ 700	SN
14	1 pc	Taillamp LH (Bottom)	X	X		\$ 280	SN
15	1 pc	Taillamps Inner Sealer LH (Bottom)	X	X		\$ 40	SN
16	1 set	Taillamps Clip	X	X		\$ 20	SN
17	1 pc	Rear Bumper	X	X		\$ 1900	SN
18	2 pcs	Rear Bumper Side Bracket	X	X	@ 45	\$ 90	SN
19	1 pc	Side Skirt LH	✓	X		\$ 580	SN
20	1 pc	Rear Absorber LH	X	X		\$ 285	SN
21	1 pc	Rear Absorber Wheel Bearing with Hud LH	X	X		\$ 650	SN
22	1 pc	Side Sticker (Excursion Bus)	✓	X		\$ 40	SN
23	1 pc	Rear Tyre LH (Outer)	✓	✓	50%	\$ 650	SN 325
24	1 pc	Rear Rim LH (Outer)	X	X		\$ 450	SN NN

6810

Labour charge

Panel Beating	✓	1800	2,000.00
Spray painting - 2 tones	✓	1500	2,600.00
Anti rust	X	X	250.00
Check Wiring	✓	30	50.00
Remove and install side fender glass	X	X	800.00
Remove and install rear carrier	X	X	600.00
To check four wheel alignment	X	X	90.00

\$ 7,290.00

10,140 -
(2,028 -)

8,112 -

8,100

LKK Auto MA
Not Author
WSP Rep
7w days
4/5/2018
16/5/2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1005D
Vehicle Details	
Vehicle No.:	PC4376J
Vehicle to be Exported:	Yes
Intended De-registration Date:	04 May 2018
Vehicle Make:	SCANIA
Vehicle Model:	K94IB4X2
Primary Colour:	Multi-Colour
Manufacturing Year:	2001
Engine No.:	6010913
Chassis No.:	YS4K4X20001840024
Maximum Power Output:	-
Open Market Value:	\$107,586.00
Original Registration Date:	03 Jan 2002
First Registration Date:	03 Jan 2002
Transfer Count:	2
Actual ARF Paid:	\$5,380.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$35,466.00
COE Rebate Amount:	\$13,490.00
Total Rebate Amount:	\$13,490.00

The information contained herein is correct as at 04 May 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1005D
Vehicle Details	
Vehicle No.:	PC4376J
Vehicle to be Exported:	Yes
Intended De-registration Date:	04 May 2018
Vehicle Make:	SCANIA
Vehicle Model:	K94IB4X2
Primary Colour:	Multi-Colour
Manufacturing Year:	2001
Engine No.:	6010913
Chassis No.:	YS4K4X20001840024
Maximum Power Output:	-
Open Market Value:	\$107,586.00
Original Registration Date:	03 Jan 2002
First Registration Date:	03 Jan 2002
Transfer Count:	2
Actual ARF Paid:	\$5,380.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$35,466.00
COE Rebate Amount:	\$13,490.00
Total Rebate Amount:	\$13,490.00

The information contained herein is correct as at 04 May 2018

OK

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autotptd@gmail.com

COMPANY REG. NO. : 53105453E

Vehicle Number : PC 4376J

Vehicle Model : SCANIA

Accident Date : 27.04.2018

Original Reg Date : 03.01.2002 (31.12.2021)

Date : 04.05.2018

Chassis : Y54K4X20001840024

TP Ins. AXA

ESTIMATE

1	1 pc	Side Fiber Fender (Top) LH	X			SN
2	1 pc	Side Fiber Fender (Lower) LH	✓			SN
3	1 pc	Side Fiber Fender Glass Moulding LH	X			SN
4	6 pcs	Side Fiber Fender Glass Inner Seal LH	✓			SN
5	6 pcs	Side Fiber Fender Glass Sealant LH	✓			SN
6	1 pc	Rear Wheel Arch Fiber Cover LH	✓			SN
7	2 pcs	Rear Wheel Arch Fiber Cover Hinge LH	X		-	SN
8	1 pc	Rear Wheel Arch Fiber Cover Key Lock LH	✓			SN
9	1 pc	Rear Wheel Arch Fiber Cover Lamp LH	✓		-	SN
10	1 pc	Rear Bottom Side Gate LH	X		-	SN
11	2 pcs	Rear Bottom Side Gate Hinge LH	X			SN
12	1 pc	Rear Bottom Side Gate Key Lock LH	✓		-	SN
13	2 set	Rear Bottom Side Gate Air Vent LH	✓		-	SN
14	1 pc	Taillamp LH (Bottom)	✓		-	SN
15	1 pc	Taillamps Inner Sealer LH (Bottom)	✓		-	SN
16	1 set	Taillamps Clip	✓		-	SN
17	1 pc	Rear Bumper	✓			SN
18	2 pcs	Rear Bumper Side Bracket	✓		-	SN
19	1 pc	Side Skirt LH	✓			SN
20	1 pc	Rear Absorber LH	✓		-	SN
21	1 pc	Rear Absorber Wheel Bearing with Hud LH	X			SN
22	1 pc	Side Sticker (Excursion Bus)	✓			SN
23	1 pc	Rear Tyre LH (Outer)	wt	5070.	-	SN
24	1 pc	Rear Rim LH (Outer)	X			SN

Labour charge

Panel Beating	1800	3,000.00
Spray painting - 2 tones	1500.	2,500.00
Anti rust	X	250.00
Check Wiring	30	50.00
Remove and install side fender glass	X	800.00
Remove and install rear carrier	X	600.00
To check four wheel alignment	X	90.00

\$ 7,290.00



Service Request Details

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Claim

S8M00FLJ

Reference

None 

Loss Date

April 27, 2018

Request Date

May 1, 2018

Due Date

May 8, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

0205 2018 @ 11:25am
mr. chia veh not in
'Virtual'

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJS191M

Make

TPVD

Service Address

...

Primary Contact/Insured

TAY BUS TRANSPORT PTE. LTD.

BLK 22 SIN MING ROAD, #01-238 SIN MING VILLE, 570022, Singapore
63380083

Claim Handler

KHOR Saw Theng

6568804754

sawtheng.khor@axa.com.sg

Additional Instructions

1. Virtual case 2. TP excess: \$3,500= \$1,500 + \$2,000 (driving license < 1 year) 3. Please request ... (expand)

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18008045/M1ea3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Date : 30-04-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJS 191M	Veh. Inspected	PC 4376J	
Policy No.	P1946952	Coverage (\$)	0.00	
Claim No.	S8M00FRG	Excess (\$)	0.00	
Assign From		Assign Date	01/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	SCANIA	c.c	8974	
Engine No.	HIDDEN	Year of Reg.	2002	
Chassis No.	YS4K4X20001840024	Colour	MULTI COLOUR	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	MICHELIN	8 mm	
L/H Front Tyre	295/80 R22.5	MICHELIN	8 mm	
R/H Rear Tyre	295/80 R22.5	MICHELIN	5 mm	
L/H Rear Tyre	295/80 R22.5	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY, DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/04/2018	Inspection Date	04/05/2018	
Survey held at	EM-1 AUTO TRADE BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 4376J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SIDE FIBER FENDER (TOP) LH (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	4,500.00	-
1	SIDE FIBER FENDER (LOWER) LH (SN) (CONSISTENT)	DISTORTED	3,500.00	3,500.00
1	SIDE FIBER FENDER GLASS MOULDING LH (SN) (CONSISTENT)	NOT NECESSARY	300.00	-
6	SIDE FIBER FENDER GLASS INNER SEAL LH @\$60.00 (SN) (CONSISTENT)	NOT NECESSARY	360.00	-
6	SIDE FIBER FENDER GLASS SEALANR LH @\$60.00 (SN) (CONSISTENT)	NOT NECESSARY	360.00	-
1	REAR WHEEL ARCH FIBER COVER LH (SN) (CONSISTENT)	DENTED	2,800.00	2,800.00
2	REAR WHEEL ARCH FIBER COVER HINGE LH @\$85.00 (SN) (CONSISTENT)	NOT NECESSARY	170.00	-
1	REAR WHEEL ARCH FIBER COVER KEY LOCK LH (SN) (CONSISTENT)	BENT	160.00	160.00
1	REAR WHEEL ARCH FIBER COVER LAMP LH (SN) (CONSISTENT)	CUT	185.00	185.00
1	REAR BOTTOM SIDE GATE LH (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	1,800.00	-
2	REAR BOTTOM SIDE GATE HINGE LH @\$85.00 (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	170.00	-
1	REAR BOTTOM SIDE GATE KEY LOCK LH (SN) (CONSISTENT)	SERVICEABLE	160.00	-
2	SET REAR BOTTOM SIDE GATE AIR VENT LH @\$350.00 (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	700.00	-
1	TAILLAMP LH (BOTTOM) (SN) (CONSISTENT)	NOT NECESSARY	280.00	-
1	TAILLAMPS INNER SEALER LH (BOTTOM) (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
1	SET TAILLAMP CLIP (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	REAR BUMPER (SN) (CONSISTENT)	NOT NECESSARY	1,900.00	-
2	REAR BUMPER SIDE BRACKET @\$45.00 (SN) (CONSISTENT)	NOT NECESSARY	90.00	-
1	SIDE SKIRT LH (SN) (CONSISTENT)	NOT NECESSARY	580.00	-
1	REAR ABSORBER LH (SN) (CONSISTENT)	NOT NECESSARY	285.00	-
1	REAR ABSORBER WHEEL BEARING WITH HUB LH (SN) (CONSISTENT)	NOT NECESSARY	650.00	-

Report Ref No. CC4/ASM18008045/M1ea3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SIDE STICKER (EXCURSION BUS) (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
1	REAR TYRE LH (OUTER)(SN) (CONSISTENT) (50%)	CUT	650.00	325.00
1	REAR RIM LH (OUTER) (SN) (CONSISTENT)	NOT NECESSARY	450.00	-
			20,150.00	6,970.00
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF SIDE FIBER FENDER (TOP) LH,REAR BOTTOM SIDE GATE LH,REAR BOTTOM SIDE GATE HINGE LH AND SET REAR BOTTOM SIDE GATE AIR VENT LH .		3,000.00	1,800.00
	SPRAY PAINTING -2 TONES.		2,500.00	1,500.00
	ANTI RUST.	NOT NECESSARY	250.00	-
	CHECK WIRING.		50.00	30.00
	REMOVE AND INSTALL SIDE FENDER GLASS.	NOT NECESSARY	800.00	-
	REMOVE AND INSTALL REAR CARRIER.	NOT NECESSARY	600.00	-
	TO CHECK FOUR WHEEL ALIGNMENT.	NOT NECESSARY	90.00	-
			7,290.00	3,330.00
GRAND TOTAL			27,440.00	10,300.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,250.00

Report Ref No. CC4/ASM18008045/M1ea3q2

MA CHIN FOOK

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.