PR: 422/2018



VEHICLE MECHANICAL INSPECTION REPORT

Vehicle Registration Number:	Date of Inspection:
SJH 4639 X	29/1/2018
Type/ Make/ Colour: Honda Fit, Yellow Color, Hatch-back off-peak car	Place of Inspection: TP Vehicle Pound, 517 Airport Road
Referred by:	Inspected by:
IO T12 0132 Khairil Kamal	Principal Technical Officer, Lim Chwee Hai

A) Steering System			Remarks/ Observation
1	Steering Column and Shaft	Serviceable	Steering system in working condition.
2	Steering Tie Rod	Serviceable	
3	Steering Lower Arm	Serviceable	

B) Brake System			Remarks/ Observation	
1	Hand Brake Lever	Serviceable	Hand Brake system in working condition	
2	Brake Pedal	Serviceable	Brake system in working condition	
3	Master Pump and Reservoir	Serviceable	has physical durings touch	
4	Brake Hoses and Pipes	Secured	No physical dismage found.	

C) Engine & Transmission System			Remarks/ Observation	
1	Clutch Pedal	NA	Auto-transmission	
2	Gear Lever	Serviceable		
3	Accelerator Cable and Return Spring	Serviceable	No provide the rest found	

PR: 422/2018



VEHICLE MECHANICAL INSPECTION REPORT

D) Vehicle Interior			Remarks/ Observation	
1	Driver Side Airbags Deployed?	Serviceable	Not Activated	
2	Passenger Airbags Deployed?	Serviceable	Not Activated	
3	Driver's Seat Belt Condition	Serviceable	20 (50)	
4	Passenger's Seat Belt Condition	Serviceable	Trans 10 par	

E)	Lighting System	Jack Hiller 17	Remarks/ Observation		
1	Were the Lights Yes/ No* able to switch on at time of No inspection?		(U Detailer Data, and Talla – political trans-		
2	Front headlight	Left Headlight:	No physical damage found		
		Right Headlight:	No physical damage found		
3	Signal Lights	Front Left:	No physical damage found		
	Learner from the	Front Right:	No physical damage found		
		Rear Left:	No physical damage found		
	eviterios and hallefo	Rear Right:	No physical damage found		
4	Rear Lights	Rear Left:	No physical damage found		
		Rear Right:	No physical damage found		
5	Brake Lights		No physical damage found		
6	Reverse Lights		No physical damage found		

PR: 422/2018



VEHICLE MECHANICAL INSPECTION REPORT

Pypu	Make/ Brand	Tyre Markings	Tread Depth	Tyre Pressure	Remarks/ Observation
Front Left Tyre	LingLong Green-Max	205/40R17 84W	6 mm	30 psi	Don, Lin Chwer Ap
Front Right Tyre	LingLong Green-Max	205/40R17 84W	7 mm	28 psi	Ikin
Rear Left Tyre	LingLong Green-Max	205/40R17 84W	8 mm	30 psi	
Rear Right Tyre	LingLong Green-Max	205/40R17 84W	8 mm	30 psi	

Tread Condition: (a) 2mm or more= serviceable (b) between 2mm and 1mm = poor (c) Less than 1 mm = bald

G) Declaration

The inspection was carried out without dismantling any of the vehicle parts or components.

2. I declare that this report (consisting of 3 pages), is true to the best of my knowledge and belief and I make it knowing that, if it is given in evidence, I will be liable to prosecution if I have wilfully stated anything which I knew to be false or did not believe to be true.

Lim Chwee Hai Principal Technical Officer Investigation Branch, TP