

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	 5	FRONT RADIATOR COOLANT	Reviewing	40	NECESSARY	
☐	 6	FRONT RIGHT FENDER INNER COWLING CLIPS	Reviewing	0	NOT NECESSARY	
☐	 7	FRONT LEFT FENDER INNER COWLING CLIPS	Reviewing	0	NOT NECESSARY	
☐	 8	FRONT LEFT LED LAMP	Reviewing	0	NOT NECESSARY	
☐	 9	FRONT RIGHT LED LAMP	Reviewing	0	NOT NECESSARY	
☐	 10	FRONT SUPPORT PANEL TOP GARNISH CLIPS	Reviewing	15	NECESSARY	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	37	1			FRONT RADIATOR LEFT SIDE SIR DEFLECTOR			Serviceable	0		25		0
	38	1			FRONT RADIATOR RIGHT SIDE AIR DEFLECTOR			Serviceable	0		25		0
Labour													
EDIT	SR NO	REPAIR/REPLACE (LABOUR)			PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)		COMMENT		
	1				LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS.	800	0	0		0	Reviewing		
	2				TO PUTTY AND SPRAY PAINTING FRONT PORTION.	1000	0	0		0	Reviewing		
	3				TO CHECK WIRING AND FOCUS FRONT HEADLAMP.	30	0	0		0	Reviewing		
	4				TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM.	0	0	0		0	Reviewing		
	5				TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA.	0	0	0		0	Reviewing		
	6				TO REMOVE AND INSTALL AIR CON SYSTEM TO FACILITATE THE REPAIR AND REFILL GAS.	60	0	0		0	Reviewing		
	7				TO REMOVE AND INSTALL COOLING SYSTEM TO FACILITATE THE REPAIR AND CHECK FOR LEAKAGE.	60	0	0		0	Reviewing		
	8				TOWING SERVICE.	60	0	0		0	Reviewing		

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	11	1			FRONT BONNET LOCK MECHANISM			Damaged	90.1		25		67.58
	12	2			FRONT BONNET HINGES			Serviceable	0		25		0
	13	1			FRONT BONNET INSULATOR			Serviceable	0		25		0
	14	2			FRONT BONNET RUBBER STOPPER			Serviceable	0		25		0
	15	1			FRONT BONNET LOCK BRACE PANEL			Bent	127.1		25		95.33
	16	1			FRONT SUPPORT PANEL			Repair	0		25		0
	17	4			FRONT SUPPORT PANEL RUBBER STOPPER			Serviceable	0		25		0
	18	1			FRONT SUPPORT PANEL TOP GARNISH			Deformed	149.2		25		111.9
	19	1			FRONT LEFT FENDER ASSY			Repair	0		25		0
	20	1			FRONT RIGHT FENDER ASSY			Repair	0		25		0
	21	1			FRONT LEFT FENDER LAMP			Serviceable	0		25		0
	22	1			FRONT LEFT FENDER INNER COWLING			Serviceable	0		25		0
	23	1			FRONT RIGHT FENDER LAMP			Serviceable	0		25		0

Yes No

Detailed Assessment

Inspection Date *

05/03/2018



Condition of Vehicle at time of survey

General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

800

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/45R17

Rear Tyre Size

225/45R17

FNOL INFORMATI... BLK 665A PUNGGOL DRIVE, #06-506,
821665, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Residential

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Female

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Married

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7516300B

CATEGORY	POST SURVEY INF...	
CATEGORY	Date of Birth	
FNOL INFORMATI...	June 9, 1975	
POST SURVEY INF...		
CATEGORY	Age	
FNOL INFORMATI...	42	
POST SURVEY INF...		
CATEGORY	Occupation	
FNOL INFORMATI...	Unknown	
POST SURVEY INF...		
CATEGORY	Education Qualification	
FNOL INFORMATI...	Other	
POST SURVEY INF...		

CATEGORY	Make	
POLICY INFORMAT...	TOYOTA	
ASSESSMENT INFO...		
CATEGORY	Model	
POLICY INFORMAT...	WISH 2.0	
ASSESSMENT INFO...		
CATEGORY	Type	
POLICY INFORMAT...		
ASSESSMENT INFO...		
CATEGORY	Type of Paint	
POLICY INFORMAT...		
ASSESSMENT INFO...		
CATEGORY	Chassis No	
POLICY INFORMAT...	JTDGJ20WX05001333	

Accelerated
workshop survey

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Messages Invoices History Documents
Assessment Metrics Notes [Add](#)

Additional Instructions

EXCESS \$300+\$500(UNNAMED)=\$800

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	6/7/18 2:44 PM	5100	5100	Open	Share	Clone
TEO Kitty	5/3/18 10:26 AM	6587.04	6587.04	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
SJY3891A POLICY.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	May 4, 2018
GIA REPORT OF SLR2525C (TP).pdf	Reports & Statement	GIA Report	KADRI Mateen	May 2, 2018
GA019082-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	TEO Kitty	May 2, 2018
EMAIL.msg	Letters and Correspondence	Others	KADRI Mateen	May 2, 2018

Accelerated
workshop survey

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes
- Document Type

Additional Instructions

EXCESS \$300+\$500(UNNAMED)=\$800

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (OD)	June 7, 2018
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (OD)	June 7, 2018