

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7116T

MAKE :

MODEL : HYUNDAI i40

DATE 5/2/2018 15:47

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X Rep</i>			\$ 1,052.20
	Front Bumper Bracket Top (LH) <i>X</i>			\$ 22.40
	Front Bumper Side Bracket (LH) <i>X</i>			\$ 14.30
	<i>Front (RH) Fender X Rep</i>			
	SUB TOTAL			\$ 1,088.90
	LESS 20%			\$ 217.78
	DISCOUNTED TOTAL			\$ 871.12
	Labour Charge			
	Panel Beating			\$ 250.00 <i>200</i>
	Spray Painting Charge (Fender/Bumper)			\$ 400.00 <i>360</i>
	Tuff Kote			\$ 50.00 <i>X</i>
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$ 1,571.12
<p><i>Kalvin LKK</i></p> <p><i>2/5/18 1535hr</i></p> <p><i>2 Rep</i></p> <p><i>P/P</i></p> <p><i>After Repair photo</i></p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged parts during survey • Parts prices are subject to cost • Third party on a "No Fault" basis • No illegal advice is allowed • Supplement any item at the discretion of the Surveyor • is subject to final from Insurance Co. <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> <p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

LKK/kalvin

pbyP

CHINA

Like