

ASS. REC. BY:

REF: CS/MSH/8008116/Asbn2

Special Instruction:

SURVIVOR

Action

ASSIGNMENT (Office)

Mumun

From (Person):

Chh'ia Nyuk Pui

of

MSH

Date/Time:

03/05/2018 1:30pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

ABC 1393U

Insured:

GBE 785T

at Workshop m/s

Premium Carz

Tel:

6636 9100

of

Blk 1 Kaki Bukit Ave 6 #01-90

Policy No:

29066577MKF

Claim No:

557214

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30042018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

03/05/2018 1:36pm

Person Contacted:

Aun Teng

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBX 1393U - CS/EQL17018190/Khloq

DA: 690917

GBE 785T - X

28/06/18

@ 11:41 a.m. revised IA to Chh'ia Nyuk Pui via mumun.
 (\$ 2,506.36 Red. 40%)

ASS. REC. BY: Adrian Ling**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBC13934 Yr Regn: 2011, JuneType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Starex c.c. 2497Colour: Grey A/C: Insured / Std / Nil / NASp. Reading: 2020/30 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: KMFWBX7JL34376862Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/70R16CR: 215/70R16C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 03/05/18Survey held at: Premium Carz.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP MS16.</u>
	<u>HS \$ 3,800.00 / 5 days</u>

RECEIVED 20 JUN 2018

Date/Time, File Pass to?

28/06/181) Typist
Date/Time, File Return to?

2) _____



: Preli. Report



: Final Report

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 3,800/- 1/5)

150
10
160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2018		03 May 2018 13:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WYN CONSTRUCTION SERVICES PTE LTD, Co. Reg. No.: 201434621C								
Main Claimant:	EVERLYN SERVICES PTE LTD, Co. Reg. No.: 199904573R								
Vehicle Reg. No.:	GBC1393U	Date of Loss:	30/04/2018 00:00 - :59 [82 Months and 14 Days From LTA Reg Date (Mon Yr)]						
Claim Type:	TP / 557214	Policy/Cover Note No.:	29066577MKF Coverage: 26/12/2017 - 25/12/2018						
Vehicle Reg. No. (Insured):	GBE785T	Policy No. (Claimant):							
		Excess:							
Repairer:	Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki, 417883 Kaki Bukit - Tel: 66369100								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/05/2018]								
Adj Asg. Remarks:	TP agree Mr Adrian Ling frm LKK to survey the vehicle.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 28 Jun 2018

Preliminary Advice

Insured Vehicle No	: GBE785T		
TP Vehicle No	: GBC1393U	Accident Date	: 30/04/2018
Make	: HYUNDAI H-1 STAREX	Assignment Date	: 03/05/2018
Date of Inspection	: 03/05/2018	Est. Duration of Repair	: 5 days
Inspection At	: Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,306.36
Revised Amount	:S\$	4,753.32
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,753.32

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Adrian's copy

Date : 30/04/2018

TO: MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Shirley

Our Customer : Everlyn Services Pte Ltd

Vehicle No : GBC1393U

Model : Hyundai H1 Starex

Manufacture Year : 2011

Date of Accident : 30/4/2018

Total Estimate Repair Days : 10

Total Pages : 2

Attn : Motor Claims Department
Fax : 6225 7402

Re: Repair Estimate For Third Party Claim against GBE785T

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper <i>Delaid</i>	1		404 \$0.00	✓
2	Rear bumper step garnish <i>Delaid</i>	1		85 \$0.00	✓
3	Rear bumper clip <i>New</i>	10	5	50 \$0.00	✓ 30
4	Rear bumper side retainer RH <i>2 new</i>	1		42 \$0.00	✓
5	Rear bumper side retainer LH <i>2 new</i>	1		42 \$0.00	✓
6	Rear bumper reinforcement <i>Best</i>	1		308 \$0.00	✓
7	Rear bumper foam <i>2 new</i>	1		120 \$0.00	✓
8	Tail lamp LH <i>cut</i>	1		321 \$0.00	✓
9	Tail lamp lower panel LH <i>new</i>	1		95.80 \$0.00	✓
10	Tail lamp clip <i>new</i>	3	6.50	19.50 \$0.00	✓
11	Tail gate <i>Delaid to</i>	1		2374.80 \$0.00	✓
12	Tail gate weatherstrip <i>cut</i>	1		128 \$0.00	✓
13	Tail gate lock <i>Damaged</i>	1		100.60 \$0.00	✓
14	Tail gate "Hyundai" emblem <i>2 new</i>	1		38 \$0.00	✓
15	Tail gate "Hyundai" logo <i>1 new</i>	1	4060.40	35 \$0.00	✓
16	Tail gate "H-1" emblem	1		32 \$0.00	✓
17	Tail gate garnish <i>New New</i>	1	3248.32	38 \$0.00	✓
18	Tail gate trimboard <i>New New</i>	1		210.50 \$0.00	✓
19	Tail gate trimboard clip <i>New</i>	10	5	50 \$0.00	✓
20	Rear end panel <i>Repair</i>	1		546.40 \$0.00	✓
21	Rear end panel garnish <i>New</i>	1		75.50 \$0.00	✓
22	Rear end panel garnish clip <i>New</i>	7	5	35.00 \$0.00	✓
	Total			\$0.00	<i>5201.70</i>
	Less 20%			\$0.00	
	Sub Total 1			\$0.00	<i>4161.36</i>
A.	Spare Parts (S/Nett)				
1	Reverse sensor (set) <i>Damaged</i>	1	\$250.00	\$250.00	<i>20</i>
2	70km/h sticker <i>New</i>	1	\$15.00	\$15.00	✓
3	Sealant <i>New</i>	1	\$60.00	\$60.00	✓ <i>275</i>
	Sub-Total 2			\$250.00	
	Total for Parts			\$250.00	

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
B.	Labour				
1	To check wiring.			\$60.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$800.00	7500
3	Spray painting all affected parts & areas.			\$900.00	700
4	To spray anti-rust undercoat.			\$60.00	X
	Total Labour			\$1,820.00	
	Total Repair Cost			\$2,070.00	

total: 4733.32
c/s: 3.81C

6306.36
Adrian Lij
c/s 03/05/18.
OSDmp.

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008116/ASBN2

Date: 29/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29066577MKF
Claimant Vehicle No :	GBC1393U	Insured Vehicle No :	GBE785T
Date of Loss:	30/04/2018	Nature of Claim:	TP
		Claim No:	557214

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC1393U	Engine No:	D4CBB849148
Make & Model:	HYUNDAI H-1 STAREX, 2.5 D CRDi (A)	Chassis No:	KMFWBX7JLBU376862
Reg. Date:	16/06/2011 (Man. Year: 2011)	Odometer:	202030 km
Colour:	Grey		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/70R16C	Rear Tyre Size:	215/70R16C
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,486.36	3,523.32	963.04	21.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	1,230.00	590.00	32.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,306.36	4,753.32	1,553.04	24.63
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	6,306.36	3,800.00	2,506.36	39.74

INSPECTION

Date of Assignment:	03/05/2018	
Date Inspected:	03/05/2018 Inspected At:	Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Jun 2018)	
Parts:	N/A	HYUNDAI H-1 STAREX 2.5 D CRDi (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC1393U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	404.00 FL	*404.00 FL
2	1		*REAR BUMPER STEP GARNISH	Deformed	85.00 FL	*85.00 FL
3	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
4	1		*REAR BUMPER SIDE RETAINER RH	Necessary	42.00 FL	*42.00 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Necessary	42.00 FL	*42.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	308.00 FL	*308.00 FL
7	1		*REAR BUMPER FOAM	Cracked	120.00 FL	*120.00 FL
8	1		*TAIL LAMP LH	Cut	321.00 FL	*321.00 FL
9	1		*TAIL LAMP LOWER PANEL LH	Not Necessary	95.80 FL	*- FL
10	3		*TAIL LAMP CLIP	Not Necessary	19.50 FL	*- FL
11	1		*TAIL GATE	Dented	2,374.80 FL	*2,374.80 FL
12	1		*TAIL GATE WEATHERSTRIP	Cut	128.00 FL	*128.00 FL
13	1		*TAIL GATE LOCK	Damaged	100.60 FL	*100.60 FL
14	1		*TAIL GATE HYUNDAI EMBLEM	Necessary	38.00 FL	*38.00 FL
15	1		*TAIL GATE HYUNDAI LOGO	Necessary	35.00 FL	*35.00 FL
16	1		*TAIL GATE H-1 EMBLEM	Necessary	32.00 FL	*32.00 FL
17	1		*TAIL GATE GARNISH	Not Necessary	38.00 FL	*- FL
18	1		*TAIL GATE TRIMBOARD	Not Necessary	210.80 FL	*- FL
19	10		*TAIL GATE TRIMBOARD CLIP	Not Necessary	50.00 FL	*- FL
20	1		*REAR END PANEL	Repair	596.40 FL	*- FL
21	1		*REAR END PANEL GARNISH	Not Necessary	75.80 FL	*- FL
22	7		*REAR END PANEL GARNISH CLIP	Not Necessary	35.00 FL	*- FL
23	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
24	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
25	1		*SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,526.70	4,335.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,040.34	812.08
Total Parts (\$\$)	4,486.36	3,523.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	60.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE,TO CUT AND WELD,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	800.00	500.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	900.00	700.00
4	TO SPRAY ANTI-RUST UNDERCOAT	New	60.00	-
Gross Labour Cost (\$\$)			1,820.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >