

TPAIG

Vic

SFG 48051C.

Holder Stream.

RN61048198.

Rear Number Plate.		30(SN) X
Rear Number Plate Holder.	$\left. \begin{matrix} 2 \\ \text{AMP} \\ \text{New} \end{matrix} \right\}$	30(SN) X.
Rear Bumper Distorted		688.80 ✓
Rear Bumper Clips.	new	30 ✓
Rear Bumper Side Holder x02	new	$24.2 \times 2 = 48.40$ ✓
Rear Bumper Tow Cover.	behind	28.50 ✓
Rear Bumper Bracket x02	Best	$18 \times 2 = 36$ ✓
Rear Sensor	Demerged	280(SN) 200(SN)
Rear End Panel	Deated.	550.20 ✓
Rear End Panel Inner Member	Repair	325.50 X.
Rear End Panel Top Garnish.	behind	116.70 ✓
Rear End Panel Sealant.	new	60(SN) ✓
Taillamp x02	Cracked.	$352.4 \times 2 = 704.80$ ✓
Tailgate	Deated.	903.20 ✓
Tailgate Lock	Demerged	109.60 ✓
Tailgate Weatherstripe.	ut	121.60 ✓
Tailgate Inner Trim Board	cracked.	284 ✓
Tailgate Inner Trim Board Clips.	new	30. ✓

STG48051C

Tailgate Glass Moulding .Ner 70.70 /

Tailgate Glass Sealant .Ner 60(SN) /

Stream Wording .Ner 31.60 /

PSZ Wording .Ner 35.80 /

Rear Fender Inner Trim Board x02 224.7x2 = 449.40 /

Rear Fender Inner Trim Board Cups .Ner 60 / 30

Spere Tyre Carrier x02 121.60 +

Rear Exhaust Pipe .Ber 515.70 -

Rear Exhaust Mounting .Ner 30.40 +

Floor Panel Top Cover x02 119.2x2 = 238.40 +

4600.8
3680.64
S.N: 320

Panel Beating .
Spray Painting .

~~1200~~ 800.
~~1300~~ 80

~~50~~ 30.
~~120~~ 40.

~~100~~ 50.
~~150~~ 60.

~~150~~ 80.
~~180~~ 120.

~~150~~ 80.

total: 60606x
L/S: 48K.
06Days

Wiring .
To undersent
To remove reverse sensor

To remove upholstery.
To transfer tailgate fittings.
To remove tailgate glass
To remove exhaust pipe .

LKK Auto Consultants hereby certify that I am the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts during survey
• Parts produced to confirm order
• Third party survey in a court of law
• No illegal modifications is allowed
• Supplementary items must be approved by the insurance company
is subject to final approval from insurance company

Acknowledged by Repairer
Signature:
Date: