



陳林摩喀私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKX2506M

Date of Accident : 29 April 2018

Mr Loh Sin Choon

Date : 03 May 2018

Estimate To Repair SJX1079Y - NISSAN SYLPHY 1.5L 4AT ABS D/AB 2WD 4
Chassis No : JN1BAAG11Z0111115

S/No	Quantity	Description	Amount
		LIST ITEMS	
01	1 pc	front bumper D.S. —	\$ 0.00
02	5 pc	front bumper clips @ \$.00 —	\$ 0.00
03	1 pc	front bumper retainer —	\$ 0.00
04	1 pc	n/s headlamp —	\$ 0.00
05	1 pc	front chrome bumper —	\$ 0.00
06	1 pc	front bumper reinforcement 2 X —	\$ 0.00
		Sub higher stage torn —	\$ 0.00
		Less 30 %	\$ 0.00
			\$ 0.00
		LABOUR & MISC. CHARGES	
01		To check electrical lighting concerned.	\$ 30.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 420.00
03		Putty and spray painting of the affected portion.	\$ 300.00
			\$ 750.00
		Total	\$ 750.00

20
300
✓

Not Afford
LKK
2/5

2/5/18
Take photo after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: