

SS. REC. BY:

REF:

CS/MS/18008138/Arbnz

Special Instruction:

Surveyor

Adnan

ASSIGNMENT (Office)

Merimen

From (Person):

Onhia Nyuk Rul

of

MSLH

Date/Time:

02052018 437pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S66 2007Z

Insured:

SJM 5285A

at Workshop m/s

Green Forest Automobile

Tel:

9271 2214

of

8 Kaki Bukit Ave 4 #05-25

Policy No:

S28864966SMA

Claim No:

567220

Sum Insured:

Excess:

Make of Veh:

D.O.A. 01-052018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

08052018 5:14pm

Person Contacted:

Onis

Vehicle ~~IN~~/OUT

Date/Time	Action/Instruction (✓) Estimate
	S66 2007Z - C66 / A6614000863 / K663W2
	SJM 5285A - X
	Sent. pending est email thru Merimen
	Confirm L/s \$4300 @ 6 days (Red \$8789.30, 67%.)

ASS. REC. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: S66200TZ Yr Regn: 2006 / May.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Sunny c.c. 1597Colour: Gold A/C: Insured / Std / NI / NASp. Reading: 131855 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNCFAN1620100225Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R15R: 195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 03/05/18Survey held at Green ForestDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MS16

* Adrian said alrd check part price

MV: 19K

PV: 13.7K

Nett: 5.3K

RECEIVED 19 JUL 2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

.

TOTAL

Report Format: TPLump Sum / H.B.I. (\$) 4300

200

10

310

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018		03 May 2018 16:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS Insured: WONG WEIXIONG, ANDREW, ID: S8711975J, Tel: +6597467275, Email: EHNDREW@GMAIL.COM Main Claimant: LIM CHIN CHAI ROBERT, ID: S0041452B Vehicle Reg. No.: SGG2007Z Date of Loss: 01/05/2018 14:00 - :59 [143 Months and 27 Days From LTA Reg Date (Man Yr)] Claim Type: TP / 557220 Policy/Cover Note No.: S28864966SMA (Comprehensive) Coverage: 07/01/2018 - 06/01/2019 Vehicle Reg. No. (Insured): SJM5285A Policy No. (Claimant): Excess: S\$500.00 Repairer: GREEN FOREST AUTOMOBILE (HQ) 8 KAKI BUKIT AVENUE 4, #05-25 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63846383 Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521] Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/05/2018] Driver/Custodian (Insured): WONG WEIXIONG, ANDREW (30 / Male), NRIC: S8711975J, Tel: +6597467275 Adj Asg. Remarks: TP agree to appoint LKK as the SJE									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1452B
Vehicle Details	
Vehicle No.:	SGG2007Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	03 May 2018
Vehicle Make:	NISSAN
Vehicle Model:	SUNNY 1.6EXA
Primary Colour:	Beige
Manufacturing Year:	2006
Engine No.:	QG16408678
Chassis No.:	JN1CFAN16Z0100225
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$12,089.00
Original Registration Date:	04 May 2006
First Registration Date:	04 May 2006
Transfer Count:	1
Actual ARF Paid:	\$10,657.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 May 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$22,789.00
COE Rebate Amount:	\$13,673.00
Total Rebate Amount:	\$13,673.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 May 2018

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Nissan Sunny

Price Range ▾

Depreciation ▾

> 10 year(s) ▾

Vehicle Type ▾



Advanced Search

Used Car Comparison

--- Comparing 3 Vehicles ---

Nissan Sunny 1.6A EX (COE till 05/2020)



Add to Shortlist

Nissan Sunny 1.6A EX (COE till 11/2020)



Add to Shortlist

Nissan Sunny 1.6A EX (COE till 03/2022)



Add to Shortlist



NO IMAGE AV

Use search bar above to get to compare.

Clear All

Add all to Shortlist

Back to search result

CAR DETAILS

Price	\$15,800	\$18,800	\$25,000
Instalment	N.A.	N.A.	N.A.
Registration Date	26-May-2005	01-Dec-2005	30-Mar-2007
Manufactured	2005	2005	2007
Mileage	145,000 km	-	390,000 km
Transmission	Auto	Auto	Auto
Engine Cap	1,597 cc	1,597 cc	1,597 cc
Road Tax	\$965 /yr	\$965 /yr	\$816 /yr
Power	81.0 kW (108 bhp)	81.0 kW (108 bhp)	81.0 kW (108 bhp)
Curb Weight	0 kg	0 kg	1,110 kg
Features	1.6L DOHC CVTC Engine, Automatic Transmission, SRS Airbags, ABS.	4 Cylinder In-line 16 Valve DOHC CVTC, Power 82kW (110 Bhp), Torque 148 Nm, Front-wheel Drive, 4 Speed (Auto Transmission).	Powerful And Responsive 1.6L DOHC CVTC Engine 4 Speed Auto Transmission, SRS, Airbags, ABS, Retractable Side Mirror.
Accessories	Sport Rims, Clarion Car Stereo System, Electrical Retractable Side Mirrors, Upholstery Leather Seats.	-	Full Factory Fitted Accessories, Leather Seat.
Description	Very Low Monthly, Just 1 Owner! Very Low Mileage! Well Kept By Previous Owner In Tip Top Condition, View And Believe It! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Drop By Our Aircon Showroom To Appreciate It In Pristine Condition Now, Before Its Gone!	Full Loan Available! Call Now To Arrange For A Viewing. Trade In Welcome, Flexible Loan Readily Available For Your Convenience.	Practical Car That Is Easy To Maintain, Well Maintained By The Previous Owner, Factory Fitted Interior, Accident Free, No Repairs Needed, Best Deal In Town. Comes With Complimentary 6 Months Gearbox And Engine Warranty By Tokio Marine. Schedule A Test Drive Today, Viewing Is Strictly By Appointment Only.
COE	\$31,722	\$28,292	\$24,715
OMV	\$13,023	\$12,234	\$11,107
ARF	\$14,326	\$13,458	\$12,218
Depreciation	\$7,660 /yr	\$7,280 /yr	\$6,400 /yr
No. of Owners	1	2	3
Type of Vehicle	Sedan	Sedan	Sedan
Category	COE Car	COE Car, Premium Ad Car	COE Car, Premium Ad Car
Availability	Available	Available	Available
Remarks	COE expiry date 2022-03-29	COE expiry date 2022-03-29	COE expiry date 2022-03-29

Print Sent Message

This mail is associated with :

***SGG2007Z (557220)**

[SJM5285A]

TP

LIM CHIN CHAI ROBERT

May 1 2018 2:00PM

[WONG WEIXIONG, ANDREW]

GREEN FOREST AUTOMOBILE

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 04/05/2018 12:08 PM.
To nyukpui_chhia@sg.msig-asia.com
CC sur@lkkauto.com
Subject SGG2007Z (557220)

Dear Sir,

Please be informed that we have inspected the vehicle **SGG 2007Z** on 03/05/2018.

We are still pending estimate from repairer.

Thank you.

Regards,
Jannice

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

TP MS16

Jance

04th MAY 2018

LIM CHIN CHAI ROBERT
8 KAKI BUKIT AVENUE 4
#05-25 Premier @ Kaki Bukit
Singapore 415875

Accident date: 01st MAY 2018

Estimated repair cost for vehicle no: SGG2007Z NISSAN SUNNY 1.6A

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Buckled</i>		\$755.40 ✓
2	1	Rear Boot Lid Number Plate <i>Not m</i>		\$50.00 ✗
3	1	Rear Bumper <i>Deformed</i>		\$444.30 ✓
4	2	Rear Bumper Bracket <i>RH Bent</i>	\$84.30	\$168.60 <i>84.30</i>
5	8	Rear bumper clips <i>new</i>	\$5.00	\$40.00 ✓
6	1	Rear Bumper reverse sensor <i>Damaged</i>		\$350.00 <i>20(SN)</i>
7	2	Rear Bumper mud shield <i>Not new</i>	\$45.20	\$90.40 ✗
8	1	Rear End Panel <i>Dented</i>		\$346.30 ✓
9	1	Rear fender R/H <i>Not m</i>		\$844.10 ✗
10	1	Rear spare tire panel sealant <i>Not m</i>		\$250.00 ✗
			Subtotal :-	\$3,339.10

S/n	Qty	Items/Nett	U/price	Amount
1	2	Rear Boot Lid Hinges <i>3 NTP</i>	\$68.10	\$136.20 ✗
2	1	Rear boot lid top moulding <i>Not m</i>		\$323.60 ✗
3	1	Rear boot lid lower moulding <i>Not m</i>		\$163.10 ✗
4	5	Rear boot lid lower moulding clips <i>Not m</i>	\$8.00	\$40.00 ✗
5	2	Rear Boot Lid Number Plate Lamp <i>Not m</i>	\$40.20	\$80.40 ✗

Sheet1

6	1	Rear Boot Lid Inner Trim board	<i>Not New</i>	\$195.10	+
7	10	Rear Boot Lid Inner Trim board clips	<i>Not New</i>	\$5.00	\$50.00 x
8	2	Rear tail lamp	<i>RH cracked</i>	\$213.60	\$427.20 213.60
9	2	Rear tail lamp panel	<i>Repis</i>	\$143.10	\$286.20 x
10	2	Rear bumper side bracket inner	<i>Not New</i>	\$32.40	\$64.80 ✓
11	2	Rear bumper side bracket outer	<i>Not New</i>	\$44.00	\$88.00 ✓
12	2	Rear bumper mud flap	<i>Not New</i>	\$85.80	\$171.60 x
13	1	Rear bumper inner sponge	<i>Del d</i>		\$123.30 ✓
14	1	Rear bumper center moulding	<i>Not New</i>		\$165.40 ✓
15	1	Rear End Panel Top Garnish	<i>cracked</i>		\$64.70 ✓
16	1	Rear End Panel lock	<i>Not New</i>		\$71.70 x
17	1	Rear End Panel Top Garnish lower trim	<i>crumpled</i>		\$176.10 ✓
18	1	Rear End Panel lock cable	<i>Not New</i>		\$70.50 x
19	2	Rear fender inner trim board	<i>RH crumpled</i>	\$195.40	\$390.80 195.40
20	1	Rear spare tire panel	<i>Repis</i>		\$876.20 x
21	1	Rear spare tire panel top cover	<i>tom</i>		\$189.20 ✓
22	1	Rear windscreen moulding	<i>Not New</i>		\$155.80 x

1200.50
1152.45

Subtotal :- \$4,309.90

S/n	Qty	Items/S.Nett	U/price	Amount
1	1	Rear Boot Lid emble logo		\$63.90 ✓
2	1	Rear Boot Lid sunny logo		\$36.10 ✓
3	1	Rear Boot Lid Super saloon logo	<i>Not New</i>	\$62.90 ✓
4	1	Rear Boot Lid CVTC logo		\$90.70 ✓
5	1	Rear Boot Lid E-THROTTE logo		\$90.70 ✓
6	1	Rear Boot Lid Inner Lock	<i>Damaged</i>	\$121.00 ✓
7	1	Rear boot lid inner rubber	<i>Not</i>	\$105.00 ✓
8	4	Rear tail lamp clips	<i>Not</i>	\$8.00 \$32.00 10
9	5	Rear end Panel Top Garnish clips	<i>Not</i>	\$8.00 \$40.00 10
10	1	Rear Exhaust	<i>Repis</i>	\$750.00 x
11	4	Rear Exhaust moulding	<i>Not New</i>	\$65.00 \$260.00 1
13	1	Rear center aluminium cover	<i>Not New</i>	\$88.00 x
14	1	Triangle Warning Sign		
			<i>120 80(SN)</i>	
			Subtotal :-	<u>\$1,740.30</u>

Labour charges

To remove & re-fix reverse sensor

~~\$100.00~~ 50

To remove & re-fix cushion

~~\$150.00~~ 60

To remove & re-fix rear exhaust

~~\$250.00~~ 80

To remove & re-fix windscreen

~~\$150.00~~ 1

Gum

~~\$50.00~~ 1

To Check Wiring System

260 ~~\$80.00~~ 30

Tuff Kote

~~\$120.00~~ 40

Panel beating

~~\$1,400.00~~ 1000

Spray painting

~~\$1,400.00~~ 1000

Subtotal :- \$3,700.00

Total:- \$13,089.30

total: 5392.53 13000.30

h/s: 43K

06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008138/ARBN2

Date: 20/07/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	S28864966SMA
Claimant Vehicle No :	SGG2007Z	Insured Vehicle No :	SJM5285A
Date of Loss:	01/05/2018	Nature of Claim:	TP
		Claim No:	557220

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGG2007Z	Engine No:	QG16408678
Make & Model:	NISSAN SUNNY, 1.6 EX (A)	Chassis No:	JN1CFAN16Z0100225
Reg. Date:	04/05/2006 (Man. Year: 2006)	Odometer:	131855 km
Colour:	Gold		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,559.30	3,132.93	6,426.37	67.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	2,260.00	1,390.00	38.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,209.30	5,392.93	7,816.37	59.17
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	13,209.30	4,300.00	8,909.30	67.45
+ GST 7.00/7.00% (S\$)	924.65	301.00	623.65	67.45
Nett Amount (S\$)	14,133.95	4,601.00	9,532.95	67.45

INSPECTION

Date of Assignment: 03/05/2018

Date Inspected: 03/05/2018 Inspected At:

GREEN FOREST AUTOMOBILE (HQ)
8 KAKI BUKIT AVENUE 4, #05-25
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Jul 2018)
Parts: 143	NISSAN SUNNY 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGG2007Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Buckled	755.40 F	*755.40 FL
2	1	*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
3	1	*REAR BUMPER	Deformed	444.30 F	*444.30 FL
4	1	*REAR BUMPER BRACKET	O/s Dented	168.60 F	*84.30 FL
5	8	*REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
6	2	*REAR BUMPER MUD SHIELD	Not Necessary	90.40 F	*- FL
7	1	*REAR END PANEL	Dented	346.30 F	*346.30 FL
8	1	*REAR FENDER R/H	Not Necessary	844.10 F	*- FL
9	1	*REAR SPARE TIRE PANEL SEALANT	Not Necessary	250.00 F	*- FL
10	2	*REAR BOOT LID HINGES	Not Necessary	136.20 F	*- FN
11	1	*REAR BOOT LID TOP MOULDING	Not Necessary	323.60 F	*- FN
12	1	*REAR BOOT LID LOWER MOULDING	Not Necessary	163.10 F	*- FN
13	5	*REAR BOOT LID LOWER MOULDING CLIPS	Not Necessary	40.00 F	*- FN
14	2	*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	80.40 F	*- FN
15	1	*REAR BOOT LID INNER TRIM BOARD	Not Necessary	195.10 F	*- FN
16	10	*REAR BOOT LID INNER TRIM BOARD CLIPS	Not Necessary	50.00 F	*- FN
17	1	*REAR TAIL LAMP	O/s Cracked	427.20 F	*213.60 FN
18	2	*REAR TAIL LAMP PANEL	Repair	286.20 F	*- FN
19	2	*REAR BUMPER SIDE BRACKET INNER	Necessary	64.80 F	*64.80 FN
20	2	*REAR BUMPER SIDE BRACKET OUTER	Necessary	88.00 F	*88.00 FN
21	2	*REAR BUMPER MUD FLAP	Not Necessary	171.60 F	*- FN
22	1	*REAR BUMPER INNER SPONGE	Deformed	123.30 F	*123.30 FN
23	1	*REAR BUMPER CENTER MOULDING	Necessary	165.40 F	*165.40 FN
24	1	*REAR END PANEL TOP GARNISH	Cracked	64.70 F	*64.70 FN
25	1	*REAR END PANEL LOCK	Not Necessary	71.70 F	*- FN
26	1	*REAR END PANEL TOP GARNISH LOWER TRIM	Crumpled	176.10 F	*176.10 FN
27	1	*REAR END PANEL LOCK CABLE	Not Necessary	70.50 F	*- FN
28	1	*REAR FENDER INNER TRIM BOARD	O/s Crumpled	390.80 F	*195.40 FN
29	1	*REAR SPARE TIRE PANEL	Repair	876.20 F	*- FN
30	1	*REAR SPARE TIRE PANEL TOP COVER	Torn	189.20 F	*189.20 FN
31	1	*REAR WINDSCREEN MOULDING	Not Necessary	155.80 F	*- FN
32	1	*REAR BOOT LID EMBLEM LOGO	Necessary	63.90 F	*63.90 FN
33	1	*REAR BOOT LID SUNNY LOGO	Necessary	36.10 F	*36.10 FN
34	1	*REAR BOOT LID SUPER SALOON LOGO	Necessary	62.90 F	*62.90 FN
35	1	*REAR BOOT LID CVTC LOGO	Necessary	90.70 F	*90.70 FN
36	1	*REAR BOOT LID E-THROTTE LOGO	Necessary	90.70 F	*90.70 FN
37	1	*REAR BOOT LID INNER LOCK	Damaged	121.00 F	*121.00 FN
38	1	*REAR BOOT LID INNER RUBBER	Cut	105.00 F	*105.00 FN
39	4	*REAR TAIL LAMP CLIPS	Necessary	32.00 F	*10.00 FN
40	5	*REAR END PANEL TOP GARNISH CLIPS	Necessary	40.00 F	*10.00 FN
41	1	*REAR EXHAUST	Repair	750.00 F	*- FN
42	4	*REAR EXHAUST MOULDING	Not Necessary	260.00 F	*- FN
43	1	*REAR CENTER ALUMINIUM COVER	Not Necessary	88.00 F	*- FN
44	1	*TRIANGLE WARNING SIGN	Cracked	120.00 FS	*80.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*GUM	Not Necessary	50.00 FS	*- FS
46	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.						
Sub Total (S\$)					9,559.30	3,821.10
- List Item Discount on L Items 0.00/30.00% (S\$)					0.00	501.09
- Nett Item Discount on N Items 0.00/10.00% (S\$)					0.00	187.08
Total Parts (S\$)					9,559.30	3,132.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RE-FIX REVERSE SENSOR	New	100.00	50.00
2	TO REMOVE & RE-FIX CUSHION	New	150.00	60.00
3	TO REMOVE & RE-FIX REAR EXHAUST	New	250.00	80.00
4	TO REMOVE & RE-FIX WINDSCREEN	New	150.00	-
5	TO CHECK WIRING SYSTEM	New	80.00	30.00
6	TUFF KOTE	New	120.00	40.00
7	PANEL BEATING	New	1,400.00	1,000.00
8	SPRAY PAINTING	New	1,400.00	1,000.00
Gross Labour Cost (\$\$)			3,650.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >