		1/SPF 18008148/KO ASSIGNMENT (O	Sired.	Part by Part: # 3	5398-89
rom (Person): Abdul	Rahman St	PF Date/Time: B	1052018	Third Parties:	
stimated Cost:	8111	I to:	0-2010	Claimant:	
		7		Surveyor: KM A	uto
DD/TP Re-inspection				Workshop:	
o Inspect Vehicle No:		932K Insured:	GBC 10839		
Workshop m/s		Tel:	6287 6666		
f	No. 2 AMIC S	H 63			
olicy No:		Claim No:	AEMD /105 /00	9/2015/146A	
um Insured:		Excess:			
Take of Veh:			24082015		
Client's Record)				DO NO	Troutize
			Н	O.D. Endorsement/Date:	(It will-C
Date/Time:	Person Con	tacted:v	Vehicle IN/OUT		
Date/Time:	Confirmed with	Final Fig 3914. 97 Q3 days	,days (Rec	I \$/_%; Or	riginal_5_days
Date/Time: 14/9/1	Submit Final Fig_	2714.77 03 days	(Red \$ 1483 721	1/2%; Original 5	days)
ate/Time Action/	Instruction				
310 8	13)K - M3/EDT 15	50 D1924/K91662.		DUA 181219	
GBC 10	83P - X				
Para(1) · Parte 6	ound not replaced				
a.a(1). Laits it	duid not reptaced	To highlight	R or UB, LE	t, Etc)	
,				-	
Para(2) : Commo	ents on consistance	w of dames on (D)	NIC	1 3100	
	ares on consistenc	y of damages (Part	s Not Consiste	nt:NC)	
	RECEIVED-1	4 MAY 2018			
Para(3) : Nett V	alue				
1(0) 1.11010 V	and.			In or	
Mark	et Value :	Inspected	i.	Fee Charged: Basic & Add	Date:
		Evaluated		Transport	500
Salva	ge Value :		884.1 5 4.04	Photos	
Nett '	Value .			Others	The second second
10.75	1-0.000	7		Total	
The second secon	18 por 1	MINISTER			
1) Date/Time 14/5/	1 110 1 455 10	nrist 2) Date/Ti		File Return to	
	File Pass to File Pass to File Pass to	2) Date/Ti 4) Date/Ti		File Return to	

Catherine Chong (LKK Auto)

From: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>

Sent: Thursday, 3 May, 2018 9:38 AM

To: assignments

Cc: SUR

Subject: [SPF]: URGENT : Pending Paper Survey Report of SHD9932K
Attachments: SHD9932K Assignment.pdf; SHD9932K Joseph Gay & Co.pdf

[Urgent]

Hi Cath,

No record of assignment dated 21 Feb 2018. Please check.

Thanks.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: <u>olivialau@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | \$(408933)

From: Abdul Rahman MOHAMAD SALIM (SPF) < Abdul_Rahman_Mohamad_Salim@spf.gov.sg>

Sent: Thursday, 3 May 2018 9:33 AM

To: Olivia Lau (LKKAuto)

Cc: Rosalyn TAN (SPF); Frankie THAY (SPF)

Subject: URGENT: Pending Paper Survey Report of SHD9932K

Our Ref: AEMD/105/009/2015/146A

Dear Olivia,

We refer to the assignment of 21 Feb 2018 which is still pending.

Please expedite as Solicitors has sent in their Third Party Claims with intent for writ against the Govt. (Attached refer).

Thanks

Abdul Rahman (Mr)
Accident Claims Officer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848



WARNING. "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



Your Ref:

SHD9932K

Our Ref:

AEMD/105/009/2015/146A

Date :

21 February 2018

SPF Accidents Claims Section Automotive Engg & Mgmt Div Police Logistics Department No. 1 Mount Pleasant Road Block 8 Old Police Academy #02-12 Singapore 298333

Tel: 64784840 Fax: 64784848

Via Fax Only: 62564315

M/s LKK Auto Consultants Pte Ltd Paya Ubi Industrial Park 51 Ubi Avenue 1 #01/02-25 Singapore 408933

Dear Sir/Madam,

ACCIDENT ON 24 AUGUST 2015 INVOLVING GOVT VEH GBC1083P AND OTHER VEH SHD9932K

We refer to the above matter.

- Please arrange for a Paper Survey of vehicle no. SHD9932K at M/s Trans-Cab Auto Services Pte Ltd of No: 58 Defu Lane 1, Singapore 539498.
- 3 For appointment please contact Tel: 62876666.
- Estimates were not provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman

Accident Claims Officer

for ASST DIRECTOR

M/s Joseph Gay & Company (Ref: 56/2018/ap)

Via fax: 65338286 only

AUTOMOBILE INSPECTION REPORT NO. 5/8/QBE006/I



KM AUTO ASSESSORS PTE. LTD.

47 Jalan Pemimpin #02-02 Halcyon 2

T 6448 8208 F 6442 9690 E kmautoassessors@gmail.com

Regn. No. 2009073402

To:	QBE INSURANCE (INT'L) LTD 60 ANSON ROAD #11-01 MAPLETREE ANSON SINGAPORE 079914							
Insured Vehicle	SKR 1018 T ACC Date	24-Aug-15		Sum Insun	ed: S THIRD PARTY			
Policy / Claim No.	V0009612			General Co	ondition: Poor / Fair / Good / Excellent			
Reg. No.	SHD 9932 K	Make/Model	REN	AULT LA	ATITUDE 2.0L DCI TAXI AUTO	Year	2014	
Engine No.	M9R8839C001216	Chassis No.	VF1	ABL15A	UC277845	Colour	White To	p/Red
Condition of Tyres				Speedome	eter Reading - Km		205851	
Front N/S	FALKEN 215/60R16	worn 10	7%	Front O/S	FALKEN 215/60R16	worn	10	96
Rear N/S	FALKEN 215/60R16	worn 10	%	Rear O/S	FALKEN 215/60R16	wom	10	56
Spare	-	worn -	%					
Extra Fittings:-	Concealed Air Con., Audio Set,	DigiTax Fare	meter	Rustpro	ofed.			
Requested By	MS JOYCE FOO			On	28-Aug-15		The Above	Vehicle
Was Inspected At (28-Aug-15) TRANS-CAB AL	JTO SERVI	CES	PL 42 S	UNGEI KADUT ST 1 SINGAP	ORE 7	29346	

And The Undermentioned Damage Was Noted:-

Boot lid assy, bent and distorted, rear panel dented and bent, bumper grazed, dented, bent, cracked and deformed, n/s inner reverse sensor snapped and dislodged, fenders distorted, boot floor panel bent.

Photographs:-	33 Copies	were taken at time of	inspection a	and are attached.	
The Repairers estimate was fo	r a total amount of		S	16,083.36	
After adjustment the estimate was revised and agreed at		\$	5,398.89		
After adjustment the estimate was revised and agreed at. The Repairers were NOT AUTHORISED to proceed with the repairs at the above figure in accordance with Appendix 'A' attached to this report, subject their collecting from the owner the Excess of		\$	N/A		

SPECIAL REMARKS

The above were due to impact to the rear portion of the taxi.

Survey was carried out without prejudice.

07 Oct 15 - Finally managed to get repairer to finalise cost of repairs.

MICHAEL EE DIP A END AMERTE AMERIE AMERIE AMERIE AMERIE

(



T 6448 8208 F 6442 9690 E kmautoassessors@gmail.com

#02-02 Halcyon 2

Regn. No. 2009073407

APPENDIX 'A' TO REPORT NO:

REGN. NO:

5/8/QBE006/I SHD 9932 K

It is estimated that the repairs will take

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revise
1 pce rear bumper fascia	852.66	dented, bent, cracked, deformed	852.66
1 pce rear bumper lower garnish	591.41	grazed, bent, cracked, deformed	591.41
1 pce rear bumper centre bracket	87.29	not necessary	117466450
1 pce rear bumper o/s side bracket	104.59	not necessary	12
1 pce rear bumper o/s retainer	34.61	not damaged	
1 pce rear bumper o/s reflector	33.55	not damaged	
1 pce rear bumper n/s side bracket	104.59	not necessary	
1 pce rear bumper n/s retainer	34.61	not damaged	1.0
1 pce rear bumper n/s reflector	33.55	not damaged	
1 pce rear bumper reinforcement	598.09	bent & flattened	509.00
1 pce rear bumper reinforcement n/s bracket	173.81		598.09
1 pce rear bumper reinforcement n/s bracket	173.81	not necessary	
1 pce boot lid	2,209.75	not necessary	
1 pce boot lid chrome moulding	429.90	to repair	
1 pce boot lid rubber		not damaged	
1 pce boot lid rubber 1 pce boot lid n/s reflector	248.50	not damaged	
	379.50	not damaged	
1 pce boot lid o/s reflector	379.50	not damaged	
1 pce boot lid "RENAULT" plate	173.35	necessary	173.35
1 pce boot lid emblem	173.35	necessary	173.35
1 pce boot lid inner lock	155.90	not necessary	-
1 pce n/s rear lamp	425.04	not damaged	
1 pce o/s rear lamp	425.04	not damaged	4
1 pce rear panel	1,132.13	dented & bent	1,132.13
1 pce rear panel inner garnish	311.20	not necessary	-
G1 F250 P	9,265.73		3,520.99
less 10%	926.57	less 10%	352.10
	8,339.16		3,168.89
S.NETT			
1 set reverse sensors (45 inner with	600.00	n/s-inner-unit snapped off	600.00
1 set rear bumper clips	66.00	necessary	66.00
1 set rear bumper centre bracket clips	33.00	necessary	33.00
1 set rear bumper o/s retainer clips	20.00	necessary	~~ 20.00
1 set rear bumper n/s retainer clips	20.00	necessary	n 20.00
1 set rear bumper lower garnish clips	66.00	necessary	66.00
1 set rear panel inner garnish clips	35.00	necessary	An 35.00
1 set boot lid chrome moulding clips	24.20	not required	-
1 pce boot lid "Tans-Cab" sticker	30.00	necessary	30.00
1 pce boot lid "6555-3333" sticker	30.00	necessary	30.00
	9,263.36		4,068.89
Total Amount Revised	\$		
Lump Sum Repairs Amount	\$		
Less Excess	S		

days to complete.



47 Jalan Pernimpin #02-02 Halcyon 2 Singapore 577200

T 6448 8208 F 6442 9690

E kmautoassessors@gmail.com

Regn. No. 2009073407

APPENDIX 'A'

TO REPORT NO: REGN. NO:

It is estimated that the repairs will take

5/8/QBE006/I SHD 9932 K

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
b/f	9,263.36		4,068.89
Towing charges.	120.00	not-required NV	
Transfer boot lid fittings to new boot lid assy. and refit.	170.00	not required MA	
Remove necessary interior upholsterys and fittings to enable necessary repairs, check and refit same.	170.00	55	60.00
Renew reverse sensors, transfer same to new bumper assy., refit and test system.	170.00		40.00
Remove damaged parts, jack and cut out damaged body panels, jack out, straighten up damaged body panels and repair body parts and fittings, whichever possible and			
necessary, replace and weld necessary damaged parts, refit and align whichever parts necessary. (incl. alignment of body structure.)	2,800.00		600.00 4
Paint replacement parts and repaint damaged sections with welded portions in and outside.	3,000.00		600.00 4
Rustproof replacement parts and touch-up damaged sections.	170.00		~~ _{30.00} X
Check and realign wheels (computerised).	220.00	not-required- MM	
TOTAL	16,083.36		5,398.89
Total Amount Revised			
â B			
Lump Sum Repairs Amount Less Excess	9		

FIVE

days to complete.





KM AUTO ASSESSORS PTE. LTD

7 Jaian Peningin #02-02 Balayan 2 managar 377986

T 6440-3208 F 6440-9690 E kisanowenoù @ginori co

To:	QBE INSURANCE (INT'L) LTD 60 ANSON ROAD #11-01 MAPLETREE ANSON SINGAPORE 079914							
Insured Vehicle	SKR 1018 T ACC Date	24-Aug-15		Sum Insure	d: S THIRD PARTY			
Policy / Claim No.	V0009612			General Co	indition: Peer / Fair / Good / Excellent			
Reg. No.	SHD 9932 K	Make/Model	REN	AULT LA	ATITUDE 2.0L DCI TAXI AUTO	Year	2014	
Engine No.	M9R8839C001216	Chassis No.	Chassis No. VF1ABL15AUC277845				White	Top/Red
Condition of Tyres	And the second of the second o			Speedome	ter Reading - Km		20585	51
Front N/S	FALKEN 215/60R16	worn 10	36	Front O/S	FALKEN 215/60R16	worn	10	%
Rear N/S	FALKEN 215/60R16	worn 10	%	Rear O/S	FALKEN 215/60R16	WORT	10	76
Spare	-	worn -	.5%					
Extra Fittings:-	Concealed Air Con., Audio Set,	DigiTax Faren	neter	Rustpro	ofed.			
Requested By	MS JOYCE FOO			On	28-Aug-15		The Al	bove Vehicle
Was Inspected At (28-Aug-15) TRANS-CAB Al	JTO SERVIO	CES	PL 42 SI	JNGEI KADUT ST 1 SINGAP	ORE 7	29346	

And The Undermentioned Damage Was Noted:-

Boot lid assy, bent and distorted, rear panel dented and bent, bumper grazed, dented, bent, cracked and deformed, n/s inner reverse sensor snapped and dislodged, fenders distorted, boot floor panel bent.

Photographs:-	33 Copies	were taken at time of inspection and are attached.			
The Repairers estimate was fo	r a total amount of		S	16,083.36	
After adjustment the estimate was revised and agreed at			\$	5,398.89	
The Repairers were NOT AUTHORISED to proceed with the repairs at the above figure in accordance with Appendix 'A' attached to this report, subject their collecting from the owner the Excess of		\$	N/A		

SPECIAL REMARKS

The above were due to impact to the rear portion of the taxi.

Survey was carried out without prejudice.

07 Oct 15 - Finally managed to get repairer to finalise cost of repairs.

MICHAEL EE DIPAENE AMRTE AVSAE, AMSOE, AMMI, MEAAA

(

17 Jalan Pennapi #802-02 Malena

> T 6448 8288 F 8442 9690

Eliminousecon @pnail.com


THE R. 2009075410

AP	P	E	N	D	X	'A'
	-	_				7.

TO REPORT NO: REGN. NO:

5/8/QBE006/I SHD 9932 K

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised
1 pce rear bumper fascia	852.66	dented, bent, cracked, deformed	852.66
1 pce rear bumper lower garnish	591.41	grazed, bent, cracked, deformed	591.41
1 pce rear bumper centre bracket	87.29	not necessary	15%
1 pce rear bumper o/s side bracket	104.59	not necessary	100
1 pce rear bumper o/s retainer	34.61	not damaged	
1 pce rear bumper o/s reflector	33.55	not damaged	23
1 pce rear bumper n/s side bracket	104.59	not necessary	
1 pce rear bumper n/s retainer	34.61	not damaged	-
1 pce rear bumper n/s reflector	33.55	not damaged	
1 pce rear bumper reinforcement	598.09	bent & flattened	598.09
1 pce rear bumper reinforcement n/s bracket	173.81	not necessary	
1 pce rear bumper reinforcement o/s bracket		not necessary	741
1 pce boot lid	2,209.75	to repair	
1 pce boot lid chrome moulding	429.90	not damaged	
1 pce boot lid rubber	248.50	not damaged	-
1 pce boot lid n/s reflector	379.50	not damaged	
1 pce boot lid o/s reflector	379.50	not damaged	
1 pce boot lid "RENAULT" plate	173.35	necessary	173.35
1 pce boot lid emblem	173.35	necessary	173.35
1 pce boot lid inner lock	155.90	not necessary	-
1 pce n/s rear lamp	425.04	not damaged	-
1 pce o/s rear lamp	425.04	not damaged	-
1 pce rear panel	1,132.13	dented & bent	1,132.13
1 pce rear panel inner garnish	311.20	not necessary	W. Sandara
1 poor tour pairer miner german	9,265.73		3,520.99
less 10%	CONT. C.	less 10%	352.10
1020 1020	8,339.16	1000	3,168.89
S.NETT			
1 set reverse sensors	600.00	n/s inner unit snapped off	600.00
1 set rear bumper clips	66.00	necessary	66.00
1 set rear bumper centre bracket clips	33.00	necessary	33.00
1 set rear bumper o/s retainer clips	20.00	necessary	20.00
1 set rear bumper n/s retainer clips	20.00	necessary	20.00
1 set rear bumper lower garnish clips	66.00	necessary	66.00
1 set rear panel inner garnish clips	35.00	necessary	35.00
1 set boot lid chrome moulding clips	24.20	not required	100000000000000000000000000000000000000
1 pce boot lid "Tans-Cab" sticker	30.00	necessary	30.00
1 pce boot lid "6555-3333" sticker	30.00	necessary	30.00
	9,263.36		4,068.89
Total Amount Revised		\$	
Lump Sum Repairs Amount		5	
Less Excess		\$	
Nett Total Approved		\$ (Incl. GST	\$ -



47 Jalan Pemmanii #02-01 Haloviii 1 Singapare 177300

T 6440 8208 F 6442 9140

E Imautoussensin@grant.com

THE RESIDENCE

APPENDIX 'A'

TO REPORT NO: REGN. NO:

5/8/QBE006/I SHD 9932 K

Nature of Work and Materials	Repairers Estimate	Remarks	Amount Revised \$
b/f	9,263.36		4,068.89
Towing charges.	120.00	not required	
Transfer boot lid fittings to new boot lid assy, and refit.	170,00	not required	
Remove necessary interior upholsterys and fittings to enable necessary repairs, check and refit same.	170.00		60.00
Renew reverse sensors, transfer same to new bumper assy., refit and test system.	170.00		40.00
Remove damaged parts, jack and cut out damaged body panels, jack out, straighten up damaged body panels and repair body parts and fittings, whichever possible and necessary, replace and weld necessary damaged parts, refit and align whichever parts necessary. (incl. alignment of body structure.)	2,800.00		600.00
Paint replacement parts and repaint damaged sections with welded portions in and outside.	3,000.00		600.00
Rustproof replacement parts and touch-up damaged sections.	170.00		30.00
Check and realign wheels (computerised).	220.00	not required	
TOTAL	16,083.36		5,398.89
Total Amount Revised Lump Sum Repairs Amount		\$ 5,398.89 \$ N/A	
Less Excess		\$ N/A	
Nett Total Approved		\$ 5,398.89	(Incl. GST \$ 5,776.81)



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AEMD/105/009/2015/146A

Date: 16th May 2018

Our Ref: CS1/SPF18008148/Kqbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section
(Singapore Police Force)

1 Mount Pleasant Road
Blk 8 Old Police Academy
Singapore 298333
(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SHD 9932K INSURED VEHICLE: GBC 1083P ACCIDENT DATE: 24/08/2015

We thank you for your instruction on 03/05/2018.

We acknowledge receipt of the following documents:-

a) Automobile Inspection Report of SHD 9932K from M/s Trans-Cab Auto Services Pte Ltd.

b) Colour damaged vehicle photographs of SHD 9932K.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SHD 9932K

Make & Model

: Renault Latitude 2.0L DCI Taxi Auto

Year of Registration

: 2014

Chassis Number

: VF1ABL15AUC277845

Engine Capacity

: 1995 cc

 We recommend that the repairs of the entire damage require about <u>3 (Three)</u> working days to complete.

We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9932K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER FASCIA	DENTED / BENT / CRACKED / DEFORMED	852.66	852.66
1	REAR BUMPER LOWER GARNISH	GRAZED / BENT / CRACKED / DEFORMED	591.41	591.41
1	REAR BUMPER CENTRE BRACKET	NOT NECESSARY	87.29	-
1	REAR BUMPER O/S SIDE BRACKET	NOT NECESSARY	104.59	-
1	REAR BUMPER O/S RETAINER	NOT DAMAGED	34.61	
1	REAR BUMPER O/S REFLECTOR	NOT DAMAGED	33.55	
1	REAR BUMPER N/S SIDE BRACKET	NOT NECESSARY	104.59	5
1	REAR BUMPER N/S RETAINER	NOT DAMAGED	34.61	
1	REAR BUMPER N/S REFLECTOR	NOT DAMAGED	33.55	1
1	REAR BUMPER REINFORCEMENT	BENT / FLATTENED	598.09	598.09
1	REAR BUMPER REINFORCEMENT N/S BRACKET	NOT NECESSARY	173.81	
1	REAR BUMPER REINFORCEMENT O/S BRACKET	NOT NECESSARY	173.81	
1	BOOT LID	TO REPAIR SEE LABOUR	2,209.75	
1	BOOT LID CHROME MOULDING	NOT DAMAGED	429.90	15
1	BOOT LID RUBBER	NOT DAMAGED	248.50	-
1	BOOT LID N/S REFLECTOR	NOT DAMAGED	379.50	
1	BOOT LID O/S RELECTOR	NOT DAMAGED	379.50	0-
1	BOOT LID "RENAULT" PLATE	NECESSARY	173.35	173.35
1	BOOT LID EMBLEM	NECESSARY	173.35	173.35
1	BOOT LID INNER LOCK	NOT NECESSARY	155.90	1
1	N/S REAR LAMP	NOT DAMAGED	425.04	8.
- 1	O/S REAR LAMP	NOT DAMAGED	425.04	
1	REAR PANEL	TO REPAIR SEE LABOUR	1,132.13	
1	REAR PANEL INNER GARNISH	NOT NECESSARY	311.20	(4)
	LESS 10% DISCOUNT		-926.57	-238.89
			8,339.16	2,149.97

Report Ref No. CS1/SPF18008148/Kqbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSORS (N/S INNER UNIT) (SN)	SNAPPED OFF	600.00	600.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	66.00	66.00
1	SET REAR BUMPER CENTRE BRACKET CLIPS (SN)	NECESSARY	33.00	33.00
1	SET REAR BUMPER O/S RETAINER CLIPS (SN)	NOT NECESSARY	20.00	
1	SET REAR BUMPER N/S RETAINER CLIPS (SN)	NOT NECESSARY	20.00	
1	SET REAR BUMPER LOWER GARNISH CLIPS (SN)	NECESSARY	66.00	66.00
1	SET REAR PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	35.00	-
1	SET BOOT LID CHROME MOULDING CLIPS (SN)	NOT REQUIRED	24.20	
1	BOOT LID "TRANS-CAB" STICKER (SN)	NECESSARY	30.00	30.00
1	BOOT LID "6555-3333" STICKER (SN)	NECESSARY	30.00	30.00
			924.20	825.00
	LABOUR			
	TOWING CHARGES.	NOT NECESSARY	120.00	-
	TRANSFER BOOT LID FITTINGS TO NEW BOOT LID ASSY AND REFIT.	NOT NECESSARY	170.00	
	REMOVE NECESSARY INTERIOR UPHOLSTERY AND FITTINGS TO ENABLE NECESSARY REPAIRS, CHECK AND REFIT SAME.		170.00	60.00
	RENEW REVERSE SENSORS, TRANSFER SAME TO NEW BUMPER ASSY, REFIT AND TEST SYSTEM.		170.00	40.00
	REMOVE DAMAGED PARTS, JACK AND CUT OUT DAMAGED BODY PANELS, JACK OUT, STRAIGHTEN UP DAMAGED BODY PANELS AND REPAIR BODY PARTS AND FITTINGS, WHICHEVER POSSIBLE AND NECESSARY, REPLACE AND WELD NECESSARY DAMAGED PARTS, REFIT AND ALIGN WHICHEVER PARTS NECESSARY. (INCL ALIGNMENT OF BODY STRUCTURE) INCLUSIVE OF THE REPAIR OF BOOT LID AND REAR PANEL.		2,800.00	400.00
	PAINT REPLACEMENT PARTS AND REPAINT DAMAGED SECTIONS WITH WELDED PORTIONS IN AND OUTSIDE.		3,000.00	440.00
	RUSTPROOF REPLACEMENT PARTS AND TOUCH-UP DAMAGED SECTIONS.	NOT NECESSARY	170.00	,
	CHECK AND REALIGN WHEELS (COMPUTERISED).	NOT NECESSARY	220.00	
			6,820.00	940.00
	GRAND TOTAL		16,083.36	3,914.97

Report Ref No. CS1/SPF18008148/Kqbs2



Page No.:3 of 3

RECOMMENDED COST OF REPAIRS 3,914.97

Report Ref No. CS1/SPF18008148/Kqbs2

KONG SENG CHEONG

Licensed Appraiser

Tu

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part, Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.