

Sunny

REF:

msch

CC3 / msh 18008163 / Ss. ber

ASSIGNMENT

From: Date: 03/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMB 143

at Workshop m/s

of

Insured: SKM 9831K

Policy No.

Claims No. M556471

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Sunny

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: 54B 143 G Yr Regn: 18/3/2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C1400 0530 cc 6374

Colour: Multi Colour A/C: Insured / Std / NI / NA

Sp. Reading: 602056 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W12 B 62808523 120698

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size: F: 275/70R22.5

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fuzion

Front

Rear

R/Bal. 6 mm

R/Bal. 6/6 mm

L/Bal. 6 mm

L/Bal. 6/6 mm

D.O.A. 19/9/18

D.O.I. 3/5/18

Survey held at SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SMB 143G - X
	SKM 9831K - X
19/06/18 @ 15:05 pm	revised IN to Lionel Tan Tian Pei via messenger.
19/06/18 @ 14:52 pm	confirmed finalised amount P/P \$830/- with Catherine via email.
	(\$ 411.00 Red - 33%)
	RECEIVED 19 JUN 2018

Date/Time, File Pass to?

19/06/18 Typst

1)

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair: 1

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

\$ + RS \$

: Photos

: Others

Report Format :

Lump Sum / I.B.I. (\$ P/P \$830/-)

TOTAL

150

10

160

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 19 June 2018 2:52 PM
To: 'Catherine Lee Sau Chan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)'
Cc: "SUR"
Subject: FW: Finalisation - SMB143G (BUS/04/18/1033) - MSIG
Attachments: img-608113850-0001.pdf; img-608113706-0001.pdf

Dear Catherine,

WITHOUT PREJUDICE

Confirmed finalised amount \$830.00 @ 1 working day under part by part repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Lee Sau Chan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) [mailto:catherineleesc@smrt.com.sg]
Sent: Wednesday, 13 June 2018 6:05 PM
To: SUR <sur@lkkauto.com>
Subject: FW: Finalisation - SMB143G (BUS/04/18/1033) - MSIG

Hi,

Please assist for the finalisation, please.

Thank you

Best Regards
Catherine Lee
SMRT Automotive Services Pte Ltd
(Accident Repair Centre)
DID: 6866 2669 Fax: 6368 5592
catherineleesc@smrt.com.sg



From: Catherine Lee Sau Chan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
Sent: 08 June 2018 11:48
To: 'SebastianYeang@lkkauto.com' <SebastianYeang@lkkauto.com>
Cc: Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC) <YewChung@smrt.com.sg>; AutoSvs-ARC (Bus) <AutoSvs-ARCBus@smrt.com.sg>
Subject: Finalisation - SMB143G (BUS/04/18/1033) - MSIG

Hi Sebastian,

Attached herewith our copy and your marked copy of the bus repair estimate for the case.
Our finalised amount is \$830.00 @ 1 working day under part by part repair.

Please confirm the COR by return email ASAP.

Thank you

Best Regards
Catherine Lee
SMRT Automotive Services Pte Ltd
(Accident Repair Centre)
DID: 6866 2669 Fax: 6368 5592
catherineleesc@smrt.com.sg



Moving People, Enhancing Lives

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 19 Jun 2018

Preliminary Advice

Insured Vehicle No	: SKM9831K	Accident Date	: 19/04/2018
TP Vehicle No	: SMB143G	Assignment Date	: 08/05/2018
Make	: MERCEDES-BENZ CITARO O530	Est. Duration of Repair	: 1 day
Date of Inspection	: 03/05/2018		
Inspection At	: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,241.00
Revised Amount	:S\$	830.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	830.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/04/2018 16:06
Date Of Accident	19/04/2018 18:20
Exact Location Of Accident	CANTONMENT LK – BEF BS05631 – BLK 16
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB143G
-----------------------------	---------

Insured/Policyholder

Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CITARO O530-6.4 D AT TURBO ABS (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090224MFBP
Cover Note Number	

Driver

Name of Driver	SYAKIRIN BIN MAHAT
NRIC No	S8177056E
Date Of Birth	15/07/1981
Occupation	OUTDOOR
Date Of Driving Pass	09/04/2015
Driving Experience	3 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Nature Of Damage

No. Of Passenger (Including Driver)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2292D
Vehicle Details	
Vehicle No.:	SMB143G
Vehicle to be Exported:	No
Intended De-registration Date:	04 May 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CITARO O530
Primary Colour:	Multi-Colour
Manufacturing Year:	2010
Engine No.:	90292600847406
Chassis No.:	WEB62808323120698
Maximum Power Output:	-
Open Market Value:	\$282,480.00
Original Registration Date:	18 Mar 2011
First Registration Date:	18 Mar 2011
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00


The information contained herein is correct as at 04 May 2018

OK

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB143G
 Ref. No : BUS/04/18/1033
 Reg. Date : 26/04/2018
 Vehicle Type : BUS -12M
 Make : MB CITARO MERCEDES
 Model : MB CITARO O530
 Name of Driver : Syakirin Bin Mahat
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 19/04/2018 06:20:00 PM
 Accident Reported Date / Time : 26/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : MSIG
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC,if any :



SMB143G - LEFT FRONT PORTION
 SKM9831K (TP) - INSURED WITH MSIG

Prepared Date : 26/04/2018 04:29:56 PM

Sebastian
 3/5/18

- Lump Sum Repair
 - Photo After Paint


 22/5/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

☐

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	795.00	0.00
Total Spray Painting Charges :	446.00	0.00
Total Material Charges :	0.00	0.00
Other Charges :	0.00	0.00
TOTAL :	1,241.00	0.00
Lum Sum Total :	1,250.00	0.00
No. of Repair Days :	2.00	0.00
Prepared / Adjusted By :	Sunny Tan Ah Leong	<i>I Jay</i>
Arc / Surveyor Sign Off Date :	03/05/2018 09:33:40 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 03/05/2018 09:33:40 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	795.00	0.00 530
Total Labour	795.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	446.00	0.00 300
Total Spray Painting & Panel Beating	446.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

1251

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)							0.00	0.00		


Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB143G
Ref. No : BUS/04/18/1033
Reg. Date : 18/03/2011
Vehicle Type : BUS -12M
Make : MB CITARO MERCEDES
Model : MB CITARO O530
Name of Driver : Syakirin Bin Mahat
Type of Accident : SIDE SWIPE
Date / Time of Accident : 19/04/2018 06:20:00 PM
Accident Reported Date / Time : 26/04/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : MSIG
Vehicle is Towed Back? : No
Towed Back Date/Time : 01/01/2000
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024095878
Special Instruction to ARC, if any :
SMB143G - LEFT FRONT PORTION
SKM9831K (TP) - INSURED WITH MSIG
Prepared Date : 26/04/2018 04:29:56 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : WEB62808323120698

Mileage : 0

Work Shop :

Repair Completed Date / Time : 01/01/2000

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 795.00	530.00
Total Spray Painting Charges	: 446.00	300.00
Total Material Charges	: 0.00	0.00
Other Charges	: 0.00	0.00
TOTAL	: 1,241.00	830.00
Lump Sum Total	: 0.00	0.00
No. of Repair Days	: 2.00	1.00
Prepared / Adjusted By	: Sunny Tan Ah Leong	SEBASTIAN LKK
Arc / Surveyor Sign Off Date	: 03/05/2018 09:33:40 AM	05/06/2018 08:09:46 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 03/05/2018 09:33:40 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	795.00	530.00
Total Labour	795.00	530.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	446.00	300.00
Total Spray Painting & Panel Beating	446.00	300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)							0.00	0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 May 2018		08 May 2018 08:15 Edit Adj Rpt	S\$830.00 Edit Estimates	S\$830.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: KONDO TAKAYUKI , ID: TK7093317									
Main Claimant: SMRT BUSES LTD , Co. Reg. No.: 198202292D									
Vehicle Reg. No.:	SMB143G	Date of Loss:	19/04/2018 18:00 - :59 [85 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 556471	Policy/Cover Note No.:	10118059 (Comprehensive) Coverage: 30/04/2017 - 29/04/2018						
Vehicle Reg. No. (Insured):	SKM9831K	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 07/06/2018]								
Driver/Custodian (Insured):	JUN KONDO (37 / Male), NRIC: S8079862H, Tel: +6591557807								
Adj Asg. Remarks:	DIRECT SURVEY DONE BY LKK AUTO CONSULTANTS ON 03/05/2018								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMB143G (556471)**
[SKM9831K]
TP
SMRT BUSES LTD
Apr 19 2018 6:00PM
[KONDO TAKAYUKI]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	08/05/18 08:07	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement <small>From: SC - Reg. No: SKM9831K, Claimant: Kondo Takayuki</small>	Load HTM	
No	Finalized On		Thumbnail	Print
1	19/06/18 15:05	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice	Load HTM	
Photos/Images				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
1	19/06/18 15:24	LKK Auto Consultants Pte Ltd (HQ) General View	Load JPG	<input checked="" type="checkbox"/>
2	19/06/18 15:24	General View	Load JPG	<input checked="" type="checkbox"/>
3	19/06/18 15:24	General View	Load JPG	<input checked="" type="checkbox"/>
4	19/06/18 15:24	General View	Load JPG	<input checked="" type="checkbox"/>
5	19/06/18 15:24	General View	Load JPG	<input checked="" type="checkbox"/>
6	19/06/18 15:24	General View	Load JPG	<input checked="" type="checkbox"/>
7	19/06/18 15:24	General View	Load JPG	<input checked="" type="checkbox"/>
8	19/06/18 15:24	General View	Load JPG	<input checked="" type="checkbox"/>
9	19/06/18 15:24	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
10	19/06/18 15:24	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
11	19/06/18 15:24	General View	Load JPG	<input checked="" type="checkbox"/>
12	19/06/18 15:24	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	08/05/18 08:07	MSIG Insurance (Singapore) Pte. Ltd. (HQ) TPD SMB143G GIA REPORT	Load PDF	
2	08/05/18 08:07	TPD SMB143G - ESTIMATE REPAIR	Load PDF	
3	08/05/18 08:07	DIRECT SURVEY BY LKK AUTO	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>		
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18008163/SSBE2

Date: 20/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 10118059

Claimant Vehicle No : SMB143G

Insured Vehicle No : SKM9831K

Date of Loss: 19/04/2018

Nature of Claim: TP Claim No: 556471

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMB143G

Make & Model: MERCEDES-BENZ CITARO O530, 6.4 D (A)

Engine No: 90292600847406

Reg. Date: 18/03/2011 (Man. Year: 2010)

Chassis No: WEB62808323120698

Colour: Multi-colour

Odometer: 602036 km

Engine Capacity: 6374 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Firenza 6 mm

Rear Left Side: Firenza 6/6 mm

Front Right Side: Firenza 6 mm

Rear Right Side: Firenza 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,241.00	830.00	411.00	33.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,241.00	830.00	411.00	33.12

INSPECTION

Date of Assignment: 08/05/2018

Date Inspected: 03/05/2018 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 1.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Jun 2018)

Parts: N/A MERCEDES-BENZ CITARO O530 6.4 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMB143G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR FRONT LH PORTION	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	446.00	300.00
Gross Labour Cost (\$\$)			1,241.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >