

REF: mslh CC3 / mslh18008165 / Srbn2

## ASSIGNMENT

From: Date: 06/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SG 1187B

at Workshop m/s: SMRT

of:

Insured: SKT 8796Z

Policy No. 28986218 QMY

Claims No. 557773

Sum Insured: Excess:

(Client's Record)

Make of Veh: Sunny

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No. SG 1187B Yr Regn: 7/7/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz Citaro 6374

Colour: Multi Colour A/C: Insured / Std / NI / NA

Sp. Reading: No Display T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WFB 6286832 3130022

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70R22.5

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 6 mm R/Bal. 6/6 mm

L/Bal. 6 mm L/Bal. 6/6 mm

D.O.A. 10/8/2017 D.O.I. 5/5/18.

Survey held at SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SG 1187B - X

SKT 8796Z - 004 / ALA / 8006617 / KwB3

DUA: 300318

Sent GIA &amp; Est. thru email.

Confirm 8 830 @ 1 day

Red: \$ 315, 28%.

RECEIVED 28 JUN 2018

Date/Time, File Pass to?



: Preli. Report

1) typst



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 1

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$

Photos:

Others:

Report Format: TP

Lump Sum / I.B.I. (\$) 280 830

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

TOTAL

150

10

160

**Janice Lee (LKKAUTO)**

---

**From:** Janice Lee (LKKAUTO)  
**Sent:** Friday, May 04, 2018 3:33 PM  
**To:** Catherine Thia; Eileen Ang; 'Pang Xiu Shi'  
**Cc:** SUR; KKLau; Accounts (LKKAUTO); 'Christopher Chionh'  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD,  
DOA: 03/5/2018 , SG 1187B (TP VEHICLE), SKT 8796Z (OI VEHICLE)  
**Attachments:** SG 1187B ESTIMATE.pdf; SG 1187B GIA.pdf

Dear Catherine/ Eileen,

Please be informed that we had inspected the vehicle SG 1187B at M/s: SMRT AUTOMOTIVE SERVICES PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705

Enclosed herewith a copy of TP's GIA report and estimate.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Janice Lee (LKKAUTO)**

---

**From:** Catherine Lee Sau Chan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)  
<catherineleesc@smrt.com.sg>  
**Sent:** Tuesday, June 26, 2018 12:10 PM  
**To:** SUR; Joy Irene (LKKAUTO)  
**Cc:** Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); AutoSvs-ARC (Bus); Bryan Ang (LKKAUTO); CS A Team; Admin A; Olivia Lau (LKKAUTO); Celine Fong (LKKAUTO)  
**Subject:** Finalisation - SG1187B (BUS/08/17/1011) - MSIG  
**Attachments:** img-626120109-0001.pdf; img-626120001-0001.pdf

To Whom it may concern.

Attached herewith our copy and Surveyor's marked copy of the bus repair estimate for the case.  
Our finalised amount is \$830.00 @ 1 working day under part by part repair.

Please confirm the COR by return email ASAP.

Thank you

Best Regards  
Catherine Lee  
SMRT Automotive Services Pte Ltd  
(Accident Repair Centre)  
DID: 6866 2669 Fax: 6368 5592  
[catherineleesc@smrt.com.sg](mailto:catherineleesc@smrt.com.sg)



Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	2292D
<b>Vehicle Details</b>	
Vehicle No.:	SG1187B
Vehicle to be Exported:	No
Intended De-registration Date:	04 May 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CITARO O530 6.4L AT TURBO ABS
Primary Colour:	Multi-Colour
Manufacturing Year:	2015
Engine No.:	902926C1101347
Chassis No.:	WEB62808323130022
Maximum Power Output:	-
Open Market Value:	\$284,910.00
Original Registration Date:	07 Jul 2016
First Registration Date:	07 Jul 2016
Transfer Count:	2
Actual ARF Paid:	\$0.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Rebate Amount:	\$0.00
<b>Total Rebate Amount:</b>	<b>\$0.00</b>


The information contained herein is correct as at 04 May 2018

OK

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG1187B  
 Ref. No : BUS/08/17/1011  
 Reg. Date : 11/08/2017  
 Vehicle Type : BUS -12M  
 Make : MB CITARO MERCEDES  
 Model : MB CITARO O530  
 Name of Driver : Lee Sing Yang  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 10/08/2017 11:08:00 AM  
 Accident Reported Date / Time : 10/08/2017 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : MSIG  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No :  
 Special Instruction to ARC, if any :



SG1187B - FRONT RIGHT PORTION  
 SGT8796Z (TP) - INSURED WITH MSIG. LEFT REAR PORTION  
 Prepared Date : 11/08/2017 03:50:53 PM

Sebastian  
 3/5/18

- Part by part repair  
 - Photo After Paint

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	795.00	0.00
Total Spray Painting Charges :	354.00	0.00
Total Material Charges :	0.00	0.00
Other Charges :	0.00	0.00
<b>TOTAL :</b>	<b>1,149.00</b>	<b>0.00</b>
<b>Lum Sum Total :</b>	<b>0.00</b>	<b>0.00</b>
No. of Repair Days :	2.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sing Off Date :	03/05/2018 09:36:57 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 03/05/2018 09:36:57 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	795.00	0.00 530
<b>Total Labour</b>	<b>795.00</b>	<b>0.00</b>

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	354.00	0.00 300
<b>Total Spray Painting &amp; Panel Beating</b>	<b>354.00</b>	<b>0.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)							0.00	0.00		

Added Spare Parts / Material Usage After Surveyor Signed off


Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG1187B  
Ref. No : BUS/08/17/1011  
Reg. Date : 07/07/2016  
Vehicle Type : BUS -12M  
Make : MB CITARO MERCEDES  
Model : MB CITARO O530  
Name of Driver : Lee Sing Yang  
Type of Accident : SIDE SWIPE  
Date / Time of Accident : 10/08/2017 11:08:00 AM  
Accident Reported Date / Time : 10/08/2017 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : MSIG  
Vehicle is Towed Back? : No  
Towed Back Date/Time : 01/01/2000  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024096067  
Special Instruction to ARC, if any :  
SG1187B - FRONT RIGHT PORTION  
SKT8796Z (TP) - INSURED WITH MSIG. LEFT REAR PORTION  
Prepared Date : 11/08/2017 03:50:53 PM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : WEB62808323130022

Mileage

0

Work Shop :

Repair Completed Date / Time : 01/01/2000

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 795.00	530.00
Total Spray Painting Charges	: 354.00	300.00
Total Material Charges	: 0.00	0.00
Other Charges	: 0.00	0.00
<b>TOTAL</b>	<b>: 1,149.00</b>	<b>830.00</b>
<b>Lump Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 2.00	1.00
Prepared / Adjusted By	:	SEBASTIAN LKK
Arc / Surveyor Sign Off Date	: 03/05/2018 09:36:57 AM	26/06/2018 11:52:47 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 03/05/2018 09:36:57 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :



**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	795.00	530.00
<b>Total Labour</b>	<b>795.00</b>	<b>530.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	354.00	300.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>354.00</b>	<b>300.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)								0.00	0.00	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18008165/SRBN2

Date: 29/06/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28986218QMY
Claimant Vehicle No :	SG1187B	Insured Vehicle No :	SKT8796Z
Date of Loss:	10/08/2017	Nature of Claim:	TP
		Claim No:	557773

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SG1187B	Engine No:	902926C1101347
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 D AT TURBO ABS (A)	Chassis No:	WEB62808323130022
Reg. Date:	07/07/2016 (Man. Year: 2015)	Odometer:	0 km
Colour:	Multi-colour		
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	275/70R22.5	Rear Tyre Size:	275/70R22.5(D)
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6/6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,149.00	830.00	319.00	27.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>1,149.00</b>	<b>830.00</b>	<b>319.00</b>	<b>27.76</b>

## INSPECTION

Date of Assignment:	09/05/2018	
Date Inspected:	03/05/2018	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705

Estimated Period of Repair: 1.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 29 Jun 2018)	
<b>Parts:</b>	N/A	MERCEDES-BENZ CITARO O530 6.4 D AT TURBO ABS (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SG1187B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

**There are no new parts selected.**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR RH FRONT PORTION	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	354.00	300.00
Gross Labour Cost (S\$)			1,149.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >