

ASS. REC. BY:

REF:

CS/CT118008178 / Ds d307

Special Instruction:

Surveyor:

Buyen

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTL

Date/Time:

04052018 11:47 am

Estimated Cost:

Bill to:

OD ~~TD~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX 2315U

Insured:

YN 1884P

at Workshop m/s

Teamwork

Tel:

6844 2475

of

53 Ubi Ave 1 #01-24

Policy No:

DMCVSN T681061701

Claim No:

SNM18D07231C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27042018

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

04052018 1:11pm

Person Contacted:

Sue

Vehicle-IN/OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

GX 2315U - NA / GALLI 80079 43 / 24

DA: 270418

YN 1884P - X

Signature

ASSIGNMENT


DE March 2019

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No. GX2315U Yr Regn: 2004 / March  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Hiace c.c. 2985  
 Colour: Green A/C: Insured / Std / NI / NA  
 Sp. Reading: 352545 T/Radio: Insured / Std / NI / NA  
 Eng/No: 5L5411193  
 C/No: LH1621010645  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 185 R14  
 R: — 11 —

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Radial

Front Rear  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 27/04/2018 D.O.I. 07/05/2018

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Survey held at Teamwork Paya Ubi  
 Des. of Damages: Frt / Rear O/S / NIS / UIC / Rooftop or  
Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	China Taping YN 1884P
	MV 7.5K } LTA 4.3K } Don't submit NL 3K }

RECEIVED 20 AUG 2019

02/08/19 Inayn 2/5 4500/- with 5 days of repair (4,605.87 Red - 60%)

Date/Time, File Pass to? 20/08/19  
 1) Typist  : Preli. Report  : Final Report  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_

Days Of Repair: 5  
 Resurvey No. of Trip: 2

Add Fee:  : Site Insp (\$) )  : S + RS + SI  
 : Interview (\$) )  : Photos  
 : Tech. Invs (\$) )  : Others  
 : Weekend (\$) )

Report Format :  
 Lump Sum / I.B.I. (\$) 4,500/- 4/5

Survey Fee: 220  
 TOTAL 220

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2018		04 May 2018 11:47 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	LANDMARK PLASTICS PTE LTD, Co. Reg. No.: -		
Main Claimant:	THL AIR-CON SERVICES PTE LTD		
Vehicle Reg. No.:	GX2315U	Date of Loss:	27/04/2018 17:00 - :59
Claim Type:	TP / SNM18D02231C02	Policy/Cover Note No.:	DMCVSN1682061701 (Comprehensive)
Vehicle Reg. No. (Insured):	YN1884P	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2018]		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		
<b>ASSOCIATED MAIL RECEIVED</b>			
There are no mail for this case.			
		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<b>ALL ASSOCIATED TASKS</b>			
		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company  
 Owner ID: 6061W

**Vehicle Details**

Vehicle No.: GX2315U  
 Vehicle to be Exported: Yes  
 Intended De-registration Date: 30 Apr 2018  
 Vehicle Make: TOYOTA  
 Vehicle Model: HIACE DIESEL  
 Primary Colour: Green  
 Manufacturing Year: 2004  
 Engine No.: 5L5411193  
 Chassis No.: LH1621010645  
 Maximum Power Output: -  
 Open Market Value: \$21,926.00  
 Original Registration Date: 10 Mar 2004  
 First Registration Date: 10 Mar 2004  
 Transfer Count: 2  
 Actual ARF Paid: \$1,097.00

**Intended PARF Rebate Details**

PARF Eligibility: No  
 PARF Eligibility Expiry Date: -  
 PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 09 Mar 2019  
 COE Category: C - Goods Vehicle & Bus  
 COE Period(Years): 5  
 PQP Paid: \$25,158.00  
 COE Rebate Amount: \$4,314.00  
 Total Rebate Amount: \$4,314.00

**Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 30 Apr 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/04/2018 14:21
Date Of Accident	27/04/2018 17:05
Exact Location Of Accident	ALONG UPP THOMSON RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GX2315U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THL AIR-CON SERVICES PTE LTD
Co Reg No	201316061W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63583219
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	HIACE DIESEL
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MOMVC000002816-01-000
Cover Note Number	
<b>Driver</b>	
Name of Driver	AHMAD RIDZUAN BIN MOHAMAD
Passport No/FIN	G2312148X
Date Of Birth	18/08/1989
Occupation	OUTDOOR
Date Of Driving Pass	19/08/2014
Driving Experience	3 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87396574
Fax Number	
Contact Number	OFFICE-87396574
EEmail Address	NOEMAIL

Address 15 JLN MERBAH 4  
TMN SCIENTEX PASIR GUDANG JOHOR

Postcode 81700

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions RAINING

Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : SOH CHEE BOON  
GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident**

REFER TO STATEMENT.

**Attachment(s)**

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number YN1884P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver KO GUAN MIN @ QUAH GUAN HIN

NRIC/Passport Number S0054799I

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	AHMAD RIDZUAN BIN MOHAMAD
Approximate Age	
Injuries Sustain	NECK & BACK
Injured person in which vehicle?	GX2315U
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

**DETAILS OF INJURED PERSON 2**

Name	SOH CHEE BOON
Approximate Age	
Injuries Sustain	NECK & BACK
Injured person in which vehicle?	GX2315U
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was completely stationary due to traffic light was red. All of a sudden, I felt an impact from my vehicle rear portion, and I got off my vehicle, I found vehicle B hit onto my rear portion.

Handwritten signature 'SJA' in the top right corner of the lined area.

DECLARATION

I/We declare that the foregoing particulars are true in every respect.



Policyholder's  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SPD/ACC/1 (Rev 01/04/2011) Form 2/1



Pte Ltd

TeamWork Garage Pte Ltd \* \*  
 53 Ubi Avenue 1 #01-23/24 Spore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475  
 E-mail : claims@teamworkgarage.com  
 Register number : 201015366H  
 3RD PARTY CLAIM ESTIMATION

China Taiping Insurance (Singapore) Pte Ltd  
 105 Cecil Street #19-00  
 The Octagon  
 Singapore 069534

Vehicle number	GX2315U
Make / Model	TOYOTA/HIACE
Chassis number	LH1621010645
Accident date	27 April 2018
Reference	1804-50

Qty Particulars Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER <i>Dented</i>	508.10 ✓
2	REAR BUMPER SIDE HOLDER <i>nm</i>	133.90 ✗
1	REAR BUMPER BEAM <i>Dented</i>	429.10 ✓
2	TAILLAMP <i>Crack</i>	632.40 ✓
2	TAILLAMP SEAL <i>nl</i>	40.20 ✗
2	TAILLAMP PANEL <i>nl</i>	563.70 ✗
1	TAILGATE <i>Dented</i>	<del>1812.32</del> ✓ <span style="float: right;">1812.32</span>
1	TAILGATE RUBBER <i>nlc</i>	311.40 ✓
1	TAILGATE EMBLEM LOGO <i>replaced</i>	61.00 ✗
1	TAILGATE LOCK <i>Dome</i>	413.70 ✓
1	TAILGATE LOCK CATCH <i>nl</i>	56.00 ✗
2	TAILGATE HINGE <i>nl</i>	178.00 ✗
1	TAILGATE RUBBER <i>replaced</i>	381.40 ✗
2	TAILGATE DAMPER <i>nl</i>	282.30 ✗
2	TAILGATE WEDGE CATCH <i>nl</i>	86.20 ✗
2	TAILGATE WEDGE ADJUSTMENT <i>nl</i>	115.60 ✗
1	TAILGATE OUTER GARNISH <i>mounting broken</i>	139.34 ✓
1	TAILGATE LOGO <i>nlc</i>	56.00 ✓
1	TAILGATE EMBLEM -HIACE <i>nlc</i>	68.00 ✓
1	REAR EXHAUST ASSY <i>nl</i>	892.10 ✗
1	REAR EXHAUST MOUNTING <i>nl</i>	40.00 ✗
		7200.76
		Less 25%
		1800.19
		Subtotal
		5400.57
		Balance C/F
		5400.57
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
		Balance B/F
		5400.57
1 SET	REAR BUMPER CLIP <i>nlc</i>	<del>60.00</del> 30/-
1 SET	REAR REVERSE SENSOR <i>nl</i>	400.00 ✗
1	REAR NUMBER PLATE <i>nl</i>	70.00 ✗
1	JOINT SELANT <i>nlc</i>	150.00 <del>40/-</del>
1	WINDSCREEN SEALANT <i>nlc</i>	150.00 <del>40/-</del>
1	70KM/H STICKER <i>nlc</i>	30.00 <del>20/-</del>

4370.36

3277.77

Less 25%  
 Subtotal  
 Balance C/F

130/-

S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	6260.57
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	<del>60.00</del> 30/-
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISGH	<del>200.00</del> 100/-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 NA
4	REMOVE AND RENEW REAR EXHAUST ASSY 1510.00	150.00 NA
5	REMOVE AND REFIT REAR WINDSCREEN	<del>150.00</del> 120/-
6	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	<del>200.00</del> 60/-
7	PANEL BEATING ON AFFECTED AREAS	<del>1500.00</del> 600/-
8	SPRAY PAINTING ON AFFECTED AREAS	<del>1400.00</del> 600/-
	Subtotal	3810.00
	Grand total	10070.57
		11105.87
		4917.77
	Supp	<u>804.00</u>

07/05/2018 @ 12:00 hrs  
 NA Author  
 L/S  
 Ryan  
 5 days.  
 LKK Auto

5721.77  
 L/S 4500/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

--

Subtotal	860.00
Balance C/F	6260.57



Pte Ltd

TeamWork Garage Pte Ltd  
 53 Ubi Avenue 1 #01-23/24 Spore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475  
 E-mail : claims@teamworkgarage.com  
 Register number : 201015366H  
 3RD PARTY CLAIM ESTIMATION

China Taiping Insurance (Singapore) Pte Ltd  
 105 Cecil Street #19-00  
 The Octagon  
 Singapore 069534

Vehicle number	GX2315U
Make / Model	TOYOTA/HIACE
Chassis number	LH1621010645
Accident date	27 April 2018
Reference	1804-50

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR END PANEL <i>Denda</i>	689.60 ✓
1	SPARE TIRE BRACKET <i>1st</i>	201.30 ✓
1	SPARE TIRE LOCK <i>1st</i>	489.50 ✓
		1380.40
	Less 25%	345.10
	Subtotal	1035.30
	Balance C/F	1035.30

*1072.00*  
*804.00*

*181.10*

*ngm*  
*2kk Auto*

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2018		04 May 2018 11:47 <a href="#">Edit Adj Rpt</a>	<b>S\$4,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>				[Created by insurer]					
Insured:	<b>LANDMARK PLASTICS PTE LTD</b> , Co. Reg. No.: -								
Main Claimant:	<b>THL AIR-CON SERVICES PTE LTD</b>								
Vehicle Reg. No.:	<b>GX2315U</b>	Date of Loss:	27/04/2018 17:00 - :59 [169 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D02231C02</b>	Policy/Cover Note No.:	DMCVSN1682061701 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>YN1884P</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Teamwork Garage Pte Ltd (HQ)</b> 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>BRYAN TANI</b> ] ... [Final Rpt due 15/05/2018]								
Adj Asg. Remarks:	NO EST, CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>	<a href="#">Compose Case Mail</a>				
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>				<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>		
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*GX2315U (SNM18D02231C02)  
 [YN1884P]  
 TP  
 THL AIR-CON SERVICES PTE LTD  
 Apr 27 2018 5:00PM  
 [LANDMARK PLASTICS PTE LTD]  
 Teamwork Garage Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
<b>Assessment Reports</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print						
1	03/05/18 15:14	<b>Accident Statement</b>		Load HTM							
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print						
1	03/05/18 15:12	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
2	03/05/18 15:12	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
3	03/05/18 15:12	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
4	03/05/18 15:12	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
5	03/05/18 15:12	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
6	03/05/18 15:12	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	26/07/19 14:40	<b>Rear View Left</b>		Load JPG	<input checked="" type="checkbox"/>						
2	26/07/19 14:40	<b>Rear View Right</b>		Load JPG	<input checked="" type="checkbox"/>						
3	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
4	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
5	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
6	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
7	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
8	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
9	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
10	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
11	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
12	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
13	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
14	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
15	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
16	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
17	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
18	26/07/19 14:41	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
19	26/07/19 14:41	<b>Odometer Reading</b>		Load JPG	<input checked="" type="checkbox"/>						
20	26/07/19 14:41	<b>Chassis Number</b>		Load JPG	<input checked="" type="checkbox"/>						
21	26/07/19 14:42	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>						
22	26/07/19 14:42	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>						
23	26/07/19 14:42	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>						
24	26/07/19 14:42	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>						
25	26/07/19 14:42	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>						

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
26	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	26/07/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
58	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
59	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
60	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
61	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
62	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
63	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
64	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
65	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
66	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
67	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
68	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
69	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
70	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
71	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
72	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
73	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
74	26/07/19 14:42	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
S & H Motor Pte Ltd (Sin Ming)				
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/05/18 11:46	<b>PRS</b>	Load PDF	
2	04/05/18 11:46	<b>OI GIA REPORT</b>	Load PDF	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	03/05/18 15:12	<b>Sketch Plan</b> [Linked Accident Report Documents]	Load TIF	
2	03/05/18 15:12	<b>Sketch Plan #2</b> [Linked Accident Report Documents]	Load TIF	
3	03/05/18 15:12	<b>Sketch Plan #3</b> [Linked Accident Report Documents]	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/08/19 10:20	<b>Supplementary</b>	Load PDF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
S & H Motor Pte Ltd (Sin Ming)				
1	03/05/18 15:14	<b>Accident Statement</b>	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	03/05/18 15:12	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
2	03/05/18 15:12	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
3	03/05/18 15:12	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
4	03/05/18 15:12	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
5	03/05/18 15:12	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
6	03/05/18 15:12	<b>Accident Photo</b>	Load JPG <input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	03/05/18 15:12	<b>Sketch Plan</b>	Load TIF	
2	03/05/18 15:12	<b>Sketch Plan #2</b>	Load TIF	
3	03/05/18 15:12	<b>Sketch Plan #3</b>	Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18008178/DSD3E2

Date: 22/08/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1682061701
Claimant Vehicle No :	GX2315U	Insured Vehicle No :	YN1884P
Date of Loss:	27/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D02231C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>GX2315U</b>	Engine No:	5L5411193
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	LH1621010645
Reg. Date:	10/03/2004 (Man. Year: 2004)	Odometer:	352545 km
Colour:	Green		
Engine Capacity:	2985 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	185 R14	Rear Tyre Size:	185 R14
Front Left Side:	Radial 5 mm	Rear Left Side:	Radial 5 mm
Front Right Side:	Radial 5 mm	Rear Right Side:	Radial 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	7,295.87	4,211.77	3,084.10	42.27	
Miscellaneous Items	0.00	0.00	0.00		
Labour	3,810.00	1,510.00	2,300.00	60.37	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>11,105.87</b>	<b>5,721.77</b>	<b>5,384.10</b>	<b>48.48</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>			
	(S\$)	11,105.87	4,500.00	6,605.87	59.48
	+ GST 7.00/7.00% (S\$)	777.41	315.00	462.41	59.48
	<b>Nett Amount (S\$)</b>	<b>11,883.28</b>	<b>4,815.00</b>	<b>7,068.28</b>	<b>59.48</b>

## INSPECTION

Date of Assignment:	04/05/2018	
Date Inspected:	07/05/2018 Inspected At:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934

Estimated Period of Repair: 5.0 days

---

**Adjuster:** BRYAN TANI

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b>	(Last Synchronised: 22 Aug 2019)
<b>Parts:</b>	N/A TOYOTA HIACE 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GX2315U)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	508.10 FL	*508.10 FL
2	2		*REAR BUMPER SIDE HOLDER	Not Necessary	133.90 FL	*- FL
3	1		*REAR BUMPER BEAM	Dented	429.10 FL	*429.10 FL
4	2		*TAILLAMP	Cracked	632.40 FL	*632.40 FL
5	2		*TAILLAMP SEAL	Not Necessary	40.20 FL	*- FL
6	2		*TAILLAMP PANEL	Not Necessary	563.70 FL	*- FL
7	1		*TAILGATE	Dented	1,812.32 FL	*1,812.32 FL
8	1		*TAILGATE RUBBER	Necessary	311.40 FL	*311.40 FL
9	1		*TAILGATE EMBLEM LOGO	Repeated	61.00 FL	*- FL
10	1		*TAILGATE LOCK	Damaged	413.70 FL	*413.70 FL
11	1		*TAILGATE LOCK CATCH	Not Necessary	56.00 FL	*- FL
12	2		*TAILGATE HINGE	Not Necessary	178.00 FL	*- FL
13	1		*TAILGATE RUBBER	Repeated	381.40 FL	*- FL
14	2		*TAILGATE DAMPER	Not Necessary	282.30 FL	*- FL
15	2		*TAILGATE WEDGE CATCH	Not Necessary	86.20 FL	*- FL
16	2		*TAILGATE WEDGE ADJUSTMENT	Not Necessary	115.60 FL	*- FL
17	1		*TAILGATE OUTER GARNISH	Mounting Broken	139.34 FL	*139.34 FL
18	1		*TAILGATE LOGO	Necessary	56.00 FL	*56.00 FL
19	1		*TAILGATE EMBLEM - HIACE	Necessary	68.00 FL	*68.00 FL
20	1		*REAR EXHAUST ASSY	Not Necessary	892.10 FL	*- FL
21	1		*REAR EXHAUST MOUNTING	Not Necessary	40.00 FL	*- FL
22	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
23	1		*SET REAR REVERSE SENSOR	Not fitted	400.00 FS	*- FS
24	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
25	1		*JOINT SEALANT	Necessary	150.00 FS	*40.00 FS
26	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
27	1		*70KM/H STICKER	Necessary	30.00 FS	*20.00 FS
28	1		*REAR END PANEL	Dented	689.60 FL	*689.60 FL
29	1		*SPARE TIRE BRACKET	Bent	201.30 FL	*201.30 FL
30	1		*SPARE TIRE LOCK	Bent	489.50 FL	*181.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>9,441.16</b>	<b>5,572.36</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>2,145.29</b>	<b>1,360.59</b>
<b>Total Parts (S\$)</b>	<b>7,295.87</b>	<b>4,211.77</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	New	60.00	30.00
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	New	200.00	100.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	0.00
4	REMOVE AND RENEW REAR EXHAUST ASSY	New	150.00	0.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
6	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	60.00
7	PANEL BEATING ON AFFECTED AREAS	New	1,500.00	600.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>3,810.00</b>	<b>1,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >