

A07/2002

SS REC BY:

REF: CG/CTU18008206/Sr bez | Special Instruction:

SUNVALDI

Substation

ASSIGNMENT (Office)

Regimen

From (Person): Irene Tng of CTL Date/Time: 04/05/2018 233pm

Estimated Cost: Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: Ym 9217T Insured:

at Workshop m/s: Sin Yew Hup Auto Tel: 6760 0819

of Blk D4 Woodlands Rd 393m

Policy No: DMCVSN 3087801700 Claim No: 21M13102221C01

Sum Insured: Excess: \$ 550.00

Make of Veh: D.O.A. 2704/2018

(Client's Record)

CA / ☒ REV / REP. / REV 24 HRS

10.05.2018 @ before 12pm

H.O.D. Endorsement:

Date/Time: 04/05/2018 331pm Person Contacted: Jing Yee Vehicle: IN / ☒ OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|--|
| | Ym 9217T - x |
| 11/5/18 | Revert thru regimen, seek mandate |
| 14/5/18 | Irene inform authorise repair. |
| 15/5/18 | Inform Jing Yee authorise repair thru email & phone. |
| | Confirm \$ 3950.00 @ 3 days (Red: \$ 1310, 25%). |

REF: CIL

ASSIGNMENT

From: Date: 10052018

Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: Ym 9217T

at Workshop n/s: Sin Yew Hup

of: Bk D4 Woodlands Road 393m

Insured:

Policy No:

Claims No:

Sum Insured: Excess: \$550.00

(Client's Record)

Make of Veh:

(Policy Condition) before 12pm

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$8K (Insurance)

IDAC Accident Report: Consistent? Yes or No

GIA / PR. Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REP / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: Ym 9217T Yr Regn: 4/8/2008

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

Make: Mitsubishi FEB 3BEG SRDEA CC 2777

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 247505 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FEB 3BEG 10727

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S/Rim / STD A/Rim or

Tyre Size: F: 7.00 R16 L7 Five Stone

R: " Cane Yang

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: Fear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 27/4/18 D.O.I: 10/5/18

Survey held at: Sin Yew Hup

Des. of Damages: Frt / Rear / OD / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 08 JUL 2018

Cust/Time: File Pass M/T

☐ : Prel. Report
☒ : Final Report

Cust/Time: File Return M/T

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee

Transportation

1. S + R = \$

1. Phone

1. Other

1. Total

Total

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Files (\$)☐ Weigh and (\$)

Report Format: OD

Lump Sum / LB: \$ 3950

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-----------------------------|-------------------------------------|--------------------------------|---------|---------------|------------|-------------------------------|
| Main | 03 May 2018 Sendback Est | 03 May 2018 16:17 \$55,260.00 | 04 May 2018 14:33 Assign | | | | New Assignment Cancel Case |

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

| | | | |
|-------------------|--|------------------------|--|
| Insured: | SKY BUILDER & EXHIBITION PTE LTD, Co. Reg. No.: 201304914G | | |
| Vehicle Reg. No.: | YM9217T | Date of Loss: | 27/04/2018 17:00 - :59 [116 Months and 23 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | OD / SNM18D02221C01 | Policy/Cover Note No.: | DMCVSN3087801700 (Comprehensive) |
| | | Excess: | S\$550.00 |
| Repairer: | Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate, 677981 Woodlands - Tel: 67600819 | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2018] | | |
| Driver/Custodian: | ISLAM MOHAMMAD SAIFUL (23 / Male), NRIC: G2428807U, Tel: +6583436918 | | |
| Adj Asg. Remarks: | PLEASE SURVEY AND REVERT | | |

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte.
Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 11 May 2018

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|-----------------------|
| Vehicle No | : YM9217T | Accident Date | : 27/04/2018 |
| Make | : MITSUBISHI FE83BE6SRDEA | Policy No. | : DMCVSN3087801700 |
| Assignment Date | : 04/05/2018 | Excess | : S\$550.00 |
| Date of Inspection | : 10/05/2018 | Est. Duration of Repair | : 3.00 |
| Inspection At | : SIN YEW HUP AUTO PTE LTD (HQ) BLK D4 WOODLANDS ROAD 393M, YEW TEE INDUSTRIAL ESTATE SINGAPORE 677981 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 5,260.00 |
| Revised Amount | :S\$ | 3,245.00 |
| Check Items (Estimated) | :S\$ | 1,695.00 |
| Total | :S\$ | 4,940.00 |
| Lump Sum Repair | :S\$ | 3,950.00 |

Total Loss Consideration

| | | |
|--------------------|------|----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 8,000.00 |
| COE / PARF Rebate | :S\$ | 289.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 7,711.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Print Received Message

This mail is associated with :

YM9217T (SNM18D02221C01)

OD

Apr 27 2018 5:00PM

[SKY BUILDER & EXHIBITION PTE LTD]

Sin Yew Hup Auto Pte Ltd

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 14/05/2018 14:14 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3950.00) - YM9217T - Claim Handler: Irene Tay Hui Ping

Approved:3950.00:PROCEED TO AUTHORIZE REPAIRS AT \$3,950.00 BEFORE EXCESS OF \$550.00

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Tuesday, May 15, 2018 9:54 AM
To: 'sinyewhup@gmail.com'; 'syhapl@singnet.com.sg'
Cc: SUR
Subject: YM 9217T CTI OD DOA : 27.04.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **YM 9217T (excess \$550/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|-------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 4914G |
| Vehicle Details | |
| Vehicle No.: | YM9217T |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 11 May 2018 |
| Vehicle Make: | MITSUBISHI |
| Vehicle Model: | FE83BE6SRDEA |
| Primary Colour: | White |
| Manufacturing Year: | 2008 |
| Engine No.: | 4M42A56496 |
| Chassis No.: | FE83BEA10927 |
| Maximum Power Output: | - |
| Open Market Value: | \$29,414.00 |
| Original Registration Date: | 04 Aug 2008 |
| First Registration Date: | 04 Aug 2008 |
| Transfer Count: | 3 |
| Actual ARF Paid: | \$1,471.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 03 Aug 2018 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| QP Paid: | \$12,659.00 |
| COE Rebate Amount: | \$289.00 |
| Total Rebate Amount: | \$289.00 |

The information contained herein is correct as at 11 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|----------------------|
| Date Of Report | 30/04/2018 16:20 |
| Date Of Accident | 27/04/2018 17:10 |
| Exact Location Of Accident | ALONG JOO CHIAT ROAD |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------------------|
| Vehicle Registration Number | YM9217T |
| Insured/Policyholder | |
| Name Of Registered Owner | SKY BUILDER & EXHIBITION PTE LTD |
| Co Reg No | 201304914G |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-62698960 |

Vehicle Particulars

| | |
|--------------|--------------|
| Manufacturer | MITSUBISHI |
| Model | FE83BE6SRDEA |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

| | |
|------------------|--------------------|
| Vehicle Category | COMMERCIAL VEHICLE |
|------------------|--------------------|

Insurance Company

| | |
|---------------------------|---|
| Name of Insurance Company | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | DMCVSN3087801700 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | ISLAM MOHAMMAD SAIFUL |
| NRIC No | G2428807U |
| Date Of Birth | 30/11/1994 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 06/06/2016 |
| Driving Experience | 1 YEAR AND 10 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-83436918 |
| Fax Number | |
| Contact Number | |
| Email Address | NOEMAIL |

| | |
|---|-----|
| Address | N/A |
| Postcode | |
| Was driver an employee of the Insured's Company | YES |
| If No, Relationship of the Driver with the Insured | |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|-------------------------------------|
| Type Of Accident | COLLISION - OPENING DOOR OF VEHICLE |
| Weather Conditions | RAINING |
| Road Surface | WET |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|--------------------|
| Vehicle Registration Number | YN4360P |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | COMMERCIAL VEHICLE |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



A.YM 9217T

B.YM 4360P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At the mentioned date and time, lorry A stop beside the road to top up cash card. When lorry A driver prepare to return to driver seat. Lorry B drive fast and hit the door of Lorry A. Before this, driver A told driver B to wait as the road is small. However, driver B never stop or lower the speed.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

DRIVER DETAIL Pg. 1

REPUBLIC OF SINGAPORE DRIVING LICENCE

02428807U

ISLAM MOHAMMAD SAIFUL

DOB: 30 Nov 1994

Issue Date: 06 Jun 2018

Valid Till: 05-06-2021

002574994C






WORK PERMIT
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer:
SKY BUILDER & EXHIBITION PTE. LTD.

Name:
ISLAM MOHAMMAD SAIFUL

Work Permit No.: 0 64210088 Sector: CONSTRUCTION

01113108

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2 Motor cars with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles with unladen weight \leq 2500kg

EFFECTIVE DATE: 06 Jun 2018

NP 428A

Licence No: 02428807U



VISIT PASS
Immigration Regulations

Name:
ISLAM MOHAMMAD SAIFUL

FIN:
02428807U

Date of Birth: 30-11-1994 Sex: M

Nationality:
BANGLADESH

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

Download SGWorkPass App to check status





CERTIFICATE OF INSURANCE Pg. 1



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

ME380/C
N 5N
ANG613A
COMPREHENSIVE
AUTOSAFE

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

| | | |
|--|---|--|
| CERTIFICATE No. | DNCVEN3087881700 | Engine No. : 4M42A56496 Chassis No. : FEB3BEA10927 |
| Index Mark and Registration Number of Vehicle | YM9217T | |
| Name of Policy Holder | M/S SKY BUILDER & EXHIBITION PTE. LTD. | |
| Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment | 14 NOVEMBER 2017 (14:43 HOURS) 13 NOVEMBER 2016 | EX SECT. IS\$550.00 EX ON WINDSCREENS\$100.00 |
| Date of Expiry of Insurance | | |
| Persons or Classes of Persons entitled to drive * | | |

ANY PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH THEIR PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

Limitations as to use: *

- (1) USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
- (2) USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD) IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
- (3) USE FOR SOCIAL, DOMESTIC OR PLEASURE PURPOSES.

THE POLICY DOES NOT COVER.

- (1) USE FOR HIRE OR REWARD OR RACING, PACE-MAKING, RELIABILITY TRIAL OR SPEED TESTING.
- (2) USE WHILST DRAWING A TRAILER EXCEPT THE TOWING OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.

** Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.*

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia). Please see reverse
For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.



Countersigned By:

Authorised Officer

Authorised Signatory



新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

| | | | |
|---------------------|----------------------------------|-----------------------|------------|
| Claim Type: | OD (OWN DAMAGE) | Ref. No: | |
| Policy No: | DMCVSN3087801700 | Date of Loss: | 27/04/2018 |
| Vehicle Reg. No.: | YM9217T | Driveable? | |
| Driver Age/Info: | 23 / MALE | Party At Fault: | UNKNOWN |
| TP Injury Involved? | NO | Third Party Involved? | YES |
| Insured/Claimant: | SKY BUILDER & EXHIBITION PTE LTD | | |
| Driver: | ISLAM MOHAMMAD SAIFUL | | |

| | | | |
|-----------------|------------------------------------|--------------------|--------------|
| Make/Model: | MITSUBISHI FE83BE6SRDEA, 3.0 D (A) | Vehicle Reg. Date: | 04/08/2008 |
| Vehicle Colour: | WHITE | | |
| Engine No: | 4M42A56496 | Chassis No: | FE83BEA10927 |
| Odometer: | 0 KM | | |

| | |
|-------------------------------|----|
| Paint Type: | |
| Total Loss? | NO |
| Est. Duration of Repair (day) | 7 |

| | |
|------------------------------|-------------------------------|
| Description of Accident/Loss | PLEASE REFER TO SKETCH PLAN. |
| Present Location: | SIN YEW HUP AUTO PTE LTD (HQ) |

| COST OF CLAIMS | Amount |
|------------------------------|----------|
| Parts | 3,990.00 |
| Miscellaneous Items | 0.00 |
| Labour | 1,270.00 |
| Paintwork Labour | 0.00 |
| Towing | 0.00 |
| Calculated Gross Total (S\$) | 5,260.00 |
| - Excess (S\$) | 550.00 |
| (S\$) | 4,710.00 |
| + GST 7.00% (S\$) | 329.70 |
| Nett Amount (S\$) | 5,039.70 |

This claim is handled by: LIM JING YEE

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 03 May 2018)

Parts: N/A MITSUBISHI FE83BE6SRDEA 3.0 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sin Yew Hup Auto Pte Ltd/YM9217T/03/05/2018 16:17

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|-------------------|-----|----------|--|-------|-------|-------------|
| 1 | 1 | | *Door RH ✓ OT | 0.00 | 0.00 | *1,100.00 F |
| 2 | 1 | | *Door Hinge Top ✓ BT | 0.00 | 0.00 | *110.00 F |
| 3 | 1 | | *Door Hinge Lower ✓ BT | 0.00 | 0.00 | *110.00 F |
| 4 | 1 | | *Door Checker ? / DMG | 0.00 | 0.00 | *65.00 F |
| 5 | 1 | | *Door glass ✓ CAC | 0.00 | 0.00 | *335.00 F |
| 6 | 1 | | *Door Glass rubber ✓ Defor | 0.00 | 0.00 | *230.00 F |
| 7 | 1 | | *Door outer moulding ✓ CAC | 0.00 | 0.00 | *95.00 F |
| 8 | 1 | | *Door Lower Garnish ✓ Defor | 0.00 | 0.00 | *60.00 F |
| 9 | 1 | | *Door Inner Lock ? JM | 0.00 | 0.00 | *205.00 F |
| 10 | 1 | | *Door Glass Regulator ? DMG Complete come with motor | 0.00 | 0.00 | *625.00 F |
| 11 | 1 | | *Door inner board top ? CAC with door inner moulding and inner handle outer cover | 0.00 | 0.00 | *290.00 F |
| 12 | 1 | | *Door inner board lower ? IRE | 0.00 | 0.00 | *420.00 F |
| 13 | 1 | | *Side lamp RH ? IRE | 0.00 | 0.00 | *90.00 F |
| 14 | 1 | | *Signal lamp RH ✓ CAC | 0.00 | 0.00 | *170.00 F |
| 15 | 1 | | *Door Outer Handle ✓ JM | 0.00 | 0.00 | *85.00 F |
| Total Parts (S\$) | | | | | | 3,990.00 |

F=Franchise part.

Sin Yew Hup Auto Pte Ltd/YM9217T/03/05/2018 16:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|-------------------------|---|----------|------------|
| Labour Items | | | |
| 1 | Remove and Refit Door Mechanism | New | 70.00 |
| 2 | To Putty and Spray Paint Door in and out, Front bumper, Door pillar, Corner panel | New | 500 600.00 |
| 3 | To remove and refit door RH, side lamp, signal lamp, panel beat corner panel, front bumper, door pillar | New | 400 600.00 |
| Gross Labour Cost (S\$) | | | 1,270.00 |

Sin Yew Hup Auto Pte Ltd/YM9217T/03/05/2018 16:17, Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

3 day

Sebastian.
10/5/18

- Lump Sum Repair
- Question, Made Item Photo
- Photo After Paint


21/5/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(1) The first of the two main parts of the
 present work is devoted to the study of the
 problem of the existence of solutions of the
 boundary value problem for the system of
 linear differential equations with constant
 coefficients. The second part is devoted to
 the study of the problem of the existence
 of solutions of the boundary value problem
 for the system of linear differential equations
 with variable coefficients.

Moscow, U.S.S.R.
 1964

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 03 May 2018)
 Parts: N/A MITSUBISHI FE83BE6SRDEA 3.0 D (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Sin Yew Hup Auto Pte Ltd/YM9217T/03/05/2018 16:17
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|-----|-----|----------|--|-------|-------|-------------|
| 1 | 1 | | *Door RH ✓ BT | 0.00 | 0.00 | *1,100.00 F |
| 2 | 1 | | *Door Hinge Top ✓ BT | 0.00 | 0.00 | *110.00 F |
| 3 | 1 | | *Door Hinge Lower ✓ BT | 0.00 | 0.00 | *110.00 F |
| 4 | 1 | | *Door Checker ✓ | 0.00 | 0.00 | *65.00 F |
| 5 | 1 | | *Door glass ✓ CRK | 0.00 | 0.00 | *335.00 F |
| 6 | 1 | | *Door Glass rubber ✓ Defen. | 0.00 | 0.00 | *230.00 F |
| 7 | 1 | | *Door outer moulding ✓ CRK | 0.00 | 0.00 | *95.00 F |
| 8 | 1 | | *Door Lower Garnish ✓ Defen. | 0.00 | 0.00 | *60.00 F |
| 9 | 1 | | *Door Inner Lock ✓ | 0.00 | 0.00 | *205.00 F |
| 10 | 1 | | *Door Glass Regulator ✓ Complete come with motor | 0.00 | 0.00 | *625.00 F |
| 11 | 1 | | *Door Inner board top ✓ with door inner moulding and inner handle outer cover | 0.00 | 0.00 | *290.00 F |
| 12 | 1 | | *Door inner board lower ✓ | 0.00 | 0.00 | *420.00 F |
| 13 | 1 | | *Side lamp RH ✓ | 0.00 | 0.00 | *90.00 F |
| 14 | 1 | | *Signal lamp RH ✓ CRK | 0.00 | 0.00 | *170.00 F |
| 15 | 1 | | *Door Outer Handle ✓ In. | 0.00 | 0.00 | *85.00 F |

F=Franchise part.

Total Parts (S\$) 3,990.00 ✓

Sin Yew Hup Auto Pte Ltd/YM9217T/03/05/2018 16:17. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Handwritten signature
 K. L. 22/5/16

Notes on Miscellaneous Items
no new miscellaneous items selected.

Notes on Labour

Particulars

Lab.Type

Amount

Labour Items

Remove and Refit Door Mechanism

New

To 70.00

To Putty and Spray Paint Door in and out, Front bumper, Door pillar, Corner panel

New

See 600.00

To remove and refit door RH, side lamp, signal lamp, panel beat corner panel, front bumper, door pillar

New

See 600.00

Gross Labour Cost (S\$) 0% 1,270.00

Sin Yew Hup Auto Pte Ltd/YM9217T/03/05/2018 16:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

3 day

Sebastian.
10/5/18.

- Lump Sum Repair
- Question, Made Iron Photo
- Photo After Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 3,990.00 /
Labour 950.00 /
4,940.00 /

L/S 20% 988.00
3,952.00 /

3,950.00 /

before excess & before GST

Sebastian
7/6/18

Janice Lee (LKKAuto)

From: Sin Yew Hup Auto Pte Ltd <sinyewhup@gmail.com>
Sent: Wednesday, May 30, 2018 4:52 PM
To: Sebastian Yeang (LKK Auto)
Cc: SUR
Subject: Fwd: OD: YM 9217 T CTI OD DOA : 27.04.2018
Attachments: calculation 1.jpeg; calculation 2.jpeg; DSCN6390.JPG; DSCN6391.JPG; DSCN6392.JPG; DSCN6393.JPG; DSCN6394.JPG; DSCN6395.JPG; DSCN6398.JPG

Hi

Good day

Dear Sebastian

Attached with the photo after paint and the COR for your perusal.

Thank you.

Best Regards,

Yong Jian

SIN YEW HUP AUTO PTE LTD
T : +65 67600819
F : +65 67690221

----- Forwarded message -----

From: Sin Yew Hup Auto Pte Ltd <sinyewhup@gmail.com>
Date: Thu, May 24, 2018 at 2:44 PM
Subject: OD: YM 9217 T CTI OD DOA : 27.04.2018
To: "Sebastian Yeang (LKK Auto)" <sebastianyeang@lkkauto.com>

Hi

Good day

Dear Sebastian

Please find the attached COR and photo after paint.

Thank you.

Best Regards,

Yong Jian

SIN YEW HUP AUTO PTE LTD

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 03 May 2018)
 Parts: N/A MITSUBISHI FE83BE6SRDEA 3.0 D (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Sin Yew Hup Auto Pte Ltd/YM9217T/03/05/2018 16:17
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|-----|-----|----------|--|-------|-------|-------------|
| 1 | 1 | | *Door RH ✓ DT | 0.00 | 0.00 | *1,100.00 F |
| 2 | 1 | | *Door Hinge Top ✓ DT | 0.00 | 0.00 | *110.00 F |
| 3 | 1 | | *Door Hinge Lower ✓ DT | 0.00 | 0.00 | *110.00 F |
| 4 | 1 | | *Door Checker ✓ DMG | 0.00 | 0.00 | *65.00 F |
| 5 | 1 | | *Door glass ✓ CRK | 0.00 | 0.00 | *335.00 F |
| 6 | 1 | | *Door Glass rubber ✓ Defen. | 0.00 | 0.00 | *230.00 F |
| 7 | 1 | | *Door outer moulding ✓ WEC | 0.00 | 0.00 | *95.00 F |
| 8 | 1 | | *Door Lower Garnish ✓ Defen. | 0.00 | 0.00 | *60.00 F |
| 9 | 1 | | *Door Inner Lock ✓ JM | 0.00 | 0.00 | *205.00 F |
| 10 | 1 | | *Door Glass Regulator ✓ DMG Complete come with motor | 0.00 | 0.00 | *625.00 F |
| 11 | 1 | | *Door inner board top ✓ CRK with door inner moulding and inner handle outer cover | 0.00 | 0.00 | *290.00 F |
| 12 | 1 | | *Door inner board lower ✓ CRK | 0.00 | 0.00 | *420.00 F |
| 13 | 1 | | *Side lamp RH ✓ CRK | 0.00 | 0.00 | *90.00 F |
| 14 | 1 | | *Signal lamp RH ✓ CRK | 0.00 | 0.00 | *170.00 F |
| 15 | 1 | | *Door Outer Handle ✓ JM | 0.00 | 0.00 | *85.00 F |

F=Franchise part.

Total Parts (S\$) 3,990.00 ✓

Sin Yew Hup Auto Pte Ltd/YM9217T/03/05/2018 16:17. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

request
K. L. 22/5/18

1) Parts : \$ 3591
 2) Labour : \$ 950

4541
 Lump Sum - 20%
 3632.80

L/S : \$ 3650 @ 3 days.

3990
 -10%
 1) 3591

Estimates on Miscellaneous Items
There are no new miscellaneous items selected.

Estimates on Labour

| Particulars | Lab.Type | Amount |
|---|----------|----------|
| <u>Labour Items</u> | | |
| Remove and Refit Door Mechanism | New | 70.00 |
| To Putty and Spray Paint Door in and out, Front bumper, Door pillar, Corner panel | New | 500.00 |
| To remove and refit door RH, side lamp, signal lamp, panel beat corner panel, front bumper, door pillar | New | 500.00 |
| | 2) 950 | |
| Gross Labour Cost (S\$) | | 1,270.00 |

Sin Yew Hup Auto Pte Ltd/YM9217T/03/05/2018 16:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

3 to 3

Sebastian.
10/5/18.

- Lump Sum Repair
- Question Mark Item Photo
- Photo After Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Part 3,990.00
Labour 950.00

4,940.00
L/s 20% 988.00

3,952.00

3,950.00

before excess & before GST


























...CLAIM SUBFOLDER...(Pending for Survey Report)






































| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|--|--|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 03 May 2018 Sendback Est | 03 May 2018 16:17 S\$5,260.00 | 04 May 2018 14:33 Edit Adj Rpt | S\$3,950.00 Edit Estimates | S\$3,950.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|--|-----------|--|------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS | | | | | | | | | |
| Insured: SKY BUILDER & EXHIBITION PTE LTD , Co. Reg. No.: 201304914G | | | | | | | | | |
| Vehicle Reg. No.: YM9217T | | Date of Loss: 27/04/2018 17:00 - :59 [116 Months and 23 Days From LTA Reg Date (Man Yr)] | | | | | | | |
| Claim Type: OD / SNM18D02221C01 | | Policy/Cover Note No.: DMCVSN3087801700 (Comprehensive) | | | | | | | |
| | | Excess: S\$550.00 | | | | | | | |
| Repairer: Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate, 677981 Woodlands - Tel: 67600819 | | | | | | | | | |
| Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192] | | | | | | | | | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 15/05/2018] | | | | | | | | | |
| Driver/Custodian: ISLAM MOHAMMAD SAIFUL (23 / Male), NRIC: G2428807U, Tel: +6583436918 | | | | | | | | | |
| Adj Asg. Remarks: PLEASE SURVEY AND REVERT | | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> CHINA_TAIPING (14/05/2018): Alert - Adj Mandate Approved (S\$3950.00) - YM9217T - Claim Handler: Irene Tay Hu... | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |


Claim Documents












YM9217T (SNM18D02221C01)
 OD
 Apr 27 2018 5:00PM
 [SKY BUILDER & EXHIBITION PTE LTD]
 Sin Yew Hup Auto Pte Ltd

| | | | | |
|---|-----------------|-----------------------------------|--|-------------------------------------|
| Upload Documents Upload Photos Compose New Letter | | | View View in Browser | |
| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Sin Yew Hup Auto Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 03/05/18 16:17 | Repairer Estimates |  Load HTM | |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 11/05/18 12:09 | Adjuster Immediate Advice |  Load HTM | |
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 11/05/18 12:25 | General View |  Load PDF | |
| 2 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 07/06/18 10:44 | General View |  Load JPG | |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | Sin Yew Hup Auto Pte Ltd (HQ) | Thumbnail | Print |
| | | | | <input checked="" type="checkbox"/> |
| 35 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 07/06/18 10:44 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 07/06/18 10:44 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 07/06/18 10:44 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 07/06/18 10:44 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 07/06/18 10:44 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 07/06/18 10:44 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 07/06/18 10:44 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 07/06/18 10:44 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 07/06/18 10:44 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 11/05/18 12:15 | YM 9217T ESTIMATE |  Load PDF | |

Linked Accident Report Documents

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|-------------------------------|--|-------------------------------------|
| No | Finalized On | Sin Yew Hup Auto Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 30/04/18 17:55 | Accident Statement |  Load HTM | |
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Sin Yew Hup Auto Pte Ltd (HQ) | Thumbnail | Print |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|-------------------------------|---|-------------------------------------|
| No | Finalized On | Sin Yew Hup Auto Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 30/04/18 17:21 | Accident Photo |  | <input checked="" type="checkbox"/> |
| 2 | 30/04/18 17:21 | Accident Photo |  | <input checked="" type="checkbox"/> |
| 3 | 30/04/18 17:21 | Accident Photo |  | <input checked="" type="checkbox"/> |
| 4 | 30/04/18 17:21 | Accident Photo |  | <input checked="" type="checkbox"/> |
| 5 | 30/04/18 17:21 | Accident Photo |  | <input checked="" type="checkbox"/> |
| 6 | 30/04/18 17:21 | Accident Photo |  | <input checked="" type="checkbox"/> |
| 7 | 30/04/18 17:21 | Accident Photo |  | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Sin Yew Hup Auto Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 30/04/18 17:20 | Accident Sketch Plan |  | <input type="checkbox"/> |
| 2 | 30/04/18 17:20 | Accident Sketch Plan |  | <input type="checkbox"/> |
| 3 | 30/04/18 17:20 | DRIVER DETAIL |  | <input type="checkbox"/> |
| 4 | 30/04/18 17:20 | CERTIFICATE OF INSURANCE |  | <input type="checkbox"/> |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118008206/SRBE2

Date: 12/06/2018

REFERENCE

| | | | | | |
|-------------------|----------------------------------|------------------|------------------|-----------|----------------|
| Insured/Claimant: | SKY BUILDER & EXHIBITION PTE LTD | Policy No: | DMCVSN3087801700 | Claim No: | SNM18D02221C01 |
| Date of Loss: | 27/04/2018 | Nature of Claim: | OD | | |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------------|-------------|--------------|
| Reg No: | YM9217T | Engine No: | 4M42A56496 |
| Make & Model: | MITSUBISHI FE83BE6SRDEA, 3.0 D (A) | Chassis No: | FE83BEA10927 |
| Reg. Date: | 04/08/2008 (Man. Year: 2008) | Odometer: | 247505 km |
| Colour: | White | | |
| Engine Capacity: | 2977 cc | | |
| Market Value/New Car Price: | S\$8,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size: | 7.00 R16LT | Rear Tyre Size: | 7.00 R16LT |
| Front Left Side: | Firestone 6 mm | Rear Left Side: | CHAO YANG 6 mm |
| Front Right Side: | Firestone 6 mm | Rear Right Side: | CHAO YANG 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|-----------------|--------------|
| Parts | 3,990.00 | 3,990.00 | 0.00 | 0.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,270.00 | 950.00 | 320.00 | 25.20 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,260.00 | 4,940.00 | 320.00 | 6.08 |
| Approved Total (Overridden) (S\$) | | 3,950.00 | | |
| - Excess (S\$) | 550.00 | 550.00 | 0.00 | 0.00 |
| (S\$) | 4,710.00 | 3,400.00 | 1,310.00 | 27.81 |
| + GST 7.00/7.00% (S\$) | 329.70 | 238.00 | 91.70 | 27.81 |
| Nett Amount (S\$) | 5,039.70 | 3,638.00 | 1,401.70 | 27.81 |

INSPECTION

| | | |
|-----------------------------|------------------------------|---|
| Date of Assignment: | 04/05/2018 Present Location: | Sin Yew Hup Auto Pte Ltd (HQ) |
| Date Inspected: | 10/05/2018 Inspected At: | Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate |
| | | Singapore 677981 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: Sebastian Yeang Wai Keen**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | (Last Synchronised: 12 Jun 2018) | |
| Parts: | N/A | MITSUBISHI FE83BE6SRDEA 3.0 D (A) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for YM9217T) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------------------|-----|----------|-------------------------|-----------|------------|-------------|
| 1 | 1 | | *Door RH | Dented | 1,100.00 F | *1,100.00 F |
| 2 | 1 | | *Door Hinge Top | Bent | 110.00 F | *110.00 F |
| 3 | 1 | | *Door Hinge Lower | Bent | 110.00 F | *110.00 F |
| 4 | 1 | | *Door Checker | Damaged | 65.00 F | *65.00 F |
| 5 | 1 | | *Door glass | Cracked | 335.00 F | *335.00 F |
| 6 | 1 | | *Door Glass rubber | Deformed | 230.00 F | *230.00 F |
| 7 | 1 | | *Door outer moulding | Necessary | 95.00 F | *95.00 F |
| 8 | 1 | | *Door Lower Garnish | Deformed | 60.00 F | *60.00 F |
| 9 | 1 | | *Door Inner Lock | Jammed | 205.00 F | *205.00 F |
| 10 | 1 | | *Door Glass Regulator | Damaged | 625.00 F | *625.00 F |
| 11 | 1 | | *Door inner board top | Cracked | 290.00 F | *290.00 F |
| 12 | 1 | | *Door inner board lower | Cracked | 420.00 F | *420.00 F |
| 13 | 1 | | *Side lamp RH | Cracked | 90.00 F | *90.00 F |
| 14 | 1 | | *Signal lamp RH | Cracked | 170.00 F | *170.00 F |
| 15 | 1 | | *Door Outer Handle | Jammed | 85.00 F | *85.00 F |
| Total Parts (S\$) | | | | | 3,990.00 | 3,990.00 |

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|---|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | Remove and Refit Door Mechanism | New | 70.00 | 50.00 |
| 2 | To Putty and Spray Paint Door in and out, Front bumper, Door pillar, Corner panel | New | 600.00 | 500.00 |
| 3 | To remove and refit door RH, side lamp, signal lamp, panel beat corner panel, front bumper, door pillar | New | 600.00 | 400.00 |
| Gross Labour Cost (S\$) | | | 1,270.00 | 950.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >