

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0175/18

DATE : 13-MAR-2018

AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : PANG LIM KWEE
ADDRESS : BLK 604 BEDOK RESERVOIR RD
#05-590
S(470604)
TELEPHONE NO : 93697270/90934751

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SJK1195M
MODEL CODE : BDUARCAG11EHJ-----
MODEL/YEAR : SYLPHY 1.5 4A/T SEDAN (MC)
ENGINE NO : HR15032731B
CHASSIS NO : JN1BAAG11Z0106864
MILEAGE : 135400 KM
DATE IN : 13/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH — 96450079
ACCIDENT DATE : 12/03/2018

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJK1195M

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR TRUNK FLOOR, BOTH REAR FENDER, RENEW REAR PANEL, TRUNK LID & REAR BUMPER.	1300.00	
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	1200.00	
3	ZZ/003	TRANSFER TRUNK LID MECHANISM.	80.00	
4	ZZ/004	RENEW REVERSE SENSOR.	55.00	
5	ZZ/005	APPLY SEALANT TO REAR PANEL.	100.00	
6	ZZ/006	PERFORM RUST PROOFING TO REAR PANEL.	120.00	
7	ZZ/007	SUPPLY REAR LICENCE PLATE.		
		TOTAL LABOUR CHARGES	2855.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJK1195M

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	SUNDRIES	NPN			100.00	
2	REAR LICENCE PLATE	RLP			60.00	
3	REAR PANEL	79110-EW000	438.70			
4	L/R LAMP PACKING	26558-EW00A	17.60			
5	R/R LAMP PACKING	26553-EW00A	17.60			
6	L/R TRUNK LAMP	26555-EW01A	109.90			
7	R/R TRUNK LAMP	26550-EW01A	109.90			
8	REAR COMB LAMP LH	26555-EW00A	219.80			
9	REAR COMB LAMP RH	26550-EW00A	219.80			
10	CARPET-TRUNK FLOOR	84902-EW01A	511.00			
11	TRUNK LID INNER CENTRE FINISHER	84966-EW00A	148.90			
12	TRUNK TOP PLATE MASK	84994-EW00A	4.20			
13	TRUNK TOP PLATE	84921-EW01A	192.00			
14	EMBLEM REAR SYLPHY	84895-EW000	87.00			
15	EMBLEM REAR NISSAN	84890-EW000	46.10			
16	WSTRIP-TRUNK LID	84830-EW000	106.30			
17	STRIKER-TRUNK LID	84621-ED400	63.70			
18	LOCK ASSY-TRUNK	84631-EW000	112.00			
19	TRUNK LID LOWER MLDG	84860-EW000	152.70			
20	TRUNK LID TOP MLDG	84810-EW005	270.60			
21	LID TRUNK	H430M-EX1MA	796.70			
22	SENSOR-REVERSE	SENSOR			200.00	
23	REAR BUMPER REFLECTOR LH	26565-EW00A	55.00			
24	REAR BUMPER REFLECTOR RH	26560-EW00A	55.00			
25	REAR BUMPER MLDG	85072-EW000	162.80			

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJK1195M

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST
26	ENERGY ABSORBER REAR BUMPER	85090-EW000	37.00	
27	REAR BUMPER SIDE BRKT LH	85227-EW000	36.60	
28	REAR BUMPER SIDE BRKT RH	85226-EW000	36.60	
29	CLIP REAR BUMPER @ \$11.20 EACH	01553-10501	7.20	
30	REAR BUMPER FASCIA	85022-EW025	660.60	
SUB TOTAL			4675.30	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			935.06	0.00
GRAND TOTAL			3740.24	0.00
OVERALL TOTAL			4100.24	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJK1195M

TOTAL LABOUR CHARGES	2855.00
TOTAL SPARE PARTS CHARGES	4100.24

GRAND TOTAL	6955.24 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.