

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INS	PECTI	ON REPORT		
SOM	OMPO INSURANCE SINGAPORE PL			CS3/SMO18008275	5/T1z4be2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SINGAPORE 048623				17-05-2018		
			Code:	SMO		
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	FX 8840S	Veh. Ir	nspected	SKL 4401G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD1801895/THE	Exces	s (\$)	0.00	
	Assign From	GRACE TEO	Assig	n Date	04/05/2018	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI ELANTRA	c.c		1591	
	Engine No. HIDDEN Year of		of Reg.	2013		
	Chassis No.	Chassis No. KMHDH41CMDU910960 Colour		r	WHITE	
	Odometer 121997 KM		Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3.		Condit	ions of	Tyres		
		Size	Make		Balance	
	R/H Front Tyre	225/40 R18	TOYO		6 mm	
	L/H Front Tyre	225/40 R18	TOYO		6 mm	
	R/H Rear Tyre	225/40 R18	TOYO		6 mm	
	L/H Rear Tyre	225/40 R18	TOYO		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA	AR N/S F	PORTION.		
5.	General Information					
	Accident Date	04/05/2018	Inspec	ct Date / Time	08/05/2018 ( 04:30 PM )	
	Survey held at	13 KAKI BUKIT RD 4 #03-29				
	Repairer ACE AUTOLUTION PTE LTD					
5a.		Remarks				
		A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000-\$11,000				
2-11	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PL	STIMATE WAS NOT PRESENTEI 'AS TOLD TO PREPARE THE ES EASE FIND DAMAGED VEHICLE	AT THE TIMATE PHOTO	E TIME OF INSPECT IGRAPHS.		
5b.	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PL	STIMATE WAS NOT PRESENTEI 'AS TOLD TO PREPARE THE ES EASE FIND DAMAGED VEHICLE	O AT THE TIMATE PHOTO GED VE	E TIME OF INSPECT IGRAPHS. HICLE IS IN THE RE		

Report Ref No. CS3/SMO18008275/T1z4be2

Inspected By

prefin

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.