



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

GBE5579P

<b>Parts</b>	(a) Cost / List Price Items	\$	<u>3,370.15</u>
	Plus/Less 25%	\$	<u>842.54</u>
	<b>Total of Cost / List</b>	\$	<u><u>2,527.61</u></u>
	(b) Nett Price Items		_____
	Less		_____
	<b>Total of Nett Item</b>		_____
	(c) Special Nett Items		_____
<b>Total Parts Cost</b>		\$	<u><u>2,527.61</u></u>
<b>Labour</b>		\$	<u><u>1,200.00</u></u>
<b>Total</b>		\$	<u><u>3,727.61</u></u>

*Not Authorized  
Penny After Paint*

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	<u>Kenneth</u>
Company	:	<u>CLC</u>
Survey conducted on	:	<u>4/15/18</u> at _____
<b>Remarks By Surveyor</b>		
(a)	The repair of this vehicle is <u>authorized</u> / is not authorized until further notice.	
(b)	Recommended Days of Repair	: <u>03</u> day(s)
(c)	Resurvey	: Required / <u>Not Required</u>
(d)	Excess	:\$ _____
(e)	Signature of surveyor	: <u>Ke</u> Date: <u>4/15/18</u>



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Spare Parts

Vehicle No. : GBE5579P  
 Make & Model : TOYOTA HIACE 3.0 DX DIESEL TURBO  
 Chassis No : KDH2015019767

Submit By : Carmen Lim  
 Year Manufacture : 2015  
 Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Tail lamp RH <i>Sm</i>	1	\$265.20		X
2	Tail lamp lower panel RH <i>Sm</i>	1	\$122.50		X
3	Rear bumper <i>Rd/Wt</i>	1	\$376.30		✓
4	Rear bumper clip <i>Sm</i>	10	\$27.90		✓
5	Rear bumper side retainer LH <i>Sm</i>	1	\$60.33		X
6	Rear bumper side retainer RH <i>Sm</i>	1	\$60.33		^
7	RH rear panel <i>R</i>	1	\$1,563.70		X
8	RH rear lower panel <i>R</i>	1	\$776.40		X
9	RH rear panel undershield <i>Sm</i>	1	\$91.81		X
10	RH rear panel undershield clip <i>Sm</i>	8	\$25.68		X
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
20					
21					
22					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

