

SMRT Accident Vehicle Repair Estimates

TH

G117

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1019K
 Ref. No : TAX/05/18/2016
 Reg. Date : 01/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : GOH HIAP HOCK
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 03/05/2018 05:31:00 PM
 Accident Reported Date / Time : 04/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095887
 Special Instruction to ARC, if any :
 SHC8362S (COMFORT) - III
 Prepared Date : 04/05/2018 09:17:30 AM



Sebastian
 7/5/18

- Part by part repair.
- Question Mark Item
- Photo
- Photo Before Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU303573178

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 0.00	0.00
Total Spray Painting Charges	: 180.00	0.00
Total Material Charges	: 1,303.27	1,303.27
Other Charges	: 200.00	0.00
TOTAL	: 1,683.27	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 2.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 04/05/2018 10:54:54 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/05/2018 10:54:46 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour		

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY VIEW MIRROR	180.00	0.00 50
Total Spray Painting & Panel Beating	180.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	120.00	0.00 30
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
Total Other Costs	200.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
87910474 50			MIRROR ASSY, OUTER REAR VIEW , RH	1	1,373.50	10.00	1,236.15	Replace	Replace	No R
87915470 70A1			COVER, OUTER MIRROR, RH	1	89.50	25.00	67.12	Replace	Replace	No ✓ R
TOTAL MATERIALS								1,303.28	1,303.27	
TOTAL MATERIALS(Discounted)							1,303.27	1,303.27		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									