

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3821R
Vehicle Details	
Vehicle No.:	SH6418Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	16 May 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	D4DFU561965
Chassis No.:	KMHLB41UMGU080435
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$20,603.00
Original Registration Date:	12 Nov 2015
First Registration Date:	12 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$20,845.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Nov 2023
PARF Rebate Amount:	\$15,633.00
Intended COE Rebate Details	
COE Expiry Date:	11 Nov 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,267.00
COE Rebate Amount:	\$31,050.00
Total Rebate Amount:	\$46,683.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	
The information contained herein is correct as at 16 May 2018	

OK

TP Veh I 40	SH 6418Y
Date of Reg	1/11/2015
DOA	4/5/2018

\$

(I) Estimated Book Value

Unit Cost	25,000.00
Import Duty	4,120.60
Registration Fee	140.00
PQP Paid	45,267.00
ARF Paid	20,845.00
Estimated Per Taxi Purchase Price	<u>95,372.60</u>
Estimated Per Taxi Purchase Price	95,372.60
Less 60% of ARF Paid	<u>12,507.00</u>
Estimated Full Lifespan Depreciation	<u>82,865.60</u>
Estimated Full Lifespan Depreciation	82,865.60
Times Balance Life (66/96 months)	<u>56,970.10</u>
Add 60% of ARF Paid	<u>12,507.00</u>
Estimated Book Value	<u><u>69,477.10</u></u>

(II) Adjusted LTA Rebate

PARF Rebate	
PQP Paid	
Times Balance Life (66/96 months)	
Adjusted COE Rebate	<u>0.00</u>
PARF Rebate	
Add Adjusted COE Rebate	<u>0.00</u>
Adjusted LTA Rebate	<u><u>0.00</u></u>

(Summary) Estimated Nett Value

Estimated Book Value	69,477.10
Less Adjusted LTA Rebate	<u>46,683.00</u>
Estimated Net Value	<u><u>22,794.10</u></u>



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 12/9/2019

Survey Details:

Date of loss	1-May-18
Date of appointment	23-May-18
Date of survey	4-May-18
Location of survey	CHUNNI MOTOR WORK PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SH 6418Y
Make and Model	HYUNDAI I40
Date of registration	12/11/2015
Excess	
Market Value	\$ 69,477.10
Part Rebate	\$ 46,683.00
Nett Loss	\$ 22,794.10

Repair details:

Initial Estimate	38,874.04
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 23,486.92
Check items (estimate)	
Labour	\$ 3,150.00
Total	\$ 26,636.92
Lump Sum(if applicable)	\$ 21,000.00

Number of days for repair	16 days
---------------------------	---------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

OID make a right turn collided with TP

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	22,470.00
Loss of use		no. of days
Loss of rental	\$	2,624.16 no. of days 22daysx \$ 119.28
Loss of income	\$	1,100.00 no. of days 22days x \$ 50.00
LTA search fees	\$	2.00
Others		
Proposed Total	\$	26,196.16



Re:TP MANDATE IA-S8M00FWD

Type

🔔 Question

Message

Please provide the book value/economical repair value before we can approve the mandate

Reply



RE: Re:TP MANDATE IA-S8M00FWD

Type

🔗 Question

Message

Hi, the estimated book value of third party taxi is \$69,477.10 less LTA Rebate: \$46,683.00 = Estimated NBV is \$22,794.10. Kindly let us have your mandate/ instruction. Thank you. Hsiao Tong - 21 Sept 2019

Reply



Re:RE: Re:TP MANDATE IA-S8M00FWD

Type

🔔 Question

Message

Please proceed based on propose mandate

Reply

Hsiao Tong (LKKAuto)

From: Chunni motor Work <chunnimw@yahoo.com.sg>
Sent: Monday, 7 October 2019 9:32 AM
To: Hsiao Tong (LKKAuto)
Cc: Admin A
Subject: Re: Your Ref: SH 6418Y *Our Ref: CC4/ASM18008319/Dpb3 [ACCIDENT INVOLVING WC 9125B(AXA) AND SH 6418Y ON 01/05/2018]

Your Ref : CC4/ASM18008319/Dpb3
Our Ref : SH 6418 Y (010518)

WITHOUT PREJUDICE

Dear Hsiao Tong,

Your email of 05-10-2019 refers.

Strictly on a without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair, GIA search fee and the Loss of rental & income during the period of repair) at a global sum of \$25,800.00.

Please note that the settlement reached is strictly for the aforesaid property damage claim only and is without prejudice to the hirer of SH 6418 Y, Ong Wee Koon's injury claim and other losses against your principals, M/s AXA Insurance Pte Ltd and /or their insured through his own solicitor.

Kindly forward us your Discharge Voucher for our client's execution as soon as possible.

Thank you and have a nice day head !

Best Regards
William
Claims Department

Chunni Motor Work Pte Ltd
10 Ang Mo Kio Industrial Park 2A
#03-19 AMK AutoPoint
Singapore 568047

Tel : 6483-6016 (Claims)

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.
It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.



Save the trees - Do you really need to print this e-mail?

On Saturday, 5 October 2019, 3:31:00 pm SGT, Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Your Ref: **SH 6418Y**

Without Prejudice

Our Ref: CC4/ASM18008319/Dpb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING WC 9125B(AXA) AND SH 6418Y ON 01/05/2018

We refer to the above matter.

We propose settlement at a global sum of **\$25,800.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Your Ref : WC 9125B

Our Ref : SH 6418Y

Ong Wee Koon c/o

CHUNNI MOTOR WORK PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A

#03-19 AMK AutoPoint

Singapore 568047

Date : 26/10/18

3019539144 - - -

The Motor Claims Department

AXA Insurance Pte Ltd

8 Shenton Way

#24-01 AXA Tower

Singapore 068811

WITHOUT PREJUDICE

60117028

Dear Sir / Madam,

RE: ACCIDENT INVOLVING SH 6418Y/WC 9125B On 01/05/2018

ALONG Science Park Drive

I am the owner/hirer of motor vehicle/taxi, SH 6418Y, which was involved in the above-mentioned accident.

The motor vehicle/taxi was surveyed by your appointed appraiser at the premises of M/S CHUNNI MOTOR WORK PTE LTD. The accident was caused by your insured's negligent driving and or management of his vehicle. Therefore, I am claiming damages and losses sustained by me against you in connection with the accident based on the appraiser's recommendation.

Our claim is as follows:

- 1) Cost of Repair
- 2) Loss of Rental
- 3) Loss of Income
- 4) GIA Report Fee
- 5) LTA Search Fee
- 6) Survey Report Fee



S\$	22,470.00
S\$	2,624.16 (\$119.28 x 22 DAYS)
S\$	1,100.00 (\$50 x 22 DAYS)
S\$	
S\$	2.00
S\$	
S\$	26,196.16

We enclose herewith the following relevant supporting documents :

- a) Authorisation Letter
- b) Final repair bill(s)
- c) LTA Search
- d) GIA report(s)
- e) Insurance Certificate

Kindly look into the matter and revert as soon as possible. Thank you.

Yours faithfully

hily



CHUNNI MOTOR WORK
PTE LTD

ONG WEE KOON APT BLK 520 WEST COAST ROAD #08-651 SINGAPORE 120520	VEHICLE NO SH 6418 Y	DATE 23.10.2018
	MAKE HYUNDAI	INVOICE NO 8659
	MODEL I40	ACC DATE/TIME 01.05.2018 @ 03:15 HRS

Cost of Repair

\$ 21,000.00

Sub-total

\$ 21,000.00

Add : 7 % - GST

\$ 1,470.00

Total

\$ 22,470.00

(SINGAPORE DOLLARS: TWENTY TWO THOUSAND FOUR HUNDRED AND
SEVENTY ONLY)





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18008319/Dpb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 29-10-2019



ATTN: YVONNE ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	WC 9125E	Veh. Inspected	SH 6418Y
Policy No.	P1647148	Coverage (\$)	0.00
Claim No.	S8M00FUP	Excess (\$)	0.00
Assign From	YVONNE ANG	Assign Date	23/05/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMGU080435	Colour	BLUE
Odometer	360921	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	CAMPEON	5 mm
L/H Front Tyre	205/60 R16	CAMPEON	5 mm
R/H Rear Tyre	205/60 R16	CAMPEON	5 mm
L/H Rear Tyre	205/60 R16	CAMPEON	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT AND REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/05/2018	Inspection Date	04/05/2018
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	16 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6418Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET (CONSISTENT)	BUCKLED	1,526.00	1,526.00
1	FRONT BUMPER COVER (CONSISTENT)	CUT	1,052.20	1,052.20
1	HEADLAMP SUPPORT PANEL ASSY (CONSISTENT)	BROKEN	1,067.50	1,067.50
1	HEADLAMP (LH) (CONSISTENT)	CUT	1,388.00	1,388.00
1	FRONT FENDER (LH) (CONSISTENT)	BUCKLED	619.00	619.00
1	FRONT FENDER APRON PANEL (LH) (CONSISTENT)	DENTED	1,575.50	1,575.50
1	FRONT FENDER SHIELD (LH) (CONSISTENT)	DEFORMED	169.80	169.80
1	FRONT DOOR (LH) (CONSISTENT)	BUCKLED	1,403.00	1,403.00
1	FRONT DOOR RUBBER (CONSISTENT)	DEFORMED	290.50	290.50
1	FRONT DOOR GLASS (LH) (CONSISTENT)	SMASHED	379.55	379.55
1	FRONT DOOR GEAR / REGULATOR (LH) (CONSISTENT)	BROKEN	785.50	785.50
1	FRONT DOOR HINGE UPPER (LH) (CONSISTENT)	BENT	53.40	53.40
1	FRONT DOOR HINGE LOWER (LH) (CONSISTENT)	BENT	53.40	53.40
1	FRONT DOOR CHECK (LH) (CONSISTENT)	BENT	110.15	110.15
1	FRONT DOOR INNER LOCK (LH) (CONSISTENT)	DAMAGED	348.95	348.95
1	SET FRONT DOOR KEY LOCK (LH) (CONSISTENT)	DAMAGED	186.50	186.50
1	FRONT DOOR OUTER HANDLE (LH) (CONSISTENT)	BROKEN	38.75	38.75
1	FRONT DOOR OUTER MOULDING (LH) (CONSISTENT)	BUCKLED	63.70	63.70
1	FRONT DOOR MIRROR (LH) (CONSISTENT)	BROKEN	980.50	980.50
1	FRONT DOOR POWER MOTOR (CONSISTENT)	DAMAGED	950.90	950.90
1	DOOR CENTRE PILLAR OUTER (LH) (CONSISTENT)	BUCKLED	1,786.20	1,786.20
1	FRT SAFETY BELT (ASSY) (LH) (CONSISTENT)	NOT NECESSARY	572.65	-
1	FRT SAFETY BELT DUCKLE (CONSISTENT)	NOT NECESSARY	86.05	-
1	FRONT WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	60.00	60.00
1	FRONT WINDSCREEN PILLAR OUTER (LH) (CONSISTENT)	BUCKLED	1,843.10	1,843.10
2	FRONT WHEEL RIM (LH/RH) @ \$351.90 (CONSISTENT)	NOT NECESSARY	703.80	-
2	FRONT WHEEL HUB CAP (LH/RH) @ \$150.70 (CONSISTENT)	CUT	301.40	301.40
2	FRONT WHEEL BEARING @ \$258.50 (CONSISTENT)	N/S DAMAGED / O/S NOT NECESSARY	517.00	258.50

Report Ref No. CC4/ASM18008319/Dpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT SHOCK ABSROBER (ASSY) (LH/RH) @ \$342.20 (CONSISTENT)	DISTORTED	684.40	684.40
2	FRONT SHOCK ABSROBER MOUNTING (LH/RH) @ \$75.10 (CONSISTENT)	NOT NECESSARY	150.20	-
1	KNUCKLE ARM (LH) (CONSISTENT)	DISTORTED	582.95	582.95
1	DASHBOARD COMPLETE (CONSISTENT)	CRACKED	2,688.00	2,688.00
2	ABS SENSOR @ \$261.50 (CONSISTENT)	NOT NECESSARY	523.00	-
1	WIRING - ENGINE (CONSISTENT)	NOT NECESSARY	3,326.00	-
1	REAR FENDER WITH HOUSING (LH) (CONSISTENT)	TO REPAIR SEE LABOUR	4,736.80	-
1	REAR FENDER INNER LINING (LH) (CONSISTENT)	NOT NECESSARY	164.40	-
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NOT NECESSARY	60.00	-
1	REAR DOOR BLACK PLASTIC COVER (CONSISTENT)	NOT NECESSARY	225.00	-
1	REAR DOOR (LH) (CONSISTENT)	BUCKLED	1,351.10	1,351.10
1	REAR DOOR RUBBER (LH) (CONSISTENT)	DEFORMED	280.50	280.50
1	REAR DOOR GLASS (LH) (CONSISTENT)	SERVICEABLE	252.10	-
1	REAR DOOR OUTER MOULDING (LH) (CONSISTENT)	BENT	212.15	212.15
1	REAR DOOR OUTER HANDLE (LH) (CONSISTENT)	BROKEN	41.40	41.40
1	REAR DOOR GEAR / REGULATOR (LH) (CONSISTENT)	BROKEN	785.50	785.50
1	REAR DOOR POWER MOTOR (LH) (CONSISTENT)	DAMAGED	950.90	950.90
1	REAR DOOR HINGE UPPER (LH) (CONSISTENT)	BENT	53.40	53.40
1	REAR DOOR HINGE LOWER (LH) (CONSISTENT)	BENT	53.40	53.40
1	REAR DOOR CHECK (LH) (CONSISTENT)	BENT	66.50	66.50
1	REAR DOOR TRIM BOARD (LH) (CONSISTENT)	MTG CRACKED	892.55	892.55
2	REAR TYRE RIM (LH/RH) @ \$351.90 (CONSISTENT)	NOT NECESSARY	703.80	-
2	REAR WHEEL HUP-CAP (LH/RH) @ \$150.70 (CONSISTENT)	CUT / DISLODGE	301.40	301.40
2	REAR WHEEL BEARING ING & HUB @ \$401.40 (CONSISTENT)	O/S DAMAGED	802.80	401.40
1	REAR TRAILING ARM (RH) (CONSISTENT)	DISTORTED	120.00	120.00
1	REAR ASSIST (RH) (CONSISTENT)	DISTORTED	120.00	120.00
1	REAR SHOCK ABSORBER (RH) (CONSISTENT)	DISTORTED	342.20	342.20
1	REAR SHOCK ABSORBER MOUNTING (RH) (CONSISTENT)	NOT NECESSARY	57.70	-
1	REAR CROSSMEMBER (CONSISTENT)	NOT NECESSARY	1,190.00	-

Report Ref No. CC4/ASM18008319/Dpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STABILIZER BAR (CONSISTENT)	DISTORTED	204.60	204.60
1	STABILIZER LINK (CONSISTENT)	DISTORTED	68.15	68.15
1	REAR UPPER ARM (RH) (CONSISTENT)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (RH) (CONSISTENT)	DISTORTED	204.35	204.35
1	REAR KNUCKLE ARM (RH) (CONSISTENT)	DISTORTED	574.80	574.80
	LESS 20% DISCOUNT		-8,403.76	-5,721.48
			33,615.04	22,885.92
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT FENDER ADVERTISEMENT LOGO (LH) (SN) (CONSISTENT)	CUT	100.00	100.00
1	FRONT DOOR COMFORT LOGO (LH) (SN) (CONSISTENT)	CUT	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (LH) (SN) (CONSISTENT)	CUT	100.00	100.00
1	FRONT WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	46.00	46.00
1	REAR BUMPER ADVERTISEMENT LOGO (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @ \$100.00 (SN) (CONSISTENT)	N/S NECESSARY / O/S NOT NECESSARY	200.00	100.00
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	46.00	-
1	REAR DOOR ADVERTISEMENT LOGO (LH) (SN) (CONSISTENT)	CUT	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN) (CONSISTENT)	CUT	80.00	80.00
2	REAR TYRE (LH/RH) @ \$216.00 (SN) (CONSISTENT)	SERVICEABLE	432.00	-
			1,229.00	601.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER WITH HOUSING (LH).		1,600.00	1,400.00
	SPRAY PAINTING CHARGE.		1,200.00	1,000.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		100.00	60.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		80.00	60.00
	REMOVE / REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	100.00	-

Report Ref No. CC4/ASM18008319/Dpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIX UNDERCARRIAGE (FRT).		200.00	80.00
	REMOVE / REFIX UNDERCARRIAGE (RR).		180.00	150.00
	FOUR WHEEL ALIGNMENT.		100.00	60.00
	REMOVE / REFIX DASHBOARD.		180.00	150.00
	REMOVE / REFIX FRONT WINDSCREEN GLASS.		100.00	80.00
	REMOVE / REFIX CUSHION & UPHOLSTERY FRONT.		90.00	80.00
			4,030.00	3,150.00
GRAND TOTAL			38,874.04	26,636.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				21,000.00

Report Ref No. CC4/ASM18008319/Dpb3s2

ANG BRYAN TANI

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.